



Notes :


This drawing has been prepared in accordance with BS 5837:2012.

This drawing is intended to be printed and used in colour only, and for no purpose other than the consideration of trees in accordance with BS 5837.

BS5837:2012 Cascade chart for tree quality assessment		
Category & Definition	Criteria (including subcategories where appropriate)	Identification on plan
<b>Trees unsuitable for retention</b>		
Category U	<p>Tree is with a condition that may result in its removal in the next 5 years or its removal in the next 10 years or its removal in the next 20 years or its removal in the next 30 years or its removal in the next 40 years or its removal in the next 50 years or its removal in the next 60 years or its removal in the next 70 years or its removal in the next 80 years or its removal in the next 90 years or its removal in the next 100 years.</p>	Red on plan RB3 RB7,8,9
<b>Trees to be considered for retention</b>		
Category A	<p>Tree of high quality with a high probability of remaining for at least 20 years.</p>	Light Green RB3 RB5,6,7,8,9
Category B	<p>Tree of moderate quality with a probability of remaining for at least 20 years.</p>	Red on plan RB3 RB5,6,7,8,9
Category C	<p>Tree of low quality with a probability of remaining for at least 10 years, or young trees with a diameter below 100mm.</p>	Grey RB3 RB5,6,7,8,9

KEY

-  Root Protection Area (RPA)
-  Tree Stem
- T1 Tree No.



Rev	Details	Date	Checked By

Drawing Number AEL-18509-TCNLP



Apex Environmental Ltd  
3 Lawrence Way, Lichfield, WS13 6RD  
TEL: 0121 249 1235 e-mail: info@ac-treecoconsultants.co.uk web: www.ac-treecoconsultants.co.uk

Client Mr A Aujla

Project 26 Wellesbourne Road, Barford

Title New Layout Plan

Scale	Date	Drawn By	Checked By	Drawing Number	Revision
1:200	04/03/2022	RJH			A

THIS DRAWING IS CONFIDENTIAL AND MUST NOT BE REPRODUCED WITHOUT THE CONSENT OF APEX ENVIRONMENTAL LTD

