



Photograph 9

**Location** - Ground floor kitchen intersection of north and east external walls.

**Detail** - Existing cupboard fittings, plastered wall, window as previously detailed with plastered ceiling.



Photograph 10

**Location** - Existing kitchen.

**Detail** - Plastered ceiling with recessed low energy downlighting.

**Proposal** - Whilst forming the small extension to the kitchen and forming a roof lantern in the position shown and described we will take the opportunity to slightly raise the ceiling which will be finished with plaster to plaster lath to match the existing with similar downlighting and the inclusion of a low profile roof lantern.



Photograph 11

**Location** - Existing flat roof with low parapet wall to rear existing kitchen facing north east

**Detail** - Flat roof with plastic resin waterproofing finish with lead flashings under stone copings and limestone spar chippings cover for solar protection.

**Proposal** - We will extend the roof in like fashion maintaining the profile of the coping stones introducing a low profile roof lantern and raising the roof height 150mm.



Photograph 12

**Location** - View from bedroom 2 northward over flat roof to kitchen