



Photograph 1

Location - North external wall to ground floor kitchen.

Detail - Divided metal frame windows set to natural stone mullions and surround sets with projecting label mould cornice over set in natural limestone random rubble wall with sawn stone quoins to opening surrounds and at corner reveals with sawn stone copings at parapet level with a flat roof to the single storey finished in spar chippings.



Photograph 2

As above.



Photograph 3

Location - External west wall to the kitchen

Detail - Showing the natural limestone wall random rubble brought to course with sawn stone window heads and quoins reveals and demonstrating the flat roof to the single storey structure with natural stone projecting copings.



Photograph 4

Location - Ground floor to kitchen showing north external wall

Detail - as described above with plastered internal walls, flagstone floor and plastered ceilings.