

One missing stone noted 5b



All Sectors: Investigate for loose sections of face-work

Cavities high-lighted. Note that surrounding stones are likely to be loosened and that gaps opening up behind stones will need filling

worn surface to stone vent

worn surface to stone vent

Sector e3 new bath-stone indent to quoin block full height of block on side face proposed with new section of stringcourse above

Purpose of issue	
Project : Church House, Wood Street ENS	
Drawing Title: Photographic Survey	
Drawing No: 2964/ H /P2	
Revision:	
Scale:	Date: June 2021
UPCHURCH ASSOCIATES	C/O 58 The Drive, High Barnet, Herts EN5 4JQ
www.upchurch-architects.com	