



worn surface to stone vent

damaged face to buttress quoin
(poorly bedded bath stone)

Two missing stones
noted 1g

worn surface to stone vent

Purpose of issue	
Project : Church House, Wood Street ENS	
Drawing Title: Photographic Survey	
Drawing No: 2964/ ff /P3	
Revision:	
Scale:	Date: June 2021
UPCHURCH ASSOCIATES	C/O 58 The Drive, High Barnet, Herts EN5 4JQ
www.upchurch-architects.com	