

The Old Post Office, 205 The Street, Thornham Magna, Eye, IP23 8HB- Dormer Window Application



Front view of house with dormer windows at the top of the house which need replacing.



Left dormer window.

The Old Post Office, 205 The Street, Thornham Magna, Eye, IP23 8HB- Dormer Window Application



Right dormer window. The sill has already rotted and fallen off.



The Old Post Office, 205 The Street, Thornham Magna, Eye, IP23 8HB- Dormer Window Application



Attic bedroom which takes up the whole of the roof space where the dormer windows are located.

The Old Post Office, 205 The Street, Thornham Magna, Eye, IP23 8HB- Dormer Window Application



Beam in attic bedroom which shows damp marks where water has come through due to missing or broken roof tiles.