


## FRONT OF HOUSE – Cliffe Farm – Windows, lintels & woodwork in current state



The front of the house – all window lintels and woodwork to be painted



The front door - all woodwork to be painted



The main gates – all woodwork to be painted



The front left top & bottom windows



The front top middle and top right windows



The front bottom right window



The bottom windows all have loose & putty missing. Paintwork on all windows in a bad state

# FRONT OF HOUSE – Windows, lintels & woodwork proposed work




Top & bottom lintels to be painted  
*'Wonderful White' W39A*

Top & bottom window woodwork  
to be painted *'Prairie Sage' R263C*



## FRONT OF HOUSE – Door woodwork proposed work



Gabled porch woodwork to be painted '*Prairie Sage*' R263C

Door woodwork to be painted '*Prairie Sage*' R263C

