

BACK OF HOUSE – Cliffe Farm – Current state



The ANNEX – all woodwork to be painted (currently does not match main house)

The back entrance to the house – all woodwork to be repaired, painted & glass panes replaced





The back patio doors



The back lounge window



The back lounge window damage to putty and wood



The back top middle window



The back top right bedroom and bathroom windows



Paintwork on all windows in a bad state



This picture shows the general state of the windows around the back of the property – badly weathered & damaged woodwork and putty loose and missing

BACK OF HOUSE – House windows & doors proposed work



Top lintels to be painted 'Wonderful White' W39A



New door (below pic) will replace this door, it will be like for like & painted Prairie Sage



Top & bottom window woodwork to be painted 'Prairie Sage' R263C



BACK OF HOUSE – House windows & doors proposed work




This is the 2nd kitchen door (that we do not use) and we propose replacing it with the new door to the right, and we will paint it '*Prairie Sage*' R263C



Picture showing both back kitchen doors



BACK OF HOUSE – Annex windows & door proposed work



All annex woodwork to be maintained and then painted '*Prairie Sage*' R263C

BACK OF HOUSE – Outbuilding doors & woodwork, proposed work



All courtyard woodwork to be maintained and then painted '*Prairie Sage*' R263C. The iron brackets & door openings will all be kept original colour and material. The courtyard outbuildings are all at the back of the property and not seen from the road.

