

16.418 Cob Wall
Collapsed Building Cob Wall Natural Stonework Lathe/Plaster studwork Brickwork Concrete Block
RIMAYLOR FARM HOUSE W WATSON sting Ground Floor Status survey O ARCHITECTURE ARCHITECTS & INTERIOR DESIGNERS TREET BRECON LD3 7DG UNITED KINGDOM.
DOARCHITECTURE.COM E MAIL : MAIL@MUNDOARCHITECTURE.COM