

Woodstock House

Mill Lane, Haltwhistle



Boundary wall from Mill Lane, pillars and railings commenced March 2021
completed May 2021



Boundary wall from house side from base of drive



Shows level of ground behind boundary wall outside house and the newly constructed piers and fence to protect against fall



Street view of wall to rear yard/steps after facing in stone, facing commenced Sept 2021 and completed Oct 2021



Picture showing existing rendered wall being faced.



Photograph of rear of wall showing existing rendered wall acts as a retaining wall and protection to fall from steps rising up.



Picture from decking looking north west.



Picture from decking looking south east commenced June 2021 completed Aug 2021



Drone image showing trees in the adjacent garden to the southern boundary which screened the property from the location of the decking prior to them being removed by the neighbour. Trees removed June 2021.