

CORRUGATED  
ASBESTOS-TYPE  
SHEET ROOFING

ROOF SAG -  
TRUSS SPREADING

VERY POOR & BULGING  
STONEMWORK

ADDED IRON  
GIRDER LINTEL

DIAGONAL  
CRACK FROM  
LINTEL-INSIDE

PARTLY BLOCKED UP  
WINDOW OPENING

MOUND OF SOIL  
& DEBRIS

FACE BLOWN OFF  
DRESSED STONE QUOIN  
AND REVEAL BLOCKS  
AND BROKEN ARISSES

SCALE 1:50

WEST ELEVATION

