

CORRUGATED
ASBESTOS-TYPE
SHEET ROOFING

ROOF SAG -
TRUSS SPREADING

VERY POOR & BULGING
STONEMWORK

ADDED IRON
GIRDER LINTEL

DIAGONAL
CRACK FROM
LINTEL-INSIDE

PARTLY BLOCKED UP
WINDOW OPENING

MOUND OF SOIL
& DEBRIS

FACE BLOWN OFF
DRESSED STONE QUOIN
AND REVEAL BLOCKS
AND BROKEN ARISSES

SCALE 1:50

WEST ELEVATION

