

	<i>Estimated % total materials</i>	Re-use in building	Re-use in garden	Total re-used	<i>% total materials reused</i>	Re-claimed materials	Total historic materials	<i>Total including re- claimed</i>
<i>Exterior cladding of old barn</i>								
Historic roof tiles	10%	50%		50%	5%	50%	100%	10.0%
Historic bricks	5%	40%	60%	100%	5%	60%	160%	8.0%
Historic rag stone	40%	50%	50%	100%	40%		100%	40.0%
non-historic broken windows	4%	0%		0%	0%		0%	0.0%
historic rotten doors	5%	0%		0%	0%		0%	0.0%
historic rotten wooden lintels & beams	5%	0%		0%	0%		0%	0.0%
historic hinges & fixings	1%	100%		100%	1%		100%	1.0%
<i>Incorporated into interior walls (non-structural)</i>								
non-historic and/or rotten internal wood	10%	0%		0%	0%		0%	0.0%
Historic King posts	5%	100%		100%	5%		100%	5.0%
non-rotten historic internal wood	5%	100%		100%	5%		100%	5.0%
non-historic concrete floor	5%	0%		0%	0%		0%	0.0%
other non-historic materials	5%	0%		0%	0%		0%	0.0%
Total materials	100%				61%			69%
Total historic & non-rotten materials	61%				92%			105%