



G.H.Design

Schedule of Photographs

For Works Before Commenced, Being Undertaken and Works Completed at

Lower House Farm
Middlehope
Craven Arms
Shropshire, SY7 9JT

Our Ref: 23-2568
Dated: 07 March 2023



Document Control Sheet

Client Name: Mr Rob Lugsdin
Site Address: Lower House Farm, Middlehope, Craven Arms, Shropshire, SY7 9JT
Report Title: Schedule of Photographs
Date: 7th March 2023
Our Ref: 23-2568

Revision	Date	Description of Revision (s)
-	07/03/2023	Retrospective Planning Submission

Contents

1.0	Section 1 - Photographs Before Works Commenced Taken in September 2022	4
2.0	Section 2 - Photographs Taken Whilst Works Were Being Undertaken Taken in October 2022	7
3.0	Section 3 - Photographs of Completed Works Taken in February 2023	11

Section 1

Photographs Before Works Commenced

Taken in
September 2022



Looking at East Elevation



Looking at West Elevation



Looking at South West Corner

Section 2

Photographs Taken Whilst Works Were Being Undertaken

Taken in
October 2022



Showing insulation and breather membrane on West elevation.



Showing insulation and breather membrane on West elevation and completed over boarding on South elevation.



Showing part completed over boarding to West elevation.



Showing part completed over boarding to West elevation.



Showing part completed over boarding to West elevation.

Section 3

Photographs of Completed Works

Taken in
February 2023



Looking at South West corner.



Looking at South elevation.



Looking at South East corner.



Looking at East elevation.



Looking at East elevation.



Looking at West elevation.