



Notes

- 1 Existing farmhouse
- 2 Existing stone barn/dairy
- 3 Former barn position. (barn destroyed by storm Arwen)
- 4 Existing hay and livestock barn
- 5 **Proposed secure machinery and feed store**

Greenholes Farm

Entrance drive



Revision	Description	Date

Please do not scale from this drawing. Any errors, omissions and discrepancies are to be reported to Insight Architectural Design (IAD) Ltd prior to use. The contractor must check and verify the dimensions of the whole site and building, including levels, sewer inverts and window openings prior to commencing work. This drawing is to be read with and checked against any specialist drawings, including those of the Structural Engineer prior to works commencing. The contractor must work in strict compliance with all British Standards, Building Regulations, Acts of Parliament and European Legislation. This drawing and the work shown are the copyright of IAD Ltd and cannot be copied without consent.

Drawing Status:	Approval

insight
Architectural Design
Greenholes Farm
Shield Hill
Haltwhistle, NE49 9NW
22GFH (EW) 02

Scale: 1/500 @ A3 Date: Nov'22
Drawn: JT Auth: