



01 PRINCIPLE ELEVATION (WITHIN GARDEN - FACING SOUTH)

W-01
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.

W-05
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.

W-09
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.

W-13 (no change)
 -Non original window opening
 -Non original concrete lintel
 -Non original double glazed (timber) casement

W-17 (no change)
 -Non original window opening
 -Non original concrete lintel
 -Non original double glazed (timber) casement

W-02
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.

W-06
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.

W-10
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.

W-14 (no change)
 -Non original window opening
 -Non original concrete lintel
 -Non original double glazed (timber) casement

W-03
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 no opening window

W-07
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.

W-11
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.

W-15 (no change)
 -Original window opening
 -Original stone Mullions
 -Non original double glazed (timber) casement

W-04
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.

W-08
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.

W-12
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.

W-16 (no change)
 -Non original window opening
 -Non original steel lintel
 -Non original double glazed (timber) casement

DRAWING TITLE
HOUSE EXISTING ELEVATIONS

PROJECT NAME **Double Glazed Windows**

SITE ADDRESS
 Rectory Farmhouse, 39 Toghill Lane, Doynton, South Glos, BS30 5SY

CLIENT **C Asprey / R Greenwood**

DATE	REV	ISSUED BY	TO	REMARK
04-11-21	1	DR	CA	Planning & LBC
10-05-23	2	JHC	CA	Planning & LBC


nash partnership
 Bath : 01225 442424 | 23a Sydney Buildings, Bath, BA2 6BZ
 Bristol : 0117 3327560 | The Generator, Counterslip, Redcliffe, Bristol, BS1 6BX
 www.nashpartnership.com
 mail@nashpartnership.com

NOTES / REMARKS

Summary
 Generally where original window openings remain, the window units are highly likely to be non original. Single glazed units causing ongoing harm within the interior of the building. Character deviated from likely original condition. Refer to other documents submitted as part of this application.



02 GARDEN ELEVATION (FACING NORTH WEST)



03 ELEVATION FACING DRIVEWAY (FACING EAST)

DATUM 82.00m A.O.D.

UM 82.00m A.O.D.

