



	201580E		UEGENDUTILITY LINETYPES
	DE		British Telecom BT Gas G Cable Television CATV Heading Pipes HP Closed Circuit Television CCTV HV Cables HV Communications C Multiple Services Route MSR Drainage DR Oil Oil Oil Drainage - Combined Water CW Oxygen OXY Drainage - Foul Water Street Lighting SL Drainage - Storm Water EW Street Lighting SL Drainage - Foul Water EW Traffic Signal Loop TSL Empty Duct ED Unknown -U Electric E Unknown Cable -UC Fire Hydrant Main FH Unknown Pipeline UPL Fibre Optic FO Water W Fuel FUEL Assumed Service Route - See GENERAL NOTES AsR ASR ASR ASR XXX ASR XXX ASR XXX ASR XXX ASR XXX ASR XXX M </th
North		587 <u>90N</u>	(Using abbreviation of service and colour as above) UTILITY SURVEY INFORMATION Located by Ground Penetrating Radar GPR Unable to Survey UTS Area of Concern — AOC— Unable to Survey UTL Contracted Survey Area — SVY AREA Unable to Trace II⊃ Previous Survey Area — PREVIOUS Unable to Trace due to blockage) IIm Depth to Top of Service (metres) (0.60d) Unable to Trace IIL
			ABREVIATIONS used on a PAS 128 Survey (0.65d B2P) 0.65d = Depth in metres, B2 = Quality Level, P = Post processed GPR TOPOGRAPHIC & UTILITY DETAILS Barrier (symbol - sized) Barrier Post Post Ballisha Beacon BB Bollard B Borbole Read Sign Briter Rodding Eye British Telecoms IC BTIC Stop Height + 50.00 Stop Light - 50.00 Cable into Ground Stop Cock Corr Level in metres CL 50.00 Distribution Board BB Earth Rod ER Eectric Sign Wall Embankment Wall FH Water Valve FH Water Valve
		587 <u>80N</u>	Flood Light ● FL Gas Valve ● GV Gate ● GV Ground Level in metres GL 50.00 Guiley ■ GU Inspection Cover ■ IC Building Canopy ■ GU Inspection Cover ■ IC Junction Box - BT ■ JB BT Junction Box - Comms ■ JB COM Junction Box - Elec ■ JB Elec Edge Detail (level in metres) 59.00 Light Bollard ● B Light Bollard ● B Hence + HERAS = + FO.00 Manhole ■ MH Manhole Capped Port ■ NH Pipe Diameter in millimetres 1000 Overhead Service Line + ERAS = + ERAS = + ERAS = + ERAS =
		587 <u>70N</u>	Centre of the sub-surface utility of the private source utility information may be shown where it assists with positional referencing. Where logic indicates a utility exists but which cannot be positively confirmed with the technology, an assumed route (ASR) is recorded. Survey Dimensions do not procure statutory or private source utility information as part of its detection service nor does it record any such information in a utility survey unless otherwise noted. Statutory plans should be consulted to supplement this survey. Vertical & Horizontal Position - Vertical position (depth) is indicative to the top of the utility/feature and is recorded as (depth to top of service) and should not be taken as exact. Where depth information is indicative to the copy of the utility/feature and is recorded as (depth to top of service) and should not be taken as exact. Where depth information from the technology is unclear, depth is not shown. Drains may have been detected using threading and the depth indicated could be between the top and the bottom of the drain. Horizontal position is indicative to the control there and should not be taken as exact. Warranty - Biodegradable paints are used to mark-out the position of the utility/feature and should not be taken as exact. Warranty - Biodegradable paints are used to mark-out the position of the utilities. Before long paint markings may become illegible depending on ground, weather and traffic conditions. No warranty is given in respect of the durability of the paint markings and that they are a complete representation of the sub-surface utilities therefore this drawing should be used as the primary reference for the survey results. This drawing does not provide an absolute representation of the sub-surface. Utilities have been detected using non-invasive technologies only and the performance can be adversely affected by ground, weather and site conditions outside of our control therefore some utilities it does not warant that 100% detection will be achieved and that appro
		587 <u>60N</u>	can be supplied on request. Irrespective of the information provided by a utility survey and statutory plans, excavation work should be undertaken with extreme caution and in accordance with HSE Guidelines - HSG47 Avoiding Danger from Underground Services Sheet 01 SHEET LAYOUT
		587 <u>50N</u>	Rev Description Drwn/Chk Date Survey Dimensions Ltd Image: Constraint of the second sec
	201580E	587 <u>40N</u>	Topographical Survey Scale: 1 : 100 @ A1 Drawn: MWS Date: 16-02-2022 Checked: PW Drawing Status: SURVEY Surveyor: KC Project Ref. Dwg No. Rev. THIS DRAWING IS COPYRIGHT. Consultants must check all dimensions on site. Only figured dimensions are to be used. Ding figured dimensions are to be used. This drawing shall be used only for the purpose intended. This drawing shall be used only for the purpose intended.



E201555	N58780	LEGEND UTILITY LINETYPES British Telecom Gas Cable Television Heating Pipes Closed Circuit Television HV Cables Communications Multiple Services Route Drainage Oil Drainage - Combined Water Oxygen Drainage - Foul Water Street Lighting Drainage - Storm Water Traffic Signal Loop Empty Duct Unknown Elocation Heating Cols
North		Electric Unknown Cable Fire Hydrant Main Unknown Pipeline Fibre Optic Water Fuel Assumed Service Route - See GENERAL NOTES (Using abbreviation of service and colour as above) ASR UTILITY SURVEY INFORMATION Located by Ground Penetrating Radar Located by Ground Penetrating Radar GPR Unable to Survey Vare of Concern Unable to Survey UT Previous Survey Area SVY AREA Unable to Infic (over) Depth to Top of Service (metres) (O.60d) Unable to Trace
	N58775	ABREVIATIONS used on a PAS 128 Survey (0.65d B2P) 0.65d = Depth in metres, B2 = Quality Level, P = Post processed GPR TOPOGRAPHIC & UTILITY DETAILS Barrier (symbol - sized) Barrier Poist O Belisha Beacon BB Bollard B Borehole Rain Water Pipe British Telecoms IC BTIC Building (incomplete detail) Spot Light Cable TV Box CTV Cable TV Box CTV Cort V Camera Stop Cock Distribution Board DB Electric Cabinet ECC Electric Cabinet ECC Electric Cabinet ECC Electric Cabinet ECC Electric Sign FH Wall Wall Gate Valve GU Gate Valve GU Gate Valve GU Electric Cabinet ECC Electric Pole EPP Fire Hydrant FH Gate GU Ground Level in metres IL 50:00 Grave GL
	N58770	Cerver Notes Service of the survey area. Any paint marks outside of the area are for investigative purposes only and may not represent the full extent of the sub-surface utilities. Only sub-surface utility information is provided. Above ground utility information may be shown where it assists with positional referencing. Where logic indicates a utility exists but which cannot be positively confirmed with the technology, an assumed route (ASR) is recorded. Survey Dimensions do not procure statutory or private source utility information as part of its detection service nor does it record any such information in a utility survey unless otherwise noted. Statutory plans should be consulted to supplement this survey. Vertical & Horizontal Position - Vertical position (depth) is indicative to the top of the utility/feature and is recorded as (depth to top of service) and should not be taken as exact. Where depth information from the technology is unclear, depth is not shown. Drains may have been detected using threading and the depth indicated could be between the top and the
	N58765	bottom of the drain. Horizontal position is indicative to the centre of the utility/feature and should not be taken as exact. Warranty - Biodegradable paints are used to mark-out the position of the utilities. Before long paint markings may become illegible depending on ground, weather and traffic conditions. No warranty is given in respect of the durability of the paint markings and that they are a complete representation of the sub-surface utilities therefore this drawing should be used as the primary reference for the survey results. This drawing does not provide an absolute representation of the sub-surface. Utilities have been detected using non-invasive technologies only and the performance can be adversely affected by ground, weather and site conditions outside of our control therefore some utilities may be undetectable. While we use reasonable endeavours to detect all utilities it does not warrant that 100% detection will be achieved and that approximate depth penetration of the technologies will be greater than two metres. Sewer and manhole details shown on this drawing have been obtained by observation and measurement from the surface and as such cannot be guaranteed. Where precise sewer details will be critical to the project design we would recommend that entry into the chamber be undertaken using a specialist team, appropriately qualified for confined space entry. These teams can be supplied on request. Irrespective of the information provided by a utility survey and statutory plans, excavation work should be undertaken with extreme caution and in accordance with HSE Guidelines - HSG47 Avoiding Danger from Underground Services
	N58760	Sheet 01 SHEET LAYOUT Rev Description Drwn/Chk Date Survey Dimensions Ltd Output Measured surveys of land and buildings 01726 390 010 +44 (0) 7970 205 932 Output
	N58755	+44 (0) 7970 205 935 info@SurveyDimensions.co.uk Project Title: 42 Fore Street Bugle St.Austell PL26 8PE Client: Ben Evans Drawing Title: Ground Floor Plan scale: 1:50 @ A1 Drawn: MWS Date: 16-02-2022 Checked: PW
E201555		Drawing Status: SURVEY Surveyor: KC Project Ref. Dwg No. Rev 220116 D2 THIS DRAWING IS COPYRIGHT. Contractors and Consultants must check all dimensions on site. Only figured dimensions are to be used.



E201555	N58780	LEGEND UTILITY LINETYPES British Telecom Gas Cable Television Heating Pipes Closed Circuit Television HV Cables Communications Multiple Services Route Drainage Oil Drainage - Foul Water Oxygen Drainage - Foul Water Street Lighting Drainage - Storm Water Traffic Signal Loop Empty Duct Unknown Electric Unknown Cable
North		Locato Unknown Pipeline Fire Hydrant Main Unknown Pipeline Fibre Optic Water Fuel Assumed Service Route - See GENERAL NOTES Assumed Service Route - See GENERAL NOTES ASR (Using abbreviation of service and colour as above) UTILITY SURVEY INFORMATION Located by Ground Penetrating Radar GPR Unable to Survey UTS Area of Concern Unable to Survey UTL Previous Survey Area SVY AREA Unable to Trace IID Previous Survey Area PREVIOUS Unable to Trace due to blockage) IIIL Located to Trace IILL End of Trace IILL
	N58775	ABREVIATIONS used on a PAS 128 Survey (0.65d B2P) 0.65d = Depth in metres, B2 = Quality Level, P = Post processed GPR TOPOGRAPHIC & UTILITY DETAILS Barrier Post Post Beisha Beacon Barler Post Post Bollard Barler Post Post Bollard Barler Post Post Bollard Barler Post Post Building (incomplete detail) Statististic Sign Post Spot Light Sst Building (incomplete detail) Spot Light Spot Light Sst Cable in Ground CtrV Stop Cock Stop Core Level in metres CL 50.00 Telephone Pole Tr Direction of Flow (Drainage) Traffic Light Improvement VP Earth Rod ER Tree VP VP Electric Cabinet Epf Vent Pipe VV VP Electric Cabinet EP Vent Pipe VV VP Electric Cabinet EP EP Vent Pipe VV Electric Cabinet EC ER Stop Cock
	N58770	Utilities may continue outside of the survey area. Any paint marks outside of the area are for investigative purposes only and may not represent the full extent of the sub-surface utilities. Only sub-surface utility information is provided. Above ground utility information may be shown where it assists with positional referencing. Where logic indicates a utility exists but which cannot be positively confirmed with the technology, an assumed route (ASR) is recorded. Survey Dimensions do not procure statutory or private source utility information as part of its detection service nor does it record any such information in a utility survey unless otherwise noted. Statutory plans should be consulted to supplement this survey. Vertical & Horizontal Position - Vertical position (depth) is indicative to the top of the utility/feature and is recorded as (depth to top of service) and should not be taken as exact. Where depth information from the technology is unclear, depth is not shown. Drains may have been detected using threading and the depth indicated could be between the top and the
	N58765	 bottom of the drain. Horizontal position is indicative to the centre of the utility/feature and should not be taken as exact. Warranty - Biodegradable paints are used to mark-out the position of the utilities. Before long paint markings may become illegible depending on ground, weather and traffic conditions. No warranty is given in respect of the durability of the paint markings and that they are a complete representation of the sub-surface utilities therefore this drawing should be used as the primary reference for the survey results. This drawing does not provide an absolute representation of the sub-surface. Utilities have been detected using non-invasive technologies only and the performance can be adversely affected by ground, weather and site conditions outside of our control therefore some utilities may be undetectable. While we use reasonable endeavours to detect all utilities it does not warrant that 100% detection will be achieved and that approximate depth penetration of the technologies will be greater than two metres. Sewer and manhole details shown on this drawing have been obtained by observation and measurement from the surface and as such cannot be guaranteed. Where precise sewer details will be critical to the project design we would recommend that entry into the chamber be undertaken using a specialist team, appropriately qualified for confined space entry. These teams can be supplied on request. Irrespective of the information provided by a utility survey and statutory plans, excavation work should be undertaken with extreme caution and in accordance with HSE Guidelines - HSG47 Avoiding Danger from Underground Services
	N58760	Sheet 01 SHEET LAYOUT Rev Description Drwn/Chk Date Survey Dimensions Ltd Output Measured surveys of land and buildings Measured surveys of land and buildings 01726 390 010 +44 (0) 7970 205 932 Dimensions Ltd
	N58755	+44 (o) 7970 205 935 info@SurveyDimensions.co.uk www.SurveyDimensions.co.uk Image: Colored Street Project Title: 42 Fore Street Bugle St.Austell PL26 8PE Image: Colored Street Client: Ben Evans Drawing Title: First Floor Plan Scale: 1:50 @ A1 Drawn: MWS Date: 16-02-2022 Checked:
E201555		Drawing Status: SURVEY Surveyor: KC Project Ref. Dwg No. Rev. 220116 03 Rev. THIS DRAWING IS COPYRIGHT. Contractors and Consultants must check all dimensions on site. Only figured dimensions are to be used.




	1		
	N58780	UTILITY LINETYPES British Telecom Cable Television Closed Circuit Television	Gas Heating Pipes HV Cables
- E201555		Communications Drainage Drainage - Combined Water Drainage - Foul Water	Multiple Services Route
555		Drainage - Pour water Drainage - Storm Water Empty Duct Electric	Traffic Signal Loop Unknown Unknown Cable
		Fire Hydrant Main Fibre Optic Fuel	Unknown Pipeline Water
		Assumed Service Route - See GENERAL NOTES — (Using abbreviation of service and colour as above) UTILITY SURVEY INFORMATION	ASR—XXX ——
North		Located by Ground Penetrating Radar GPR Area of Concern Contracted Survey Area SVY AREA	Unable to Survey UTS Unable to Lift (cover) UTL Unable to Trace Ⅱ⊃
		Previous Survey Area PREVIOUS Depth to Top of Service (metres) (0.60d)	Unable to Trace (due to blockage) IIC Unable to Trace Further IIL End of Trace III
		ABREVIATIONS used on a PAS 128 Survey (0.65d B2P) 0.65d = Depth in metres, B2 = Quality Level, P = Post pro TOPOGRAPHIC & UTILITY DETAILS	cessed GPR
		Barrier (symbol - sized) Belisha Beacon	Post O PO Rain Water Pipe O RWP
		Bollard Borehole British Telecoms IC Br IC	Road Sign O RS Rodding Eye RE Sign Post O SP Spot Light O SL
		Building (incomplete detail) Cable into Ground & Cable TV Box	Spot Light -+ 50.00 Stop Cock \diamond SC Stop Valve \square SV
		CCTV Camera Cover Level in metres CL 50.00 Direction of Flow (Drainage)	Survey Station Telephone Pole Traffic Light
	N58775	Distribution Board DB Earth Rod ER Electric Cabinet EC	Tree O
		Electric Pole	Vent Pipe OVP Wall Waste Pipe OWP
		Feeder Pillar FP Fire Hydrant FH Flag Pole FP	Water Meter O WM Water Valve U Water
		Flood Light O FL Gas Valve O GV Gate O GV	
		Ground Level in metres GL 50.00 Gulley GU Inspection Cover IC	Building Canopy
		Invert Level in metres IL 50.00 Junction Box - BT JB BT Junction Box - Comms JB COM Junction Box - Elec JB Elec	Drainage Channel Drop Kerb (level in metres)50.00 Edao Detail (level in metree)50.00
		Lamp Post LIP Light Bollard LIB Light in ground OLIG	Footpath (level in metres)
		Manhole MH Manhole Capped Port JC Pipe Diameter in millimetres 1000	Kerb channel (level in metres) + 50.00 Kerb top (level in metres) + 50.00Tk Overhead Service Line - 50.00Tk
		Pipe into Ground	Pedestrian Railing
		General Note	S
		Utilities may continue outside of the survey area. Any investigative purposes only and may not represent the	paint marks outside of the area are for
	N58770	Only sub-surface utility information is provided. Above	
		where it assists with positional referencing. Where logic indicates a utility exists but which cannot I	be positively confirmed with the
		technology, an assumed route (ASR) is recorded. Survey Dimensions do not procure statutory or private	e source utility information as part of its
		detection service nor does it record any such informat noted. Statutory plans should be consulted to suppler	ion in a utility survey unless otherwise
		Vertical & Horizontal Position - Vertical position (de utility/feature and is recorded as (depth to top of serv	ice) and should not be taken as
		exact. Where depth information from the technology have been detected using threading and the depth inco bottom of the drain. Horizontal position is indicative to	licated could be between the top and the
		not be taken as exact. Warranty - Biodegradable paints are used to mark-ou	it the position of the utilities. Before long
		paint markings may become illegible depending on gro warranty is given in respect of the durability of the pai representation of the sub-surface utilities therefore th	nt markings and that they are a complete
		reference for the survey results.	
		This drawing does not provide an absolute representa detected using non-invasive technologies only and the ground, weather and site conditions outside of our con-	e performance can be adversely affected by ntrol therefore some utilities may be
		undetectable. While we use reasonable endeavours to 100% detection will be achieved and that approximate be greater than two metres.	
		Sewer and manhole details shown on this drawing hav measurement from the surface and as such cannot be	
	N58765	will be critical to the project design we would recomm undertaken using a specialist team, appropriately qual	end that entry into the chamber be
		can be supplied on request. Irrespective of the information provided by a utility sur	
		work should be undertaken with extreme caution and i HSG47 Avoiding Danger from Underground Services	in accordance with HSE Guidelines -
		Sheet 0	1
		SHEET LAYOUT	
	NE0700		
	N58760		
		Rev Description	Drwn/Chk Date
		Survey Dimensi	ons Ltd 🕢
		Measured surveys of land	
		01726 390 010 +44 (0) 7970 205 932 +44 (0) 7970 205 935	• *****
		info@SurveyDimensions.co.uk www.SurveyDimensions.co.uk	
		Project Title:	
		42 Fore Street Bugle	
		St.Austell PL26 8PE	
	N69765	_{Client:} Ben Evans	
	N58755	Drawing Title:	
		Second Floor Plan	
		Scale: 1:50 @ A1 Draw	m: MWS
		Date: 16-02-2022 Checke	
		Status: SURVEY Survey	Dwg No. Rev.
E201555		220116 THIS DRAWING IS COPYRIGHT. Contractors and Co	04 Donsultants must check all dimensions on site.
01		Only figured dimension	



Datum: 140.00m Front Elevation

1:100 0 2m 4m 6m 8m 10m





Side Elevation

Datum: 140.00m

Datum: 140.00m

Rear Elevation

	LEGE	ND	
UTILITY LINETYPES			
British Telecom	——вт——	Gas	—— G ——
Cable Television	CATV	Heating Pipes	—— HP ——
Closed Circuit Television		HV Cables	—— HV ——
Communications	C	Multiple Services Route	MSR
Drainage	DR	Oil	
Drainage - Combined Water Drainage - Foul Water	CW	Oxygen Street Lighting	SL
Drainage - Storm Water	sw	Traffic Signal Loop	
Empty Duct	ED	Unknown	U
Electric	— Е — —	Unknown Cable	UC
Fire Hydrant Main	—— FH ——	Unknown Pipeline	
Fibre Optic	——F0——	Water	w
Fuel Assumed Service Route - See GENER/		—ASR—XXX —ASR—XXX —	-ASR-XXX -
(Using abbreviation of service and colou UTILITY SURVEY INFORMATION			
Located by Ground Penetrating Radar	GPR	Unable to Survey	UTS
Area of Concern	AOC	Unable to Lift (cover)	UTL
Contracted Survey Area	SVY AREA	Unable to Trace	IID
Previous Survey Área	PREVIOUS	Unable to Trace (due to blockage)	IΩ
Depth to Top of Service (metres)	(O.60d)	Unable to Trace Further	114
		End of Trace	IШ
ABREVIATIONS used on a PAS 12	28 Survey		
(O.65d B2P) 0.65d = Depth in metres,	B2 = Quality Level, P = Post	t processed GPR	
TOPOGRAPHIC & UTILITY DETA			
Barrier (symbol - sized)	Barrier	Post	O PO
Belisha Beacon	🔴 BB	Rain Water Pipe	O RWP
Bollard	• B	Road Sign	O RS
Borehole	÷	Rodding Eye	♦ RE
British Telecoms IC		Sign Post	O SP
		Spot Light	O SL
Building (incomplete detail)	_	Spot Height	+ 50.00
Cable into Ground	\sim	Stop Cock	♦ SC
Cable TV Box	CTV	Stop Valve	🗆 SV
CCTV Camera		Survey Station	
Cover Level in metres	CL 50.00	Telephone Pole	О ТР
Direction of Flow (Drainage)	_>	Traffic Light	0
Distribution Board	DB	Tree	
Earth Rod		1166	<u> </u>
Electric Cabinet	EC	Unknown Valve	UV 🗌
Electric Pole		Vent Pipe	O VP
Electric Sign		Wall	
Embankment	Betom	Waste Pipe	O WP
Feeder Pillar	🖂 FP	Water Meter	O WM
Fire Hydrant		Water Valve	□ Water
Flag Pole	O FP		
Flood Light	() FL		
Gas Valve Gate	♦ GV		
Ground Level in metres	GL 50.00		
Gulley Inspection Cover	GU	Building Canopy	
Invert Level in metres	□ IC IL 50.00	Crash Barrier	
Junction Box - BT	JB BT	Drainage Channel	
Junction Box - Comms		Drop Kerb (level in metres)	50.00
Junction Box - Elec		Edge Detail (level in metres)	<u> </u>
Lamp Post		Footpath (level in metres)	50.00
Light Bollard	• LB	Fence	/
Light in ground	OLIG	Heras Fence	
Manhole	I MH	Kerb channel (level in metres)	50.00
Manhole Capped Port	 	Kerb top (level in metres)	50.00Tk
Pipe Diameter in millimetres	100Ø	Overhead Service Line	
Pipe into Ground	\oplus	Pedestrian Railing	//

General Notes

Utilities may continue outside of the survey area. Any paint marks outside of the area are for investigative purposes only and may not represent the full extent of the sub-surface utilities.

Only sub-surface utility information is provided. Above ground utility information may be shown where it assists with positional referencing.

Where logic indicates a utility exists but which cannot be positively confirmed with the technology, an assumed route (ASR) is recorded.

Survey Dimensions do not procure statutory or private source utility information as part of its detection service nor does it record any such information in a utility survey unless otherwise noted. Statutory plans should be consulted to supplement this survey.

Vertical & Horizontal Position - Vertical position (depth) is indicative to the top of the utility/feature and is recorded as (depth to top of service) and should not be taken as exact. Where depth information from the technology is unclear, depth is not shown. Drains may have been detected using threading and the depth indicated could be between the top and the bottom of the drain. Horizontal position is indicative to the centre of the utility/feature and should not be taken as exact.

Warranty - Biodegradable paints are used to mark-out the position of the utilities. Before long paint markings may become illegible depending on ground, weather and traffic conditions. No warranty is given in respect of the durability of the paint markings and that they are a complete representation of the sub-surface utilities therefore this drawing should be used as the primary reference for the survey results.

This drawing does not provide an absolute representation of the sub-surface. Utilities have been detected using non-invasive technologies only and the performance can be adversely affected by ground, weather and site conditions outside of our control therefore some utilities may be undetectable. While we use reasonable endeavours to detect all utilities it does not warrant that 100% detection will be achieved and that approximate depth penetration of the technologies will be greater than two metres.

Sewer and manhole details shown on this drawing have been obtained by observation and measurement from the surface and as such cannot be guaranteed. Where precise sewer details will be critical to the project design we would recommend that entry into the chamber be undertaken using a specialist team, appropriately qualified for confined space entry. These teams can be supplied on request.

Irrespective of the information provided by a utility survey and statutory plans, excavation work should be undertaken with extreme caution and in accordance with HSE Guidelines - HSG47 Avoiding Danger from Underground Services



