

Job no: drawing no: revision: scale @ A3 date: drawn by: checked by:

2309 - SV-04 B

4 May 2023

IDP


-

project:
Brecklands, Lower Froyle

drawing:
Window schedule



PERRY + BELL LTD
ARCHITECTS
21 WOODSTOCK ST
LONDON W1C 2AP



architecture@perryandbell.com T: 020 7495 6636

Rev	Comment
A	Windows updated
B	Windows updated

Issued By	Issue Date
IDP	17-07-2023
IDP	25-07-2023

Window List

ID	size (mm)	description	condition	Proposed action
F 04	1,653×975	Single glazed Timber frame casement window	Paintwork flaking	Replace with new double glazed painted timber window to match
F 05	550×975	Single glazed Timber frame casement window	Paintwork minor flaking	Replace with new double glazed painted timber window to match
F 06	1,653×975	Single glazed Timber frame casement window	Paintwork flaking	Replace with new double glazed painted timber window to match
F 07	550×975	Single glazed Timber frame casement window	Paintwork minor flaking	Replace with new double glazed painted timber window to match
F 08	1,109×975	Single glazed Timber frame casement window, sill flush to wall	Paintwork minor flaking	Replace with new double glazed painted timber window to match
F 09	1,109×975	Single glazed Timber frame casement window, sill flush to wall	Paintwork minor flaking, no projecting sill	Replace with new double glazed painted timber window to match
F 10	1,109×975	Single glazed Timber frame casement window, sill flush to wall	Paintwork minor flaking, no projecting sill	Replace with new double glazed painted timber window to match
F 11	1,109×975	Single glazed Timber frame casement window	Paintwork minor flaking, no projecting sill	Replace with new double glazed painted timber window to match
F 12	1,109×975	Modern timber casement window (in new extension)	Paintwork flaking but timber appears sound	Replace with new double glazed painted timber window to match

Survey