

Photo Schedule: Dyrham Mansion Fire Stopping Proposals

Roof void compartmentation wall



View of section of wall to receive fire stopping alterations



View of section of wall to receive fire stopping alterations



Gap to top of existing stone wall



Gap to top of existing wall



View of other side of proposed compartmentation wall from previous photos.



Example of existing fire stopping installed to different sections of roof



Modern door within roof void containing asbestos to be replaced.



Modern hatch within roof void containing asbestos to be replaced