



Gas Protection Validation Site Record

One record sheet to be completed per plot. To be completed by the ERGO Professional Inspecting

Site: <i>Suncroft</i>	Plot no: <i>Plot 1</i>	Inspection date/time: <i>9/11/22</i>
Inspection by: <i>JM</i>	Installers: <i>DP</i>	Photographed: <input checked="" type="checkbox"/>

Complete <input checked="" type="checkbox"/>	Membrane Type	Laps and joins	Membrane Condition (inc. underside)	Extent of coverage
Remarks inc. any repairs	<i>Correct</i>	<i>Adequate and sealed</i>	<i>Swept prior to laying</i>	<i>Full, Adequate</i>
	<i>Minor pinpoints identified and completed under supervision</i>	Please select: <input checked="" type="checkbox"/> Taped <input type="checkbox"/> Hand welded <input type="checkbox"/> Auto welded <input type="checkbox"/> Other (please state)		

Complete <input checked="" type="checkbox"/>	Service Entries	Damp Proof Course	Test Type
Remarks inc. any repairs	<i>Adequately sealed</i>	<i>Correct</i>	<input checked="" type="checkbox"/> Pick Test / Air Lance
	Pre-formed: <input checked="" type="checkbox"/> y / n		

This Plot has **PASSED/FAILED*** inspection. (Any proposed remedial works will be noted in the "Remarks" column on this form).
 An additional inspection visit IS/IS NOT* required for this Plot.

Inspection by: *J. Malley* Signed: 