


Existing Stables



Old-fashioned and damaged Linear wooden stables block comprising 1 feedroom (RHS) and 3 stables. Currently these buildings are dangerous and horses can only stay in them during the day when someone is here in case of collapse. Some illustrations of damage shown below:



RHS Stable: Front lifted and door can no longer be closed



Middle stable: Front pushed no longer attached and can easily be pushed out and collapse



Left hand side stable damage to front and door not functioning