



ABOVE

Rendered image of Bighton Road boundary with existing vehicle entrance gates and driveway in-filled with brickwork to match and align with existing garden wall. Tarmac removed and grass verge established.

LEFT

Photograph of Bighton Road boundary showing existing inset vehicle entrance gates and tarmac driveway.