



Fig.1 - West Wing Elevation - General Photo

Not to Scale





- Brickwork

- Timber

- Failing render

- Stonework

- Render removal

Not to Scale

Fig.2 - Parapet Wall Render