



SURVEYED BY
GUILDFORD & WISBECH SURVEYS
 ORCHARD HOUSE
 HIGH ROAD
 WISBECH ST. MARY
 WISBECH
 PE13 4RA
 MOB: 07588 510886
 Email: jcshowell@msn.com

S1093

Symbols

- +10.00 Level Position
- / — Fence
- ⊕ Step Up
- ⊖ Gates
- 100 → □ Foul Drainage (100mm Pipe)
- ⊙ Trunk Diameter
⊙ Height
⊙ Spread

Abbreviations

- ac Assumed Pipe Connection
- ap/s Approximate Position & Size
- BIS Block Support
- BrW Brick Wall
- CB Close Boarded Fence
- CL Inspection Cover Level
- FB Flower Bed
- G Gully
- h High/Height
- IC Inspection Cover
- IL Pipe Invert Level
- MH Manhole
- OSBM OS Benchmark
- PF Picket Fence
- RL Ridge Level
- StrW Stone Retaining Wall
- STW Stone Wall
- SVP Soil Vent Pipe
- TP Telephone Pole
- UTL Unable to Lift
- VP Vent Pipe
- WHL Window Head Level
- WL Wall Level
- WM Water Meter
- WSL Window Sill Level

Notes

Level Datum: Newlyn
 Bench Marks Used: O.S.B.M.
 Cutmark on Wall,
 34 Glapthorn Road,
 South West Face.
 Value 40.764m.

JOB TITLE

**34a Glapthorn Road
 Oundle
 Peterborough
 PE8 4JQ**

DRAWING TITLE

Topographic Survey

DRAWING 1 OF 1		DIGITAL DATA FILE NAME		
JOB No. S1093		34a Glapthorn Road		
SCALE 1/100		REVISION SUFFIX		
SHEET SIZE A2	DATE May 2023	SURVEYOR JCS	ASST N/A	CHECKED JCS