

Tree Survey Data

No.	Species	Age	DBH	Stems	Height	Crown Spread				CH	EstD	General Observations	EstCont	BS Cat	Recommendation
						N	S	E	W						
1	Tibetan Cherry	Y	5	1	3	1	1	1	1	0.5	N	Not located on topographical survey - location estimated.	40+	C1	No work required
2	Norway Maple	Y	14	2-5	6	2	1	2	2	0.5	N	Split branch union at 1m - very poor form.	<10	U	Fell
3	Silver Maple	Y	14	2-5	5	2	2	2	2	1.5	N		cbi.	C1	No work required
4	Field Maple	Y	13	1	5	2	2	2	1	0.5	N	Suppressed and poor form.	40+	C2	No work required
5	Field Maple	Y	8	1	5	2	2	1	1	0.5	N	supp poor form.	40+	C2	No work required
6	Aspen	Y	20	1	8	3	3	2	3	0.5	N	Suppressed and poor form. Crown has poor quality branch form and attachments - suspected non-integrated wood fibres in branch unions - structural defect.	20+	C1	No work required
7	Aspen	Y	20	1	8	3	3	3	2	0.5	N	Crown has poor quality branch form and attachments - suspected non-integrated wood fibres in branch unions - structural defect.	20+	C1	No work required
8	Aspen	Y	18	1	8	3	3	2	3	0.5	N	Crown has poor quality branch form and attachments - suspected non-integrated wood fibres in branch unions - structural defect.	20+	C1	No work required

No.	Species	Age	DBH	Stems	Height	Crown Spread				CH	EstD	General Observations	EstCont	BS Cat	Recommendation
						N	S	E	W						
9	Aspen	Y	20	2-5	8	3	3	3	3	0.5	N	Crown has poor quality branch form and attachments - suspected non-integrated wood fibres in branch unions - structural defect.	20+	C1	No work required
10	Birch spp	Y	10	1	6	3	2	2	2	1.5	N		40+	C1	No work required
11	Ash	Y	18	1	8	3	0.5	2	2	0.5	N	Symptoms of early infection by Ash Dieback.	10+	C1	No work required
12	Horse Chestnut	Y	5	2-5	2.5	1	1	1	1	0.5	N		40+	C1	No work required
13	Horse Chestnut	Y	8	2-5	3	2	1	1	1	0.5	N		40+	C1	No work required
14	Birch spp	Y	9	1	6	1	2	1	1	1	N		40+	C1	No work required
15	Horse Chestnut	Y	11	1	5	2	2	2	2	1	N		40+	C1	No work required
16	Field Maple	Y	8	2-5	5	2	0.5	2	2	1	N	Multi-stemmed.	40+	C1	No work required
17	Crack Willow	M	100	2-5	15	8	9	8	8	1	Y	Off-site. Multi-stemmed base. Other side of boundary watercourse.	20+	B1	No work required