



Notes _____

1. Copyright Jessop and Cook Architects Limited. 2. Do not scale from drawings, all dimensions to be checked on site.

3. For more information on the condition of the fabric of the Barn and Stables please refer to the report produced by Hall & Ensom Chartered Surveyors "Building Condition Survey in respect of Lords Farm Barn" (August 2019).

Demolition of walls, partitions and other ____ structures — — Boundaries

-stonesfield slates ΖÞ -painted timber \searrow casement window with timber lintel course rubblestone -painted timber casement window with timber lintel

Existing Stables

Revisions

for

PLANNING ISSUE

Conversion of thrashing barn into residence at Lords Farm, 2 Queen Street Eynsham, Witney OX29 4HQ

Oxford Preservation Trust 10 Turn Again Lane, St Ebbes, Oxford. OX1 1QL Drawing title

Sections and Elevations Existina

LAISting	WEST WING, 9 PARK END 0XFORD 0X1		
JESSOP & COC ARCHITECTS	T:01865 591 E: info@jes:	.212 sopandcook.co.uk andcook.co.uk	
Scale at A1 1:100	^{Date} Sep 19	Drawn by AB	Checked
Drawing number P.1354_08	31	Revision	