


Existing Living/Kitchen Architrave Detail (1:1)

Note: Profile taken from First Floor Living room Window Architrave. No Architrave currently present to the Kitchen window.



Proposed Living/Kitchen Architrave Detail (1:1)

Note: Detail is a profile match of the original architrave within the Living Room/Kitchen which is to be retained. New architrave to be installed to Living room and Kitchen windows only.

