23B Windsor Street, Edinburgh, EH7 5LA

Photographic Fabric Survey 16/10/2023





1 Windsor Street – No External Painting

2 Windsor Street – No External Painting





3 Windsor Street – No External Painting

4 Windsor Street – No External Painting








6 Windsor Street – Window Reveals Painted



7 Windsor Street – Basement Wall Painted & Window Reveals Painted



8 Windsor Street – Basement Wall Painted, Partial Upper Wall Painted & Window Reveals Painted







9 Windsor Street – Entrance Columns Painted

10 Windsor Street – Basement Wall, Entrance Columns & Window Reveals Painted








12 Windsor Street – Basement Wall, Entrance Columns & Window Reveals Painted



13 Windsor Street – Basement Wall, Entrance Columns & Window Reveals Painted



14 Windsor Street – Basement Wall, Entrance Columns & Window Reveals Painted





15 Windsor Street – No External Painting

16 Windsor Street – Basement Wall, Entrance Columns & Window Reveals Painted







18 Windsor Street – Basement Wall, Entrance Columns & Window Reveals Painted




19 Windsor Street – No External Painting



20 Windsor Street – Entrance Columns Painted








22 Windsor Street – Entrance Columns Painted








24 Windsor Street – Entrance Columns Painted








26 Windsor Street – Upper Elevation & Columns Painted






28 Windsor Street – No External Painting

27 Windsor Street – Entire Elevation Painted





29 Windsor Street – Entire Elevation Painted

30 Windsor Street – No External Painting



31 Windsor Street – Basement Wall Painted