

LEVEL MONITORING

for Subsidence Management Services

8 Taylers Cottages, Potters Bar, EN6 3LL

Client:	Subsidence Management Services
Client Contact:	Ian Domigan
Claim Number:	500401678
Client Reference:	IFS-LBG-SUB-22-0104199
Policy Holder:	Mr Trevor Williams
Report Date:	14 July 2023
Our Ref:	M20164

Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4
28/12/2022	11.2507	11.1322	11.1983	11.5491
24/01/2023	11.2514	11.1325	11.1983	11.5497
23/02/2023	11.2512	11.1331	11.1988	11.5494
23/03/2023	11.2507	11.1321	11.1971	11.5478
19/05/2023	11.2512	11.1333	11.1972	11.5474
15/06/2023	11.2497	11.1311	11.1977	11.5470
13/07/2023	11.2504	11.1311	11.1980	11.5477



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

TBM is a manhole outside the property. No remote datum. If this is not suitable, please advise if a deep datum is required.

Site Visit: 28 December 2022

Tech advise site plan isn't correct as looks like requested stud is wanted next door and unable to get permission from them. Please advise if still needed.