

Monitoring Details

Provider Name:	My Home Needs Ltd	Monitoring Interval:	6 Weekly
Instruction Date:	14/08/2023	Number of Visits:	50
Reading Date:	30/10/2023	Visits Completed:	2
Date of Issue:	31/10/2023	Visits Outstanding:	48


Client Details

Client:	Questgates	Engineer / Handler:	Chelsea Beddows
Job Reference:	QG1T1228431		

Monitored Address

Occupier:	
Address:	Flat 3, 21 Mount Park Road, London, W5 2RS
Telephone:	Email:

Site Plan



Level Readings (Displayed in metres)


Visits	1	2	3	4	5	📌 DATUM
31/08/2023	10.2394	10.2011	10.0092	10.1266	10.0705	10.0000
30/10/2023	10.2397	10.2021	10.0110	10.1265	10.0707	10.0000

DATUM: TBM is a manhole in front of property.

Level Readings Difference (Displayed in millimetres)

Visits	1	2	3	4	5	📌 DATUM
31/08/2023	N/A	N/A	N/A	N/A	N/A	N/A
30/10/2023	0.30 ↑	1.00 ↑	1.80 ↑	-0.10 ↓	0.20 ↑	0.00 =

Relative Movement (Relative Survey, for illustration purposes only)




■ Baseline

■ Visit 1 (31/08/2023)

■ Visit 2 (30/10/2023)

Level Readings Chart



Homeowner Notes

Visit	Homeowner Notes
31/08/2023	No concerns raised.
30/10/2023	No concerns raised.