



## Photographic Log – RO102

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 14	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Made Ground arisings from 12.0m to 13.5m bgl.			
<b>Photo No.</b> 14	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Made Ground arisings from 13.5m to 15.0m bgl.			

## Photographic Log – RO102

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 15	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Made Ground arisings from 15.0m to 16.5m bgl.			
<b>Photo No.</b> 16	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Natural arisings from 18.0m to 19.5m bgl.			



## Photographic Log – RO102

<b>Client Name:</b> Glenny LLP	<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
-----------------------------------	---	-------------------------------


<b>Photo No.</b> 17	<b>Date</b> September 2023	
<b>Description:</b> RO102 – Natural arisings from 19.5m to 21.0m bgl.		


<b>Photo No.</b> 18	<b>Date</b> September 2023	
<b>Description:</b> RO102 – Natural arisings from 21.0m to 22.5m bgl.		

## Photographic Log – RO102


<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 19	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Natural arisings from 22.5m to 24.0m bgl.			
<b>Photo No.</b> 20	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Natural arisings from 24.0m to 25.5m bgl.			

### Photographic Log – RO102



<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 21	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Natural arisings from 25.5m to 27.0m bgl.			

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 22	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Natural arisings at 29.0m bgl.			



### Photographic Log – RO102

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 23	<b>Date</b> September 2023		
<b>Description:</b> RO102 – Natural arisings from 27.0m to 30.0m bgl.			

### Photographic Log – RO103

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 24	<b>Date</b> September 2023		
<b>Description:</b>  RO103 – Made Ground arisings from ground level to 1.00m bgl.			
<b>Photo No.</b> 25	<b>Date</b> September 2023		
<b>Description:</b>  RO103 – Made Ground arisings from 2.00m to 3.00m bgl.			

### Photographic Log – RO103



<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 26	<b>Date</b> September 2023		
<b>Description:</b> RO103 – Made Ground arisings from 3.00m to 4.00m bgl.			
<b>Photo No.</b> 27	<b>Date</b> September 2023		
<b>Description:</b> RO103 – Made Ground arisings from 5.00m to 6.00m bgl.			





### Photographic Log – RO103

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 28	<b>Date</b> September 2023		
<b>Description:</b> RO103 – Made Ground arisings from 6.00m to 7.50m bgl.			
<b>Photo No.</b> 29	<b>Date</b> September 2023		
<b>Description:</b> RO103 – Made Ground arisings at 10.5m bgl.			

### Photographic Log – RO103

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 30	<b>Date</b> September 2023		
<b>Description:</b> RO103 – Made Ground arisings from 12.00m to 13.50m bgl.			
<b>Photo No.</b> 31	<b>Date</b> September 2023		
<b>Description:</b> RO103 – Made Ground arisings from 13.50m to 15.00m bgl.			



### Photographic Log – RO103

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 32	<b>Date</b> September 2023		
<b>Description:</b> RO103 – Made Ground arisings from 15.00m to 16.50m bgl.			
<b>Photo No.</b> 33	<b>Date</b> September 2023		
<b>Description:</b> RO103 – Natural arisings at 18.00m bgl.			

## Photographic Log – RO103

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells		<b>Project No.:</b> 561063	
<b>Photo No.</b> 34	<b>Date</b> September 2023				
<b>Description:</b>  RO103 – Natural arisings from 19.50m to 21.00m bgl.					
<b>Photo No.</b> 35	<b>Date</b> September 2023				
<b>Description:</b>  RO103 – Natural arisings from 23.00m to 25.00m bgl.					

## Photographic Log – RO104

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 36	<b>Date</b> September 2023		
<b>Description:</b> RO104 – Made Ground arisings from ground level to 3.00m bgl.			
<b>Photo No.</b> 37	<b>Date</b> September 2023		
<b>Description:</b> RO104 – Made Ground arisings from 4.50m to 6.00m bgl.			

## Photographic Log – RO104

<b>Client Name:</b> Glenny LLP		<b>Site Location:</b> Chapman Way, Tunbridge Wells	<b>Project No.:</b> 561063
<b>Photo No.</b> 38	<b>Date</b> September 2023		
<b>Description:</b>  RO104 – Made Ground arisings from 6.00m to 7.50m bgl.			
<b>Photo No.</b> 39	<b>Date</b> September 2023		
<b>Description:</b>  RO104 – Made Ground arisings from 9.00m to 10.50m bgl.			