

CRACK MONITORING

for Subsidence Management Services

**Woodstock, COTTESMORE ROAD, ASHWELL, Oakham, RUTLAND,
LEICESTERSHIRE, LE15 7LJ**

Client:	Subsidence Management Services
Client Contact:	Fyaz Jan
Claim Number:	346516/H/AV/HSA/2022
Client Reference:	IFS-PRE-SUB-22-0104778
Policy Holder:	Mrs Yvonne Olive Walters
Report Date:	27 October 2023
Our Ref:	M20509

Crack Monitoring Readings

The following table shows the reading levels of the Crack Monitoring Stations.

Date	A=B (H)	B=C (D)(C)	A=C (V)	Crack Width
C1 - INT- Top of stairs on front wall				
9 February 2023	101.30	127.27	83.19	0.30 - 0.40
18 April 2023	101.12	127.25	83.12	
13 June 2023	101.00	127.12	83.10	
17 August 2023	101.11	127.19	83.14	
26 October 2023	101.65	127.19	83.63	0.90 - 0.90

Crack Monitoring Difference Graphs

The following graphs display the progressive movement that each Crack Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.

