

Monitoring Details

Provider Name:	My Home Needs Ltd	Monitoring Interval:	8 Weekly
Instruction Date:	21/06/2023	Number of Visits:	7
Reading Date:	14/11/2023	Visits Completed:	2
Date of Issue:	15/11/2023	Visits Outstanding:	5


Client Details

Client:	Questgates	Engineer / Handler:	Andrea Varney
Job Reference:	QG1S1141035		


Monitored Address

Occupier:	
Address:	Silverton Lodge, 118 Church Road, London, SE19 2UE
Telephone:	0208 7690161

Site Plan




Level Readings (Displayed in metres)


Visits	2	3	4	5	6	7	8	 DATUM 1
18/08/2023	9.8462	10.1922	11.8560	12.4216	12.4349	12.2865	10.6732	10.0000
14/11/2023	9.8430	10.1882	11.8544	12.4205	12.4347	12.2865	10.6710	10.0000

DATUM 1: TBM on station 1, it has an assumed value of 10.0000m.

Level Readings Difference (Displayed in millimetres)

Visits	2	3	4	5	6	7	8	 DATUM 1
18/08/2023	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
14/11/2023	-3.20 ↓	-4.00 ↓	-1.60 ↓	-1.10 ↓	-0.20 ↓	0.00 =	-2.20 ↓	0.00 =

Relative Movement (Relative Survey, for illustration purposes only)




■ Baseline

■ Visit 1 (18/08/2023)

■ Visit 2 (14/11/2023)

Level Readings Chart



Homeowner Notes

Visit	Homeowner Notes
18/08/2023	No concerns raised.
14/11/2023	No concerns raised.