

Ref: 23207 – KIRLAND MANOR, BODMIN

## ADDITIONAL PHOTOGRAPHS

ON: KIRLAND MANOR, BODMIN, PL30 5AA

FOR: MS CAITLIN DEAN

DATE: SEPTEMBER 2023

PREPARED BY: A JOHNSON

CHECKED BY: J A TAYLOR B.Sc (Hons) Assoc RICS



Figure 1 - Photograph showing entrance to Kirland Manor.



Figure 2 - Photograph showing rotten floor joists to first floor landing.



Figure 3 - Photograph showing rotten floor joists to first floor landing.



Figure 4 - Photograph showing North elevation.



Figure 5 - Photograph showing existing pool.



Figure 6 - Photograph showing damp staining and plaster blistering.



Figure 7 - Photograph showing area of wall to be replastered.



Figure 8 – Photograph showing cracking on first floor landing.