



Image of Existing Storage Area

Existing Back of House Storage Yard to be Removed and Replaced with High-Quality Facilities. Existing Facilities are a Risk to Public Health and are in Very Poor Condition

Key Plan

- - Site Boundary
- - Land Under Ownership
- - Public Right of Way

IMPORTANT NOTICE

This Drawing remains at all times in the copyright of The Inspired Partnership Limited. This drawing shall not be altered or copied in whole or in part without their prior written consent.

THIS DRAWING HAS BEEN PREPARED FROM SITE SURVEY INFORMATION TAKEN BY OTHERS

Contractors must check ALL dimensions on site. Only figured dimensions are to be worked from.

Discrepancies must be reported immediately to the client before proceeding. Neither IPL nor the client accepts responsibility for works undertaken or materials purchased without accurate site assessment and specific measurement

- Survey
- SO: For discussion
- S1: Fit for coordination
- S2: Fit for information
- S3: Fit for internal review
- S4: Fit for construction approval
- D1: Fit for costing
- D2: Tender issue
- D3: Fit for contractor design
- D4: Fit for manufacture procurement
- A: Construction issue
- B: Partially signed-off
- AB: As built drawing

Date	Rev ID	Description
12/10/2023	P2	Planning Revision
11/07/2023	P1	Planning Issue

Client Approval

<input checked="" type="checkbox"/>	A - Approved
<input type="checkbox"/>	B - Approved with Comments
<input type="checkbox"/>	C - Do Not Use

Project:
Medmerry Park - Site Redevelopment



Drawn: JG Date: July'23
Sheet Size: A1 Scale: 1:500

Drawing: **BOH Existing Site Plan**

Drawing Subset:
Back of House Facilities
Drawing Status Purpose of Issue
S2 Information

Sheet Number: **427.01_2400.2** Rev: **P2**

N

Back of House Area - Existing Site Plan
1:500 @ A1