## **BEFORE CONSTRUCTION WORK**

PHOTO 1 - WEST ELEVATION



## PHOTO 2 - SOUTH & EAST ELEVATION



**DURING CONSTRUCTION WORK** - STRIPPING OUT, INCLUDING REMOVAL OF EXISTING CONCRETE SLAB / INTERNAL SOLID WALLS / REMOVAL OF BIOMASS BOILER AND ASSOCIATED PLANT

PHOTOS 3&4 - INTERNAL PHOTOS OF CONSTRUCTION





PHOTOS 5-8 - INTERNAL PHOTOS OF CRACKS THAT APPEARED









## PHOTOS 9 - START OF SALVAGE WORK

