



NOTES
 It is the contractors responsibility to check design levels and sizes for compliance. Any discrepancies or errors to be identified to the design team.
 Topographical Survey Undertaken to obtain existing levels and dimensions of the site.

REVISION	DETAILS	BY	DATE	CHECKED



 info@sportslabsconsult.com

ST GREGORY'S CATHOLIC ACADEMY
TOPOGRAPHICAL SURVEY
CONSTRUCTION OF A NEW 2G PITCH



Date: 10/2023 Scale: 1:250 @ A3	Job No. 3219	Drawn by: CH Checked by: DD
------------------------------------	--------------	--------------------------------