



**LEGEND**

- Existing shrubs
- Existing tree

Tree stem location and value category according to BS5837

- Tree survey ref. no
- Indicative tree stem location and categorisation
- Indicative crown spread
- Tree proposed for removal

Tree stem location and value category according to BS5837

- No Value
- Moderate Value
- Low Value
- High Value

