



## Ground to First Floor Existing Stairs



Stairs in both directions showing large painted timber cover strips on the strings to both sides



First Floor Bedroom 3 shows where an original staircase was located and now boarded over.



Underside of these stairs showing they are modern poor quality and poorly fitted in the space with large gaps to both sides.