



Around The World
TREE & LANDSCAPING
36A Ellesmere Court, Sunderland, SR2 9UA

Tree Preservation/Conservation Order Application

Date 08/01 January 2024

St Aidan's Catholic Academy

Willow Bank Road

Sunderland

SR2 7HJ

Description of works –

These works have been identified on the Tree Survey carried out by Amenity Tree with the works and TPO application carried out by ATW Tree and Landscaping Specialists LTD.

T157 – RED ARROW – Mature Sycamore tree - Main leader and scaffold branches appear to be dead, ivy-covered stem, unremarkable tree in falling distance of main road, remove to eliminate risk.

T159 – YELLOW ARROW – Swedish Whitebeam – Dryads saddle evident from cavity 5m up, main stem on east side, tree leans towards main road, fell to eliminate risk.

T172 – BLUE ARROW – Common Holly – Remove Holly tree on metal spiked fence, eventually cambium will rupture, not the best specimen, removing will provide the two adjacent Holly trees for more space.

T180 – PURPLE ARROW – Horse Chestnut – Young Horse Chestnut situated at wall overhanging footpath, heavy lean-to Southeast, poor specimen and recommended removal.

