

velux and rotted timber surrounding frame

Scale 10mm: 01m
Printed 1:2 scale

0.064m

→ ← crosshatch area to be replaced

