


velux and rotted timber surrounding frame




Scale 1:5

0.064m



crosshatch area to be replaced



0.33m

0.458m

