


Appendix I

Photograph taken on 9th August 2018 of the ground floor front (now the living room at 23B Cambridge Grove), showing that conversion works into a single dwellinghouse were underway by this date. The windows and glazed door are in situ to the front of the premises.



Photograph taken on 9th August 2018 of the ground floor middle (now the living room / dining room at 23B Cambridge Grove), showing that conversion works into a single dwellinghouse were underway by this date.



IMG_7926_7_8Interior01 Properties

General Security Details Previous Versions

Property	Value
Description	
Title	
Subject	
Rating	☆☆☆☆☆
Tags	
Comments	
Origin	
Authors	
Date taken	09/08/2018 16:20
Program name	
Date acquired	
Copyright	
Image	
Image ID	
Dimensions	3983 x 2655
Width	3983 pixels
Height	2655 pixels
Horizontal resolution	72 dpi
Vertical resolution	72 dpi

[Remove Properties and Personal Information](#)

OK Cancel Apply

Photograph taken on 9th August 2018 of the front elevation at 23B Cambridge Grove, showing the glazed door and windows in situ behind the open carriage doors.



IMG_7885_6_7Interior01 Properties

General Security Details Previous Versions

Property	Value
Description	
Title	
Subject	
Rating	☆☆☆☆☆
Tags	
Comments	
Origin	
Authors	
Date taken	09/08/2018 14:33
Program name	
Date acquired	
Copyright	
Image	
Image ID	
Dimensions	3977 x 2647
Width	3977 pixels
Height	2647 pixels
Horizontal resolution	72 dpi
Vertical resolution	72 dpi

[Remove Properties and Personal Information](#)

OK Cancel Apply