

1 Photo of Old Rear Access Gate

Replaced Rear Access Gate Material: tanalised timber with metal fixings, connected to timber posts to match the old gates. Top posts - tapered & chamfered

Existing Garden Wall Access Gate Existing Garden Stone Wall Existing Garden Stone Wall Existing Garden Stone Wall PLAN Description ELEVIATION 


3 Plan & Elevation Replaced Rear Gate 1:50



### 2 Photo of Replaced Rear Access Gate

#### © Lux et Umbra Architecture Ltd

Figured dimensions only are to be taken from this drawing. All dimensions are to be checked on site before any work is put in hand.





88 Brighton Road, Horsham West Sussex, RH13 5DE

07876 480079 carmina@luarchitecture.co.uk Client's name

## Mr. Roy Teo

### Job title

# The Thatched Cottage Erection of Gates and Fence

Drawing title

### Replaced Rear Access Gate

#### Scale

## **1:50** @ A3

Drawn	Checked	Date
CI	CI	25/01/2024
Job No	Drawing No	Rev
2303	200-104	00
Status		
Information		