



**BROWNFIELD  
SOLUTIONS LTD**

GEO-ENVIRONMENTAL ENGINEERING EXCELLENCE

## CARE DEVELOPMENTS (OSWESTRY) LTD

Guttercrest, Oswestry

Remediation Validation Report

PH/C4717/12804

February 2024

**PROJECT QUALITY CONTROL DATA SHEET**

<b>Site Name:</b>	Guttercrest, Oswestry		
<b>Document Name:</b>	Remediation Validation Report		
<b>Reference:</b>	PH/C4717/12804		
<b>Status:</b>	-	07/02/2024	Final.

<b>Issued By:</b>	<b>Client:</b>	<b>Engineer:</b>
Brownfield Solutions Ltd William Smith House 173 – 183 Witton Street Northwich Cheshire CW9 5LP  Tel: 01606 334 844 brownfield-solutions.com	Care Developments (Oswestry) Ltd Suite 10 2nd Floor Britannia House St Georges Street Douglas Isle of Man IM1 1JD	
	Contact: Mr D Entwistle	Contact:

Written by:



P Holland  
BSc (Hons)  
Project Engineer

Checked by:



N Swallow  
BSc (Hons) MSc MEnvSc  
Principal Project Engineer

Approved by:



D M Gates  
MGeoscience FGS  
Principal Project Engineer



**CONTENTS**

<b>1.0</b>	<b>INTRODUCTION .....</b>	<b>1</b>
1.1	CONTEXT .....	1
1.2	OBJECTIVES .....	1
1.3	PROPOSED DEVELOPMENT .....	1
1.4	PREVIOUS REPORTS AND CORRESPONDENCE .....	1
1.5	LIMITATIONS .....	1
<b>2.0</b>	<b>GROUND MODEL SUMMARY .....</b>	<b>3</b>
2.1	DESCRIPTION OF SITE .....	3
2.2	ENVIRONMENTAL SETTING .....	3
2.3	GROUND CONDITIONS .....	4
2.4	GROUNDWATER .....	4
2.5	EVIDENCE OF CONTAMINATION .....	5
<b>3.0</b>	<b>SUMMARY OF RISK ASSESSMENTS .....</b>	<b>6</b>
3.1	GENERAL .....	6
3.2	HUMAN HEALTH RISKS .....	6
3.3	GROUND GAS AND VAPOURS .....	6
3.4	RISKS TO CONTROLLED WATERS .....	6
3.5	SUMMARY .....	7
<b>4.0</b>	<b>REMEDIATION STRATEGY .....</b>	<b>8</b>
4.1	OUTLINE .....	8
4.2	SITE REMEDIATION REQUIREMENTS .....	8
<b>5.0</b>	<b>SITE REMEDIATION AND VALIDATION .....</b>	<b>9</b>
5.1	GENERAL .....	9
5.2	SOURCE 1: HYDROCARBON POINT SOURCES .....	9
5.3	SOURCE 2: INSTALLATION OF CLEAN COVER SYSTEM / BREAK LAYER .....	10
<b>6.0</b>	<b>CONCLUSIONS .....</b>	<b>13</b>
6.1	GENERAL .....	13
6.2	HYDROCARBON POINT SOURCE EXCAVATIONS .....	13
6.3	VERIFICATION OF CLEAN COVER SYSTEM .....	13
6.4	WATCHING BRIEF .....	13
6.5	LONG TERM MONITORING AND OTHER REQUIREMENTS .....	13

**DRAWINGS**

Drawing Number	Re	Title
10122020	-	Sketch Site Layout Plan
C4717/01	-	Site Location Plan
C4717/02	-	Pertinent Site Features Plan
C4717/03	-	Exploratory Hole Location Plan
C4717/04	-	UST Removal Records
C4717/05	B	Validation Pit Location Plan

**APPENDICES**

Appendix	Title
Appendix A	Chemical Testing Results
Appendix B	PID Calibration Certificates
Appendix C	Waste Transfer Notes

---

Appendix D	Photographic Volume – Recorded Tank Excavation
Appendix E	Photographic Volume – Clean Cover System Validation