

**Photographs of Gable Wall  
for Listed Building Consent**

Old Hall, Finningham Road, Walsham-le-Willows, IP31 3BN



Photo 1: External view



Photo 2: Internal view of cracking. Wall leans inwards above the horizontal crack.



Photo 3: External view of where garage roof is keyed into the gable wall