

PHOTOGRAPHIC SCHEDULE



Fig.1 North East External Elevation



Fig.2 South East External Elevation.



Fig.3 Existing 3-Light window to South East Elevation. Replacement window proposed to match existing.



Fig.4 Part North East External Elevation.



Fig.5 Part North East External Elevation.



Fig.6 Existing 2-Light window to North East Elevation. Replacement window proposed to match existing.



Fig.7 North East External Elevation of Existing Porch. Replacement doors proposed to match existing style. .



Fig.8 Existing Rooflight to be replaced with patent glazing system to match style of existing with lead covers to hips.



Fig.9 North East Internal Elevation. Replacement window proposed to match existing.



Fig.10 Replacement window proposed to match existing on North East Elevation.



Fig.11 South West Internal Elevation.



Fig.12 North East Internal Elevation.



Fig.13 South East Internal Elevation. Replacement window proposed to match existing.



Fig.14 Replacement window proposed to match existing on South East Elevation.



Fig.15 Existing roof structure. Insulation to be installed between rafters and lined with plasterboard and skim. Lantern to be replaced.



Fig.16 Existing roof Lantern to be replaced.



Fig.17 Internal View of Porch. Door to be replaced to match existing.



Fig.18 Internal View of Porch roof structure. Insulation to be installed between rafters and lined with plasterboard and skim