

**50 SYCAMORE AVENUE, SIDCUP, DA15 8PL**

**DESK STUDY REPORT**

**Reference: 1586/DS**

**3<sup>rd</sup> February 2023**

**CLIENT:**

**12 Burewelle  
Milton Keynes  
MK8 8LS**

**SITE: 50 Sycamore Avenue  
Sidcup  
London  
DA15 8PL**

**DESK STUDY REPORT**

**Reference: 1586/DS**

**3<sup>rd</sup> February 2023**

Prepared By:

Peter Baxter Associates Ltd  
Kestner Works  
Bredgar Road  
Gillingham, Kent  
ME8 6PL

Tel: 01634 717974

[www.peterbaxterassociates.co.uk](http://www.peterbaxterassociates.co.uk)

---

## CONTENTS

### FOREWORD

<b>1.0</b>	<b>SUMMARY</b>	<b>1</b>
<b>2.0</b>	<b>SITE DESCRIPTION</b>	<b>2</b>
2.1	Site Location and Description	2
2.2	Proposed Development	2
2.3	Published Geology	2
2.4	Geological Hazards and Radon	2
2.5	Historic Usage of Site and Surrounding Area	2
<b>3.0</b>	<b>ENVIRONMENTAL SETTING</b>	<b>4</b>
3.1	Sensitive Land Usage	4
3.2	Discharge Consents and Pollution Incidents	4
3.3	Mining and Mineral Extraction	4
3.4	Hydrogeology and Flooding	4
3.5	Landfilling and Waste	4
3.6	Trade Directory Entries and Fuel	4
<b>4.0</b>	<b>SITE WALK OVER SURVEY</b>	<b>5</b>
4.1	Observations	5
<b>5.0</b>	<b>CONTAMINATION RISK ASSESSMENTS</b>	<b>6</b>
5.1	Preliminary Environmental Risk Assessment, Human Health and Controlled Waters	6
<b>6.0</b>	<b>CONCLUSIONS AND RECOMMENDATIONS</b>	<b>7</b>

### REFERENCES

- Reference 1            Envirocheck Report, 305648156\_1\_1 10<sup>th</sup> January 2023
- Reference 2            Land Contamination Risk Management, Environment Agency 2021

**FIGURES**

1586/Figure 1	Plan of Site
1586/Figure 2	Illustration of Conceptual Model

**TABLE**

Table 1	Conceptual Model and Preliminary Risk Assessment
---------	--

**APPENDICES**

**Appendix A                    EXISTING DATA**

Appendix A1	Geological Maps
Appendix A2	Selected Historical Maps
Appendix A3	Site Sensitivity Maps
Appendix A4	Datasheet

**Appendix B                    PHOTOGRAPHS**

## FOREWORD

1. This document has been prepared by Peter Baxter Associates Ltd with all reasonable skill, care and diligence within the terms of the contract with the Client and within the limitations of the resources devoted to it by agreement with the client.
2. This document is confidential to the Client and Peter Baxter Associates Ltd accepts no responsibility whatsoever to third parties to whom this document, or any part thereof, is made known. Any such party relies upon the document at their own risk.
3. This document shall not be used unless the document status is 'Final', and Peter Baxter Associates Ltd's fees have been settled in full.
4. Unless specifically assigned or transferred within the terms of the agreement, the consultant asserts and retains all Copyright, and other intellectual Property Rights in and over the Report and its contents.

## 1.0 SUMMARY

- 1.1 The Clients, plan to construct two new houses on a 700m<sup>2</sup> plot situated at 50 Sycamore Avenue, Sidcup, DA15 8PL. The Site is in a suburban residential area on the outskirts of London and is occupied by a prefabricated building which was a charity advice centre. The Site is shown on Figure 1 and photographs in Appendix B.
- 1.2 Peter Baxter Associates (PBA) were commissioned by the Client to carry out an Environmental Desk Study. The objectives of the Phase 1 Desk Study were to identify the extent, scale, and nature of any contamination at the site from previous land use, and to carry out a Preliminary Risk Assessment of the associated risks to site occupants, controlled waters and other receptors from both on-site and off-site contamination sources. The information on which this Desk Study was based was sourced from Envirocheck (Reference 1) and from a site walkover survey. Information from Reference 1 is presented in this Report as Appendices.
- 1.3 The report presents the Site's geology, history, and environmental setting, describes the observations of a Site walk over survey, and discusses potential contaminant sources, pathways and receptors and the assessed environmental risks associated with the Site.
- 1.4 The Site geology is London Clay, and the Site is situated over unproductive aquifer strata.
- 1.5 The Site was undeveloped until 1988 when the current building was first shown. The surrounding properties date from the 1930s. Surrounding land use was identified as residential, with shops along the nearby Blackfen Road. No contamination was observed during a site walkover.
- 1.6 From the observations of the Site walkover and a review of historic data and adjacent land use, a preliminary risk assessment, presented as Table 1, was carried out in accordance with planning guidance document Land Contamination Risk Management (Reference 2).
- 1.7 The preliminary risk assessment concluded that the environmental risk to Site Occupants and other onsite receptors from onsite contaminated soil was low. The risk to offsite receptors from onsite sources was considered low. The environmental risk to onsite receptors from offsite sources was assessed as low.
- 1.8 No further investigation is considered necessary.
- 1.9 Undetected contamination may be present which would affect this conclusion.

## **2.0 SITE DESCRIPTION**

### **2.1 Site Location and Description**

2.1.1 The Site is a triangular plot of land, 700m<sup>2</sup> in area, situated at 50 Sycamore Avenue, Sidcup DA15 8PL. It is accessed via an alley off Sycamore Avenue. The Site's National Grid Coordinates are 546060E, 174490N, and the Site is in the district of Blackfen, approximately 200m south of the A2 and 2km north of Sidcup railway station, on the south east fringe of London.

2.1.2 The site contains a single story prefabricated building, which has been boarded up, a paved car park, and a number of mature trees. The Site is bounded on two sides by residential housing and to the north by a paved vehicle access, which also serves properties on Blacken Road. The Site is flat and secured by low fences. Blacken is a suburban district of low rise housing dating mainly from the interwar period.

2.1.3 The Client stated that the building was most recently used as a charity advice centre.

2.1.4 The Site is shown on Figure 1 and is illustrated in photographs in Appendix B.

### **2.2 Proposed Development**

2.2.1 It is planned to build two houses on the Site. The local planning authority is the London Borough of Bexley.

### **2.3 Published Geology**

2.3.1 Reference 1 indicated that the Site geology was London Clay. Made ground was shown approximately 100m from the Site. No geological faults were shown within 1000m. Geological maps are included in Appendix A1.

### **2.4 Geological Hazards and Radon**

2.4.1 Reference 1 indicated no hazards from compressible ground, ground dissolution, and running sand, a very low risk from landslide and collapsible ground, and a moderate risk of shrinking or swelling clay.

2.4.2 The Site was in a low probability radon area with a probability of less than 1% of properties being above the Action Level. No protection is required against radon.

### **2.5 Historic Usage of Site and Surrounding Area**

2.5.1 The past uses of the Site and surrounding areas were established from historic maps (Reference 1).

- 2.5.2 The Site was shown as undeveloped on an 1870 map. The surrounding properties were first shown on a 1936 map. The Site was shown undeveloped until 1988, when a structure on site corresponding to the current building was shown. A garage on Blacken Road was shown from 1956 to 1991, about 130m north west of the Site, which is now a car dealership. Historic maps are included in Appendix A2. No historic industries or quarries were shown on or near the Site.
- 2.5.3 No adjacent sources of offsite environmental risk were identified from the historic maps.



### **3.0 ENVIRONMENTAL SETTING**

#### **3.1 Sensitive Land Usage**

3.1.1 Reference 1 indicated no sensitive land use areas within 1000m of the Site.

#### **3.2 Discharge Consents and Pollution Incidents**

3.2.1 No discharge consents were listed within 1000m of the Site, Thirty seven pollution incidents were shown within 1000m of the Site, the nearest being a minor incident 69m south. The nearest “significant” incident was 627m south west.

#### **3.3 Mining and Mineral Extraction**

3.3.1 Reference 1 showed that there were no man-made or natural cavities within 1000m of the Site.

3.3.2 No mineral sites were shown within 1000m.

#### **3.4 Hydrogeology and Flooding**

3.4.1 Reference 1 indicated that the Site was underlain by unproductive strata. No water abstractions were shown within 1000m.

3.4.2 The nearest surface water feature was 450m south west of the Site. (Appendix A4).

3.4.3 The site had no potential for groundwater flooding at surface and no risk of flooding from rivers and seas without defences (Appendix A3).

#### **3.5 Landfilling and Waste**

3.5.1 There were no historic landfill sites recorded within 1000m of the Site.

#### **3.6 Trade Directory Entries and Fuel**

3.6.1 There were 137 contemporary trade entries listed within 1000m of the Site with 11 registered as active within 500m. The closest was a window workshop 21m north. A funeral directors was noted opposite the Site.

3.6.2 There was one fuel station listed within 1000m of the Site, an inactive site 137m north west.

## **4.0 SITE WALK OVER SURVEY**

### **4.1 Observations**

- 4.1.1 The Site was visited in the afternoon of 9<sup>th</sup> January 2023 by a PBA geologist. The weather was dry and cold. The Site could not be entered due to a faulty padlock, but was viewed and photographed over the perimeter fence.
- 4.1.2 The Site contained a single storey prefabricated building of estimated 60m<sup>2</sup> area which had been boarded up. The south east boundary of the Site was lined by a hedge of mature conifers.
- 4.1.3 The Site was secure from pedestrian and vehicle access, with a 1.8m high fence along the alleyway to the north. No fly tipping, debris or stains were observed on site, although some litter was observed.
- 4.1.4 The Site is shown on Figure 1 and in photographs in Appendix B.

## **5.0 CONTAMINATION RISK ASSESSMENTS**

### **5.1 Preliminary Environmental Risk Assessment, Human Health and Controlled Waters**

5.1.1 A preliminary environmental risk assessment was carried out in accordance with Reference 2. A conceptual model was developed from available information sources, listing source, pathway, and receptor. The risk assessment is given as Table 1 and the conceptual model illustrated as Figure 2.

5.1.2 The preliminary risk assessment from this conceptual model concluded that the risk to Site Occupants and other on-site receptors from onsite sources via airborne dust, ingestion, vegetable uptake, and dermal contact, were low. The history of the Site did not indicate any industrial use. No signs of contamination were observed during the Site walkover.

5.1.3 The preliminary risk assessment from this conceptual model concluded that the risk to controlled waters and other off-site receptors from onsite sources via migrating gases and vapours, infiltration, dust and run off were low. The Site overlay unproductive strata and no signs of contamination were observed during the Site walkover.

5.1.4 The preliminary risk assessment from this conceptual model concluded that the risk to Site Occupants and other on-site receptors from offsite sources via migrating gases and vapours were low. No sources of offsite environmental risk were identified, and the Site's soils were shown as low permeability London Clay.


## **6.0 CONCLUSIONS AND RECOMMENDATIONS**

- 6.1 A review of desk study data of the Site was undertaken, and the Site was visited for a Site walkover. A preliminary risk assessment, presented in Table 1, concluded that the environmental risk to Site Occupants and other onsite receptors from onsite contaminated soil was low.
- 6.2 The risks to offsite receptors were considered low as contamination levels were likely to be low and the Site was located over unproductive strata.
- 6.3 The environmental risk to onsite receptors from offsite sources was assessed as low. No sources were identified near the Site.
- 6.4 No further environmental investigation is considered necessary.
- 6.5 If undetected contamination is present, these conclusions may be affected.


**P Baxter BEng CEng MICE (Director)**

**For and on behalf of Peter Baxter Associates Ltd**

## FIGURES



**Notes**  
 1. Based on BaARC Ltd DRW-SIT-3N PLNRVB



Peter Baxter Associates Ltd Kestner Works Bredgar Road Gillingham Kent. Tel. +44 (0)1634 717974

Client


Project  
 50 Sycamore Avenue Sidcup

Title  
 Plan of Site

Rev.	Date	Drn.	App.	Revision

Drawn	PB	Checked	PB
Size	A3	Scale	N.T.S.
Status	Information		

Drawing No. **1586/Figure 1** Rev. **A**



				Client	Azadakki Khamani & Zabin Tejani	Drawn	PB	Checked	PB
				Project	50 Sycamore Avenue, Sidcup DA15 8PL	Size	A4	Scale	N.T.S.
			A	Information		Drawing No.	<b>1586/Figure 2</b>		Rev.
				Information					<b>A</b>
Rev.	Date	Dm.	App.	Revision	Illustration of Conceptual Model	Peter Baxter Associates Ltd, Kestner Works, Bredgar Road, Gillingham, Kent ME8 6PL, Tell 01634 717974			



**TABLE**





## APPENDICES

**APPENDIX A4**  
**Data Sheet**

## Envirocheck<sup>®</sup> Report:

### Datasheet

#### Order Details:

**Order Number:**

305648156\_1\_1

**Customer Reference:**

1586

**National Grid Reference:**

546060, 174490

**Slice:**

A

**Site Area (Ha):**

0.07

**Search Buffer (m):**

1000

#### Site Details:

50, Sycamore Avenue

SIDCUP

DA15 8PL

#### Client Details:

Mr P Baxter

Peter Baxter Associates Ltd

Kestner Works

Bredgar Road

Gillingham

Kent

ME8 6PL

#### Prepared For:

Report Section	Page Number
Summary	-
Agency & Hydrological	1
Waste	13
Hazardous Substances	-
Geological	14
Industrial Land Use	15
Sensitive Land Use	-
Data Currency	25
Data Suppliers	31
Useful Contacts	32

### Introduction

The Environment Act 1995 has made site sensitivity a key issue, as the legislation pays as much attention to the pathways by which contamination could spread, and to the vulnerable targets of contamination, as it does the potential sources of contamination. For this reason, Landmark's Site Sensitivity maps and Datasheet(s) place great emphasis on statutory data provided by the Environment Agency/Natural Resources Wales and the Scottish Environment Protection Agency; it also incorporates data from Natural England (and the Scottish and Welsh equivalents) and Local Authorities; and highlights hydrogeological features required by environmental and geotechnical consultants. It does not include any information concerning past uses of land. The datasheet is produced by querying the Landmark database to a distance defined by the client from a site boundary provided by the client. In this datasheet the National Grid References (NGRs) are rounded to the nearest 10m in accordance with Landmark's agreements with a number of Data Suppliers.

### Copyright Notice

© Landmark Information Group Limited 2023. The Copyright on the information and data and its format as contained in this Envirocheck® Report ("Report") is the property of Landmark Information Group Limited ("Landmark") and several other Data Providers, including (but not limited to) Ordnance Survey, British Geological Survey, the Environment Agency/Natural Resources Wales and Natural England, and must not be reproduced in whole or in part by photocopying or any other method. The Report is supplied under Landmark's Terms and Conditions accepted by the Customer. A copy of Landmark's Terms and Conditions can be found with the Index Map for this report. Additional copies of the Report may be obtained from Landmark, subject to Landmark's charges in force from time to time. The Copyright, design rights and any other intellectual rights shall remain the exclusive property of Landmark and /or other Data providers, whose Copyright material has been included in this Report. © Environment Agency & United Kingdom Research and Innovation 2023. © Natural Resources Wales & United Kingdom Research and Innovation 2023.

### Natural England Copyright Notice

Site of Special Scientific Interest, National Nature Reserve, Ramsar, Special Protection Area, Special Conservation Area, Marine Nature Reserve data (derived from Ordnance Survey 1:10000 raster) is provided by, and used with the permission of, Natural England who retain the copyright and Intellectual Property Rights for the data.

### Scottish Natural Heritage Copyright

Contains SNH information licensed under the Open Government Licence v3.0.

### Ove Arup Copyright Notice

The Mining Instability data was obtained on licence from Ove Arup & Partners Limited (for further information, contact mining.review@arup.com). No reproduction or further use of such Data is to be made without the prior written consent of Ove Arup & Partners Limited. The supplied Mining Instability data is derived from publicly available records and other third party sources and neither Ove Arup & Partners nor Landmark warrant the accuracy or completeness of such information or data.

### Stantec Copyright Notice

The cavity data presented has been extracted from the PBA (now Stantec UK Ltd) enhanced version of the original DEFRA national cavity databases. Stantec UK Ltd retain the copyright & intellectual property rights in the data. Whilst all reasonable efforts are made to check that the information contained in the cavity databases is accurate we do not warrant that the data is complete or error free. The information is based upon our own researches and those collated from a number of external sources and is continually being augmented and updated by Stantec UK Ltd. In no event shall Stantec UK Ltd or Landmark be liable for any loss or damage including, without limitation, indirect or consequential loss or damage arising from the use of this data.

### Radon Potential dataset Copyright Notice

Information supplied from a joint dataset compiled by The British Geological Survey and Public Health England.

### Natural Resources Wales Copyright Notice

Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right. Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Some features of this information are based on digital spatial data licensed from the Centre for Ecology & Hydrology © NERC (CEH). Defra, Met Office and DARD Rivers Agency © Crown copyright. © Cranfield University. © James Hutton Institute. Contains OS data © Crown copyright and database right 2023. Land & Property Services © Crown copyright and database right.

### Report Version v53.0

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
<b>Agency &amp; Hydrological</b>					
BGS Groundwater Flooding Susceptibility	pg 1		Yes	Yes	n/a
Contaminated Land Register Entries and Notices					
Discharge Consents					
Prosecutions Relating to Controlled Waters			n/a	n/a	n/a
Enforcement and Prohibition Notices					
Integrated Pollution Controls					
Integrated Pollution Prevention And Control					
Local Authority Integrated Pollution Prevention And Control					
Local Authority Pollution Prevention and Controls	pg 1		3		1
Local Authority Pollution Prevention and Control Enforcements					
Nearest Surface Water Feature	pg 2			Yes	
Pollution Incidents to Controlled Waters	pg 2		2	1	31
Prosecutions Relating to Authorised Processes					
Registered Radioactive Substances					
River Quality	pg 8				1
River Quality Biology Sampling Points					
River Quality Chemistry Sampling Points					
Substantiated Pollution Incident Register	pg 8				3
Water Abstractions	pg 8				(*6)
Water Industry Act Referrals					
Groundwater Vulnerability Map	pg 10	Yes	n/a	n/a	n/a
Groundwater Vulnerability - Soluble Rock Risk			n/a	n/a	n/a
Bedrock Aquifer Designations	pg 10	Yes	n/a	n/a	n/a
Superficial Aquifer Designations			n/a	n/a	n/a
Source Protection Zones	pg 10	1		1	
Extreme Flooding from Rivers or Sea without Defences				n/a	n/a
Flooding from Rivers or Sea without Defences				n/a	n/a
Areas Benefiting from Flood Defences				n/a	n/a
Flood Water Storage Areas				n/a	n/a
Flood Defences				n/a	n/a
OS Water Network Lines	pg 10			1	18

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
<b>Waste</b>					
BGS Recorded Landfill Sites					
Historical Landfill Sites					
Integrated Pollution Control Registered Waste Sites					
Licensed Waste Management Facilities (Landfill Boundaries)					
Licensed Waste Management Facilities (Locations)					
Local Authority Landfill Coverage	pg 13	1	n/a	n/a	n/a
Local Authority Recorded Landfill Sites					
Registered Landfill Sites					
Registered Waste Transfer Sites					
Registered Waste Treatment or Disposal Sites					
<b>Hazardous Substances</b>					
Control of Major Accident Hazards Sites (COMAH)					
Explosive Sites					
Notification of Installations Handling Hazardous Substances (NIHHS)					
Planning Hazardous Substance Consents					
Planning Hazardous Substance Enforcements					
<b>Geological</b>					
BGS 1:625,000 Solid Geology	pg 14	Yes	n/a	n/a	n/a
BGS Recorded Mineral Sites					
CBSCB Compensation District			n/a	n/a	n/a
Coal Mining Affected Areas			n/a	n/a	n/a
Mining Instability			n/a	n/a	n/a
Man-Made Mining Cavities					
Natural Cavities					
Non Coal Mining Areas of Great Britain	pg 14	Yes		n/a	n/a
Potential for Collapsible Ground Stability Hazards	pg 14	Yes		n/a	n/a
Potential for Compressible Ground Stability Hazards	pg 14		Yes	n/a	n/a
Potential for Ground Dissolution Stability Hazards				n/a	n/a
Potential for Landslide Ground Stability Hazards	pg 14	Yes		n/a	n/a
Potential for Running Sand Ground Stability Hazards	pg 14		Yes	n/a	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards	pg 14	Yes		n/a	n/a
Radon Potential - Radon Affected Areas			n/a	n/a	n/a
Radon Potential - Radon Protection Measures			n/a	n/a	n/a

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
<b>Industrial Land Use</b>					
Contemporary Trade Directory Entries	pg 15		34	24	53
Fuel Station Entries	pg 24		1		
Gas Pipelines					
Underground Electrical Cables	pg 24		1		
<b>Sensitive Land Use</b>					
Ancient Woodland					
Areas of Adopted Green Belt					
Areas of Unadopted Green Belt					
Areas of Outstanding Natural Beauty					
Environmentally Sensitive Areas					
Forest Parks					
Local Nature Reserves					
Marine Nature Reserves					
National Nature Reserves					
National Parks					
Nitrate Sensitive Areas					
Nitrate Vulnerable Zones					
Ramsar Sites					
Sites of Special Scientific Interest					
Special Areas of Conservation					
Special Protection Areas					
World Heritage Sites					



Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13NW (W)	87	1	545950 174486
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13SW (SW)	193	1	545900 174350
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (NE)	202	1	546200 174650
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13SE (S)	240	1	546150 174250
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (NE)	245	1	546300 174600
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	263	1	545850 174300
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13NE (NE)	272	1	546300 174650
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	278	1	545800 174350
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (E)	290	1	546350 174600
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13SW (W)	291	1	545750 174450
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	298	1	545850 174250
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (S)	324	1	546000 174150
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A14NW (E)	372	1	546450 174550
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Limited Potential for Groundwater Flooding to Occur	A14NW (E)	384	1	546450 174600
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A8NW (S)	399	1	545900 174100
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A8NW (S)	419	1	546050 174050
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A8NW (S)	469	1	546059 174000
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A8NE (S)	472	1	546100 174000
	<b>BGS Groundwater Flooding Susceptibility</b> Flooding Type: Limited Potential for Groundwater Flooding to Occur	A8NE (S)	492	1	546200 174000
1	<b>Local Authority Pollution Prevention and Controls</b> Name: Reds Dry Cleaners Location: 233 Blackfen Road, Sidcup, Da15 8pr Authority: London Borough of Bexley, Environmental Health Department Permit Reference: PP/07/31.0 Dated: 31st October 2007 Process Type: Local Authority Pollution Prevention and Control Description: PG6/46 Dry cleaning Status: <b>Permitted</b> Positional Accuracy: Manually positioned to the address or location	A13NE (N)	66	2	546068 174557

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
2	<p><b>Local Authority Pollution Prevention and Controls</b></p> <p>Name: Shell Woodman            Location: Westwood Lane, SIDCUP, Kent, DA15 9PT            Authority: London Borough of Bexley, Environmental Health Department            Permit Reference: PP/98/16.0            Dated: 17th January 1998            Process Type: Local Authority Pollution Prevention and Control            Description: PG1/14 Petrol filling station  <b>Status: Authorisation revoked</b>            Positional Accuracy: Manually positioned to the address or location</p>	A13NE (NE)	159	2	546218 174571
3	<p><b>Local Authority Pollution Prevention and Controls</b></p> <p>Name: Blackfen Express Cleaners            Location: 11 Wellington Parade, Blackfen Road, Sidcup, Da15 9nb            Authority: London Borough of Bexley, Environmental Health Department            Permit Reference: PP/07/30.0            Dated: 31st October 2007            Process Type: Local Authority Pollution Prevention and Control            Description: PG6/46 Dry cleaning  <b>Status: Permitted</b>            Positional Accuracy: Manually positioned to the address or location</p>	A13NE (E)	225	2	546308 174509
4	<p><b>Local Authority Pollution Prevention and Controls</b></p> <p>Name: The Oval Dry Cleaners            Location: 1 The Oval, Sidcup, Da15 9er            Authority: London Borough of Bexley, Environmental Health Department            Permit Reference: PP/07/34.0            Dated: 31st October 2007            Process Type: Local Authority Pollution Prevention and Control            Description: PG6/46 Dry cleaning  <b>Status: Permitted</b>            Positional Accuracy: Manually positioned to the address or location</p>	A8SE (S)	675	2	546168 173805
	<b>Nearest Surface Water Feature</b>	A12SE (SW)	450	-	545720 174165
5	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Fish Farms            Location: Days Lane, BEXLEY            Authority: Environment Agency, Southern Region            Pollutant: Miscellaneous - Inert Suspended Solids            Note: Yellow Colour Of River Shuttle            Incident Date: 14th September 1998            Incident Reference: 197306            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Deliberate Disposal To Drain            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A13SW (S)	69	3	546050 174400
6	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Petrol/Fuelling Stations            Location: Blendon Garage, Blackfen Road, SIDCUP            Authority: Environment Agency, Southern Region            Pollutant: Oils - Petrol            Note: Petrol Spill; Garage Forecourt            Incident Date: 20th October 1997            Incident Reference: 397442            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Not Given            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A13SE (S)	192	3	546120 174290
7	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Engineering            Location: Rear Of 3.3A Blackfen Road, BLACKFEN            Authority: Environment Agency, Southern Region            Pollutant: Oils - Waste Oil            Note: Oil Drums Leaking Down Drains            Incident Date: 9th November 1998            Incident Reference: 198356            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Poor Operational Practice            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A14NW (E)	416	3	546500 174500

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
8	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Not Given            Location: BLACKFEN            Authority: Environment Agency, Southern Region            Pollutant: Oils - Waste Oil            Note: Oil On Stream At Berwick Crescent            Incident Date: 27th January 1993            Incident Reference: 92T540            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Oils/Related Products            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	616	3	545600 174050
8	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Miscellaneous Premises: Unknown            Location: Days Lane, Berwick Crescent, SIDCUP            Authority: Environment Agency, Southern Region            Pollutant: Oils - Waste Oil            Note: Oil On River Shuttle            Incident Date: 18th February 1997            Incident Reference: 397044            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Oils/Related Products            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	618	3	545650 174000
8	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Water Company Sewage: Other            Location: Days Lane, SIDCUP            Authority: Environment Agency, Southern Region            Pollutant: Chemicals - Detergents/Surfactant            Note: Detergent In River Shuttle; Water Company Sewage: Foul Sewer            Incident Date: 19th May 1995            Incident Reference: 395092            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Industrial Chemicals            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	651	3	545600 174000
8	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Water Company Sewage: Other            Location: Rear Of Berwick Crescent            Authority: Environment Agency, Southern Region            Pollutant: Oils - Tars/Bitumen            Note: Oil On River Shuttle; Water Company Sewage: Surface Water Outfall            Incident Date: 11th July 1995            Incident Reference: 395218            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Oils/Related Products            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	655	3	545600 173995
9	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Miscellaneous Premises: Unknown            Location: Berrwick Crescent            Authority: Environment Agency, Southern Region            Pollutant: Oils - Waste Oil            Note: Oil On Shuttle            Incident Date: 19th February 1997            Incident Reference: 397046            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Oils/Related Products            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	622	3	545650 173995
10	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Water Company Sewage: Other            Location: Days Lane, SIDCUP            Authority: Environment Agency, Southern Region            Pollutant: Sewage Debris/Litter            Note: Sewage In River Shuttle            Incident Date: 20th September 1997            Incident Reference: 197030            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Not Given            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	627	3	545700 173950

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
10	<b>Pollution Incidents to Controlled Waters</b> Property Type: WSC Sewage, Sewerage & Supply Location: Fen Grove, SIDCUP Authority: Environment Agency, Southern Region Pollutant: Contaminated Water : Other Note: Not Supplied Incident Date: 2nd August 1999 Incident Reference: 2515 Catchment Area: Darent Receiving Water: Potential River Cause of Incident: Structural Failure : Pipe Failure (Below Ground) Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 10m	A7NE (SW)	629	3	545705 173945
11	<b>Pollution Incidents to Controlled Waters</b> Property Type: WSC Sewage, Sewerage & Supply Location: Fen Grove, SIDCUP Authority: Environment Agency, Southern Region Pollutant: Contaminated Water : Other Note: Not Supplied Incident Date: 2nd August 1999 Incident Reference: 2477 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Structural Failure : Pipe Failure (Below Ground) Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 10m	A7NE (SW)	631	3	545700 173945
11	<b>Pollution Incidents to Controlled Waters</b> Property Type: Miscellaneous Premises: Other Location: Days Lane , SIDCUP Authority: Environment Agency, Southern Region Pollutant: Miscellaneous - Unknown Note: Soapy/Cement Substance In River Shuttle Incident Date: 16th September 1997 Incident Reference: 397397 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Not Given Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A7NE (SW)	674	3	545700 173895
12	<b>Pollution Incidents to Controlled Waters</b> Property Type: Private Sewage (Non-PLC): Surface Water Outfall Location: Shuttle At, Willersley Avenue Authority: Environment Agency, Southern Region Pollutant: Oils - Diesel (Including Agricultural) Note: Petrol In River Incident Date: 13th August 1996 Incident Reference: 396372 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Private Surface Water Overflow Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A7NE (SW)	669	3	545700 173900
12	<b>Pollution Incidents to Controlled Waters</b> Property Type: Not Given Location: Days Lane, Berwick Crescent Authority: Environment Agency, Southern Region Pollutant: Oils - Diesel (Including Agricultural) Note: Oil On River Shuttle At Above Address Incident Date: 3rd November 1993 Incident Reference: 93T255 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Oils/Related Products Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A7NE (SW)	681	3	545650 173920
12	<b>Pollution Incidents to Controlled Waters</b> Property Type: Other General Premises Location: Culvert, Days Lane, SIDCUP Authority: Environment Agency, Southern Region Pollutant: Crude Sewage Note: Smell Of Sewage In River Shuttle; Miscellaneous Premises: Unknown Incident Date: 1st October 1994 Incident Reference: 94T317 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Sewage - Other Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A7NE (SW)	697	3	545650 173900

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
12	<b>Pollution Incidents to Controlled Waters</b> Property Type: Water Company Sewage: Other Location: Days Lane Authority: Environment Agency, Southern Region Pollutant: Crude Sewage Note: Sewage In Stream; Water Company Sewage: Foul Sewer Incident Date: 24th September 1994 Incident Reference: 94T349 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Plc Sewage Other Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A7NE (SW)	701	3	545650 173895
12	<b>Pollution Incidents to Controlled Waters</b> Property Type: Road (Road Traffic Accident) Location: Days Lane, SIDCUP Authority: Environment Agency, Southern Region Pollutant: Miscellaneous - Urban Runoff Note: Sewage Entering River Shuttle Incident Date: 23rd January 1996 Incident Reference: 396037 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Road Traffic Accident Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A7NE (SW)	727	3	545600 173900
13	<b>Pollution Incidents to Controlled Waters</b> Property Type: WSC Sewage, Sewerage & Supply Location: HOLLY OAK PARK Authority: Environment Agency, Southern Region Pollutant: Organic Chemicals : Mixed / Unidentified / Waste Mineral & Synthetic Oils Note: Not Supplied Incident Date: 19th August 1999 Incident Reference: 2993 Catchment Area: Not Supplied Receiving Water: Not Supplied Cause of Incident: Other Cause Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 10m	A8SW (S)	715	3	545800 173800
13	<b>Pollution Incidents to Controlled Waters</b> Property Type: Not Given Location: Wyncham Stream Authority: Environment Agency, Southern Region Pollutant: Miscellaneous - Unknown Note: River Level Raised And Discoloured Incident Date: 2nd November 1993 Incident Reference: 93T254 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Miscellaneous/Other Pollution Type Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SW (S)	762	3	545800 173750
14	<b>Pollution Incidents to Controlled Waters</b> Property Type: WSC Sewage, Sewerage & Supply Location: Crossroad Of Willersley Ave &, Hadon Grove, SIDCUP Authority: Environment Agency, Southern Region Pollutant: General Biodegradable : Crude Sewage & Sewerage Material Note: Not Supplied Incident Date: 2nd September 1999 Incident Reference: 3275 Catchment Area: Darent Receiving Water: Potential River Cause of Incident: Drainage Failures : Surface Water Sewer Failure Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 10m	A8SW (S)	719	3	546050 173750
15	<b>Pollution Incidents to Controlled Waters</b> Property Type: Domestic/Residential Location: Days Lane/Berwick Crescent, SIDCUP Authority: Environment Agency, Southern Region Pollutant: Oils - Kerosene Fuel Oil Note: Oil Breaking Away From Previously Installed Boom Incident Date: 10th February 1993 Incident Reference: 92T515 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Oils/Related Products Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A7NE (SW)	724	3	545500 174000

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
15	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Road (Road Traffic Accident)            Location: Berwick Crescent            Authority: Environment Agency, Southern Region            Pollutant: Oils - Other Oil            Note: Oil In River Shuttle            Incident Date: 16th October 1997            Incident Reference: 197007            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Not Given            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	728	3	545500 173995
16	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Water Company Sewage: Surface Water Outfall            Location: River Shuttle, Days Lane, SIDCUP            Authority: Environment Agency, Southern Region            Pollutant: Crude Sewage            Note: Grey Sludge In River            Incident Date: 29th December 1997            Incident Reference: 197055            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Not Given            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	731	3	545600 173895
17	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Domestic/Residential            Location: Days Lane Adjacent To, Berwick Crescent            Authority: Environment Agency, Southern Region            Pollutant: Miscellaneous - Inert Suspended Solids            Note: Sand And Cement In River            Incident Date: 7th January 1993            Incident Reference: 92T531            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Miscellaneous/Other Pollution Type            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A7NE (SW)	749	3	545400 174100
18	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Other General Premises            Location: Between Berwick Crescent, Marlborough Park            Authority: Environment Agency, Southern Region            Pollutant: Oils - Waste Oil            Note: Oil On Shuttle; Domestic/Residential            Incident Date: 3rd September 1995            Incident Reference: 395303            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Oils/Related Products            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A8SE (S)	882	3	546200 173600
18	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Water Company Sewage: Treated Water Distribution System            Location: Marlborough Park Avenue            Authority: Environment Agency, Southern Region            Pollutant: Miscellaneous - Inert Suspended Solids            Note: River Cray Has Yellowish Tinge            Incident Date: 29th January 1998            Incident Reference: 197063            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Miscellaneous/Other Pollution Type            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A8SE (S)	887	3	546200 173595
19	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Restaurant/Hotels/Pubs            Location: Danson Park, BEXLEYHEATH            Authority: Environment Agency, Southern Region            Pollutant: General Biodegradable : Vegetable Oils            Note: Not Supplied            Incident Date: 12th October 1999            Incident Reference: 3561            Catchment Area: Darent            Receiving Water: Potential River            Cause of Incident: Deliberate Action            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 10m</p>	A19NW (NE)	914	3	546500 175300

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
20	<b>Pollution Incidents to Controlled Waters</b> Property Type: WSC Sewage, Sewerage & Supply Location: Danson Park, WELLING Authority: Environment Agency, Southern Region Pollutant: General Biodegradable : Crude Sewage & Sewerage Material Note: Not Supplied Incident Date: 20th December 1999 Incident Reference: 3878 Catchment Area: Darent Receiving Water: Potential River Cause of Incident: Drainage Failures : Foul Sewer Failure Incident Severity: Category 2 - Significant Incident Positional Accuracy: Approximate location provided by supplier	A19NW (NE)	944	3	546700 175200
20	<b>Pollution Incidents to Controlled Waters</b> Property Type: Restaurant/Hotels/Pubs Location: Danson Park, BEXLEYHEATH Authority: Environment Agency, Southern Region Pollutant: General Biodegradable : Vegetable Oils Note: Not Supplied Incident Date: 19th October 1999 Incident Reference: 3634 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Drainage Failures : Other Drainage Type Failure Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 10m	A19NE (NE)	977	3	546750 175200
21	<b>Pollution Incidents to Controlled Waters</b> Property Type: Road Location: Marlborough Park Avenue Authority: Environment Agency, Southern Region Pollutant: Oils - Unknown Note: Oil Pollution Incident Date: 11th September 1992 Incident Reference: 92T401 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Oils/Related Products Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SW (S)	951	3	546000 173520
22	<b>Pollution Incidents to Controlled Waters</b> Property Type: Domestic/Residential Location: 98 Buckingham Avenue, WELLING Authority: Environment Agency, Southern Region Pollutant: Unknown Sewage Note: Washing Up Water Going Down Drain Incident Date: 14th January 1997 Incident Reference: 397003 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Sewage - Other Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A17NE (NW)	967	3	545500 173300
23	<b>Pollution Incidents to Controlled Waters</b> Property Type: Domestic/Residential Location: Location Description Not Available Authority: Environment Agency, Southern Region Pollutant: Oils - Other Oil Note: Oil At Marlborough Park Avenue Sidcup Incident Date: 17th November 1992 Incident Reference: 92T396 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Oils/Related Products Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SE (S)	981	3	546200 173500
23	<b>Pollution Incidents to Controlled Waters</b> Property Type: Miscellaneous Premises: Other Location: Shuttle Adjacent To Mr Wheatley's House Authority: Environment Agency, Southern Region Pollutant: Oils - Diesel (Including Agricultural) Note: Oil On River Incident Date: 21st July 1997 Incident Reference: 197038 Catchment Area: Not Given Receiving Water: Not Given Cause of Incident: Not Given Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SE (S)	986	3	546200 173495

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
23	<p><b>Pollution Incidents to Controlled Waters</b></p> <p>Property Type: Domestic/Residential            Location: Shuttle Adjacent To Mr Wheatley's House            Authority: Environment Agency, Southern Region            Pollutant: Oils - Diesel (Including Agricultural)            Note: Oil On River            Incident Date: 21st July 1997            Incident Reference: 397471            Catchment Area: Not Given            Receiving Water: Not Given            Cause of Incident: Not Given            Incident Severity: Category 3 - Minor Incident            Positional Accuracy: Located by supplier to within 100m</p>	A8SE (S)	986	3	546205 173495
	<p><b>River Quality</b></p> <p>Name: Shuttle R            GQA Grade: River Quality C            Reach: Cray Conf - Source            Estimated Distance (km): 7.5            Flow Rate: Flow less than 0.31 cumecs            Flow Type: River            Year: 2000</p>	A7NE (SW)	628	3	545564 174074
24	<p><b>Substantiated Pollution Incident Register</b></p> <p>Authority: Environment Agency - South East Region, Kent &amp; South London Area            Incident Date: 26th April 2021            Incident Reference: 1929014            Water Impact: Category 2 - Significant Incident            Air Impact: Category 4 - No Impact            Land Impact: Category 4 - No Impact            Positional Accuracy: Located by supplier to within 10m            Pollutant: Crude Sewage</p>	A7NE (SW)	627	3	545681 173964
25	<p><b>Substantiated Pollution Incident Register</b></p> <p>Authority: Environment Agency - South East Region, Kent &amp; South London Area            Incident Date: 22nd January 2009            Incident Reference: 647860            Water Impact: Category 2 - Significant Incident            Air Impact: Category 4 - No Impact            Land Impact: Category 4 - No Impact            Positional Accuracy: Located by supplier to within 10m            Pollutant: Oils - Diesel (Including Agricultural)</p>	A8SW (S)	743	3	545989 173729
26	<p><b>Substantiated Pollution Incident Register</b></p> <p>Authority: Environment Agency - South East Region, Kent &amp; South London Area            Incident Date: 18th October 2002            Incident Reference: 115567            Water Impact: Category 2 - Significant Incident            Air Impact: Category 4 - No Impact            Land Impact: Category 4 - No Impact            Positional Accuracy: Located by supplier to within 10m            Pollutant: Crude Sewage</p>	A19SE (NE)	995	3	546850 175120
	<p><b>Water Abstractions</b></p> <p>Operator: London Borough Of Bexley            Licence Number: 9/40/01/0058/A/Sr            Permit Version: 102            Location: Lake At Danson Park, Bexley            Authority: Environment Agency, Southern Region            Abstraction: General Agriculture: Spray Irrigation - Direct            Abstraction Type: Water may be abstracted from any point within an area            Source: Surface            Daily Rate (m3): Not Supplied            Yearly Rate (m3): Not Supplied            Details: Land Shown Edged Green On The Map.            Authorised Start: 01 April            Authorised End: 30 September            Permit Start Date: 30th May 2019            Permit End Date: Not Supplied            Positional Accuracy: Located by supplier to within 10m</p>	A19SE (NE)	1056	3	546970 175060



Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	<p><b>Water Abstractions</b></p> <p>Operator: Mayor &amp; Burgesses Of The London Borough Of Bexley  Licence Number: 9/40/01/0058/A/Sr  Permit Version: 101  Location: Lake At Danson Park, Bexley  Authority: Environment Agency, Southern Region  Abstraction: General Agriculture: Spray Irrigation - Direct  Abstraction Type: Water may be abstracted from any point within an area  Source: Surface  Daily Rate (m3): Not Supplied  Yearly Rate (m3): Not Supplied  Details: Land Shown Edged Green On The Map.  Authorised Start: 01 April  Authorised End: 30 September  Permit Start Date: 30th October 2006  Permit End Date: Not Supplied  Positional Accuracy: Located by supplier to within 10m</p>	A19SE (NE)	1056	3	546970 175060
	<p><b>Water Abstractions</b></p> <p>Operator: The Mayor And Burgesses Of The London Borough Of Bexley  Licence Number: 9/40/01/0058/A/Sr  Permit Version: 100  Location: Lake At Danson Park, Bexley  Authority: Environment Agency, Southern Region  Abstraction: General Agriculture: Spray Irrigation - Direct  Abstraction Type: Water may be abstracted from any point within an area  Source: Surface  Daily Rate (m3): 68  Yearly Rate (m3): 1363.8  Details: Land Shown Edged Green On The Map.  Authorised Start: 01 April  Authorised End: 30 September  Permit Start Date: 3rd July 1998  Permit End Date: Not Supplied  Positional Accuracy: Located by supplier to within 10m</p>	A19SE (NE)	1056	3	546970 175060
	<p><b>Water Abstractions</b></p> <p>Operator: The National Grid Company Plc  Licence Number: 9/40/01/0162/G  Permit Version: 100  Location: Point A3, Footscray Lane, Bexley.  Authority: Environment Agency, Southern Region  Abstraction: Amenity: Spray Irrigation - Direct  Abstraction Type: Water may be abstracted from a single point  Source: Groundwater  Daily Rate (m3): Not Supplied  Yearly Rate (m3): Not Supplied  Details: The Position Marked A On The Map.  Authorised Start: 01 October  Authorised End: 30 September  Permit Start Date: 23rd November 2006  Permit End Date: Not Supplied  Positional Accuracy: Located by supplier to within 10m</p>	A10NW (SE)	1271	3	547190 173860
	<p><b>Water Abstractions</b></p> <p>Operator: Sidcup Golf Club 1926 Ltd  Licence Number: 37/101  Permit Version: 100  Location: Point A, Lake At Sidcup Golf Club.  Authority: Environment Agency, Southern Region  Abstraction: Golf Courses: Spray Irrigation - Direct  Abstraction Type: Water may be abstracted from a single point  Source: Surface  Daily Rate (m3): Not Supplied  Yearly Rate (m3): Not Supplied  Details: As Boldly Outlined On Licence Map.  Authorised Start: 01 April  Authorised End: 31 October  Permit Start Date: 30th October 2006  Permit End Date: Not Supplied  Positional Accuracy: Located by supplier to within 10m</p>	A4NE (SE)	1291	3	546880 173470

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	<b>Water Abstractions</b> Operator: The National Grid Company Plc Licence Number: 9/40/01/0162/G Permit Version: 100 Location: Point A2, Footscray Lane, Bexley. Authority: Environment Agency, Southern Region Abstraction: Amenity: Spray Irrigation - Direct Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: The Position Marked A On The Map. Authorised Start: 01 October Authorised End: 30 September Permit Start Date: 23rd November 2006 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A5NW (SE)	1635	3	547230 173320
	<b>Groundwater Vulnerability Map</b> Combined Unproductive Aquifer (may have productive aquifer beneath) Classification: Unproductive Vulnerability: Unproductive Bedrock Aquifer, No Superficial Aquifer Combined Aquifer: Low Pollutant Speed: Mixed Bedrock Flow: <300 mm/year Dilution: 40-70% Baseflow Index: <90% Superficial Patchiness: <3m Superficial Thickness: No Data Superficial Recharge:	A13NW (NE)	0	4	546059 174486
	<b>Groundwater Vulnerability - Soluble Rock Risk</b> None				
	<b>Bedrock Aquifer Designations</b> Aquifer Designation: Unproductive Strata	A13NW (NE)	0	4	546059 174486
	<b>Superficial Aquifer Designations</b> No Data Available				
27	<b>Source Protection Zones</b> Name: Not Supplied Source: Environment Agency, Head Office Reference: Not Supplied Type: Zone III (Total Catchment): The total area needed to support the discharge from the protected groundwater source.	A13NW (NE)	0	3	546059 174486
28	<b>Source Protection Zones</b> Name: Not Supplied Source: Environment Agency, Head Office Reference: Not Supplied Type: Zone II (Outer Protection Zone): Either 25% of the source area or a 400 day travel time whichever is greater.	A8NE (S)	395	3	546186 174098
	<b>Extreme Flooding from Rivers or Sea without Defences</b> None				
	<b>Flooding from Rivers or Sea without Defences</b> None				
	<b>Areas Benefiting from Flood Defences</b> None				
	<b>Flood Water Storage Areas</b> None				
	<b>Flood Defences</b> None				
29	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 52.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Thames Primacy: 1	A12SE (SW)	450	5	545720 174165

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
30	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 47.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NE (SW)	621	5	545659 173988
31	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 14.4 Watercourse Level: Underground Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NE (SW)	622	5	545666 173981
32	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 277.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NE (SW)	625	5	545675 173970
33	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 2.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NE (SW)	632	5	545625 174004
34	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 192.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NE (SW)	633	5	545623 174005
35	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 154.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wyncham Stream Catchment Name: Thames Primacy: 1	A8SW (S)	717	5	545862 173778
36	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 452.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A8SW (S)	717	5	545870 173776
37	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 88.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Thames Primacy: 1	A7NE (SW)	728	5	545444 174070
38	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 17.6 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NE (SW)	739	5	545441 174053

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
39	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 2.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NE (SW)	755	5	545424 174051
40	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 162.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NE (SW)	757	5	545422 174050
41	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 1260.7 Watercourse Level: Not Supplied Permanent: True Watercourse Name: Not Supplied Catchment Name: Thames Primacy: 1	A7NW (SW)	773	5	545377 174093
42	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 35.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Thames Primacy: 1	A8SW (SW)	820	5	545725 173718
43	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 660.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wyncham Stream Catchment Name: Thames Primacy: 1	A8SW (S)	834	5	545749 173692
44	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 4.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NW (SW)	918	5	545285 173965
45	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 306.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A7NW (SW)	922	5	545283 173962
46	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 8.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A8SE (S)	936	5	546215 173547
47	<b>OS Water Network Lines</b> Watercourse Form: Inland river Watercourse Length: 1005.6 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Shuttle Catchment Name: Thames Primacy: 1	A8SE (S)	944	5	546220 173540

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	<b>Local Authority Landfill Coverage</b> Name: London Borough of Bexley - Has supplied landfill data		0	2	546059 174486
	<b>Local Authority Landfill Coverage</b> Name: London Borough of Greenwich - Has supplied landfill data		891	6	545180 174257

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	<b>BGS 1:625,000 Solid Geology</b> Description: Thames Group	A13NW (NE)	0	1	546059 174486
	<b>Coal Mining Affected Areas</b> In an area that might not be affected by coal mining				
	<b>Non Coal Mining Areas of Great Britain</b> Risk: Unlikely Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486
	<b>Potential for Collapsible Ground Stability Hazards</b> Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486
	<b>Potential for Compressible Ground Stability Hazards</b> Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486
	<b>Potential for Compressible Ground Stability Hazards</b> Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NE (NE)	210	1	546185 174670
	<b>Potential for Ground Dissolution Stability Hazards</b> Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486
	<b>Potential for Landslide Ground Stability Hazards</b> Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486
	<b>Potential for Running Sand Ground Stability Hazards</b> Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486
	<b>Potential for Running Sand Ground Stability Hazards</b> Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NW (W)	84	1	545954 174507
	<b>Potential for Running Sand Ground Stability Hazards</b> Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NE (NE)	210	1	546185 174670
	<b>Potential for Shrinking or Swelling Clay Ground Stability Hazards</b> Hazard Potential: Moderate Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486
	<b>Potential for Shrinking or Swelling Clay Ground Stability Hazards</b> Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NW (W)	84	1	545954 174507
	<b>Radon Potential - Radon Affected Areas</b> Affected Area: The property is in a Lower probability radon area (less than 1% of homes are estimated to be at or above the Action Level). Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486
	<b>Radon Potential - Radon Protection Measures</b> Protection Measure: No radon protective measures are necessary in the construction of new dwellings or extensions Source: British Geological Survey, National Geoscience Information Service	A13NW (NE)	0	1	546059 174486

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
48	<b>Contemporary Trade Directory Entries</b> Name: Affix Windows & Doors Ltd Location: 226, Blackfen Road, Sidcup, DA15 8PW Classification: Window Frame Manufacturers Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NW (N)	21	-	546059 174513
48	<b>Contemporary Trade Directory Entries</b> Name: Aura Construction Location: 236 Blackfen Road, Sidcup, Kent, DA15 8PW Classification: Mechanical Engineers Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	23	-	546097 174504
48	<b>Contemporary Trade Directory Entries</b> Name: Blackfen M O T Testing Station Location: Rear Of 243-259 Blackfen Road, Sidcup, DA15 8PR Classification: Mot Testing Centres Status: <b>Active</b> Positional Accuracy: Manually positioned to an adjacent address or location	A13NE (NE)	61	-	546107 174543
48	<b>Contemporary Trade Directory Entries</b> Name: Beaven Bros Location: 243, Blackfen Road, Sidcup, Kent, DA15 8PR Classification: Disability Equipment - Manufacturers & Suppliers Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	62	-	546103 174546
48	<b>Contemporary Trade Directory Entries</b> Name: Mr Steel Location: 247, Blackfen Road, Sidcup, DA15 8PR Classification: Garage Services Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	62	-	546111 174542
48	<b>Contemporary Trade Directory Entries</b> Name: Fenways Location: 241, Blackfen Road, Sidcup, Kent, DA15 8PR Classification: Car Dealers Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	63	-	546092 174550
48	<b>Contemporary Trade Directory Entries</b> Name: Fivestar Dry Cleaning Location: 233, Blackfen Road, Sidcup, Kent, DA15 8PR Classification: Dry Cleaners Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (N)	66	-	546068 174556
48	<b>Contemporary Trade Directory Entries</b> Name: Court Electrics Location: 251, Blackfen Road, Sidcup, DA15 8PR Classification: Domestic Appliances - Servicing, Repairs & Parts Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	66	-	546120 174540
48	<b>Contemporary Trade Directory Entries</b> Name: Reds Location: 233, Blackfen Road, Sidcup, Kent, DA15 8PR Classification: Dry Cleaners Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (N)	66	-	546068 174556
48	<b>Contemporary Trade Directory Entries</b> Name: Blackfen M O T Centre Location: Rear of 243-259, Blackfen Road, Sidcup, DA15 8PR Classification: Mot Testing Centres Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	95	-	546138 174563
49	<b>Contemporary Trade Directory Entries</b> Name: Homepride Ltd Location: 224, Blackfen Road, Sidcup, Kent, DA15 8PN Classification: Builders' Merchants Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NW (NW)	29	-	546035 174525
49	<b>Contemporary Trade Directory Entries</b> Name: P W Motors Blackfen Ltd Location: 216-218, Blackfen Road, Sidcup, Kent, DA15 8PT Classification: Car Dealers Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NW (NW)	50	-	546009 174537

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
49	<b>Contemporary Trade Directory Entries</b> Name: Scooter & Mobilitymart Location: 223, Blackfen Road, Sidcup, Kent, DA15 8PR Classification: Stairlifts - Manufacturers & Installers Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NW (N)	73	-	546039 174569
49	<b>Contemporary Trade Directory Entries</b> Name: Sheerglass Wheels & Tyres Location: Sidcup, DA15 8PR Classification: Tyre Dealers Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NW (N)	73	-	546031 174569
49	<b>Contemporary Trade Directory Entries</b> Name: Sheerclass Wheels & Tyres Location: 219-221, Blackfen Road, Sidcup, DA15 8PR Classification: Tyre Dealers Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NW (N)	78	-	546032 174574
50	<b>Contemporary Trade Directory Entries</b> Name: Blackfen Reproductions Location: 242, Blackfen Road, Sidcup, Kent, DA15 8PW Classification: Furniture - Reproduction Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (E)	43	-	546125 174498
51	<b>Contemporary Trade Directory Entries</b> Name: Premier Autocentres Location: 184-214, Blackfen Road, Sidcup, Kent, DA15 8PT Classification: Mot Testing Centres Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NW (NW)	74	-	545985 174548
52	<b>Contemporary Trade Directory Entries</b> Name: Multi Function Recovery Services Location: 2, Wellington Avenue, Sidcup, Kent, DA15 9HG Classification: Car Breakdown & Recovery Services Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13SE (E)	122	-	546199 174448
53	<b>Contemporary Trade Directory Entries</b> Name: Alpha Healthchecks Location: 19, Blackfen Parade, Blackfen Road, Sidcup, Kent, DA15 9LU Classification: Medical & Dental Laboratories Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13SE (E)	175	-	546258 174467
53	<b>Contemporary Trade Directory Entries</b> Name: S E Tyres Fast Fit Centre Location: 6-7, Wellington Parade, Blackfen Road, Sidcup, DA15 9NB Classification: Tyre Dealers Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NE (E)	201	-	546283 174510
54	<b>Contemporary Trade Directory Entries</b> Name: Pakt Location: 168, Blackfen Road, Sidcup, DA15 8PT Classification: Mould Manufacturers Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NW (W)	192	-	545854 174553
55	<b>Contemporary Trade Directory Entries</b> Name: Art Of Ironing Location: 310, Westwood Lane, Sidcup, Kent, DA15 9PT Classification: Ironing & Home Laundry Services Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	199	-	546234 174616
55	<b>Contemporary Trade Directory Entries</b> Name: Art Of Ironing Location: 310, Westwood Lane, SIDCUP, Kent, DA15 9PT Classification: Ironing & Home Laundry Services Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	199	-	546234 174616
55	<b>Contemporary Trade Directory Entries</b> Name: Approved Cars & Finance Location: 300-302, Westwood Lane, Sidcup, Kent, DA15 9PT Classification: Car Dealers - Used Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	216	-	546233 174642



Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
55	<b>Contemporary Trade Directory Entries</b> Name: Brockley Park Cars Ltd Location: 300-302, Westwood Lane, Sidcup, DA15 9PT Classification: Garage Services Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	216	-	546233 174642
55	<b>Contemporary Trade Directory Entries</b> Name: Bridgewood Motor Co Ltd Location: 300-302, Westwood Lane, Sidcup, Kent, DA15 9PT Classification: Car Dealers - Used Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	216	-	546233 174642
55	<b>Contemporary Trade Directory Entries</b> Name: Motorzone Ltd Location: 300-302, Westwood Lane, Sidcup, Kent, DA15 9PT Classification: Car Dealers Status: <b>Inactive</b> Positional Accuracy: Manually positioned to the address or location	A13NE (NE)	216	-	546233 174642
55	<b>Contemporary Trade Directory Entries</b> Name: Pickford Mix Location: 300-302, Westwood Lane, Sidcup, Kent, DA15 9PT Classification: Firework Stockists Status: <b>Inactive</b> Positional Accuracy: Manually positioned to the address or location	A13NE (NE)	216	-	546233 174642
55	<b>Contemporary Trade Directory Entries</b> Name: Motorcare Cars Location: 300-302, Westwood Lane, Sidcup, Kent, DA15 9PT Classification: Car Dealers - Used Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	216	-	546233 174642
55	<b>Contemporary Trade Directory Entries</b> Name: Blackfen Sales & Service Centre Location: 300-302, Westwood Lane, Sidcup, Kent, DA15 9PT Classification: Car Dealers - Used Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (NE)	216	-	546233 174642
56	<b>Contemporary Trade Directory Entries</b> Name: S & G Brown Location: 27a, Lime Grove, Sidcup, DA15 8PH Classification: Road Haulage Services Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13SW (SW)	224	-	545853 174366
57	<b>Contemporary Trade Directory Entries</b> Name: Blackfen Dry Cleaners Location: 11, Wellington Parade, Blackfen Road, Sidcup, Kent, DA15 9NB Classification: Dry Cleaners Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A13NE (E)	226	-	546308 174509
57	<b>Contemporary Trade Directory Entries</b> Name: Wash World Location: 11, Wellington Parade, Blackfen Road, Sidcup, Kent, DA15 9NB Classification: Laundries & Launderettes Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (E)	226	-	546308 174509
57	<b>Contemporary Trade Directory Entries</b> Name: Blackfen Window Co Location: 21-22, Wellington Parade, Blackfen Road, Sidcup, Kent, DA15 9NB Classification: Fascias and Soffits Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (E)	275	-	546357 174509
57	<b>Contemporary Trade Directory Entries</b> Name: Cars For You Location: Blackfen Rd, Sidcup, Kent, DA15 9NG Classification: Car Dealers - Used Status: <b>Inactive</b> Positional Accuracy: Manually positioned to the road within the address or location	A13SE (E)	282	-	546366 174474
57	<b>Contemporary Trade Directory Entries</b> Name: Saunders Abbott Location: 309-315, Blackfen Road, Sidcup, Kent, DA15 9NG Classification: Car Dealers - Used Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A13NE (E)	293	-	546376 174496

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
57	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Danson Motors            Location: 309-311, Blackfen Road, Sidcup, DA15 9NG            Classification: Car Dealers - Used  <b>Status: Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NE (E)	293	-	546377 174493
57	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Motorwyse            Location: 309-311, Blackfen Road, Sidcup, Kent, DA15 9NG            Classification: Car Dealers - Used  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NE (E)	293	-	546376 174496
57	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Main Dealer Direct            Location: 309-311, Blackfen Road, Sidcup, Kent, DA15 9NG            Classification: Car Dealers - Used  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NE (E)	293	-	546376 174496
57	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Blackfen Motorist Centre Ltd            Location: Rear of 309-315, Blackfen Road, Sidcup, DA15 9NG            Classification: Garage Services  <b>Status: Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NE (E)	298	-	546381 174507
57	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Gillman Motors Ltd            Location: Rear of 309-315, Blackfen Road, Sidcup, DA15 9NG            Classification: Car Dealers - Used  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NE (E)	298	-	546381 174507
57	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Blackfen Drive In Accident Repair Centre            Location: 309-315, BLACKFEN ROAD, SIDCUP, DA15 9NG            Classification: Car Body Repairs  <b>Status: Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NE (E)	299	-	546382 174492
57	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Empire Motor Co            Location: 313-315, Blackfen Road, Sidcup, Kent, DA15 9NG            Classification: Car Dealers  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NE (E)	310	-	546393 174490
57	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Motorzone Ltd            Location: 313-315, Blackfen Road, Sidcup, Kent, DA15 9NG            Classification: Car Dealers - Used  <b>Status: Inactive</b>            Positional Accuracy: Manually positioned to an adjacent address or location</p>	A13NE (E)	310	-	546393 174490
58	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Clutches Of Sidcup            Location: 9, Ashcroft Avenue, Sidcup, Kent, DA15 8NS            Classification: Brake &amp; Clutch Service Centres  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13SE (S)	247	-	546111 174230
59	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: J A D E Cleaning Services            Location: 2, Christopher Close, Sidcup, Kent, DA15 8PU            Classification: Commercial Cleaning Services  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NW (W)	269	-	545773 174545
60	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Epson (Cleaning) Ltd            Location: 251, Days Lane, Sidcup, Kent, DA15 8JX            Classification: Cleaning Services - Commercial  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13SW (SW)	275	-	545899 174241
60	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: International Medical Movements Ltd            Location: Unit C, 251, Days Lane, Sidcup, Kent, DA15 8JX            Classification: Road Haulage Services  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13SW (SW)	275	-	545899 174241

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
61	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Shell (Uk) Ltd            Location: Woodman Service Station, Westwood La, Sidcup, Kent, DA15 9PT            Classification: Petrol Filling Stations - 24 Hour  <b>Status: Inactive</b>            Positional Accuracy: Manually positioned to the road within the address or location</p>	A13NE (NE)	298	-	546268 174720
62	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Barry Crow            Location: 41, Harman Drive, Sidcup, Kent, DA15 8JZ            Classification: Photocopiers  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13SW (SW)	310	-	545800 174288
63	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Blackfen Building Services            Location: 122, Lyndon Avenue, Sidcup, Kent, DA15 8RN            Classification: Engineers - General  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13NW (NW)	323	-	545843 174754
64	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Swandale Refridgeration            Location: 241, Days Lane, Sidcup, Kent, DA15 8JX            Classification: Road Haulage Services  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A13SW (SW)	358	-	545855 174171
65	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Bickmans Electrical Contractors Ltd            Location: 45, Queenswood Road, Sidcup, Kent, DA15 8QP            Classification: Electrical Engineers  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12SE (SW)	370	-	545711 174323
66	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: S T Resurfacing Ltd            Location: 233, Days Lane, Sidcup, Kent, DA15 8JX            Classification: Asphalt &amp; Coated Macadam Laying Contractors  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A8NW (SW)	411	-	545823 174128
66	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Cubewing Systems            Location: 233, Days Lane, Sidcup, Kent, DA15 8JX            Classification: Office Furniture &amp; Equipment  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A8NW (SW)	411	-	545823 174128
67	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: House Maids Direct            Location: 71, Queenswood Road, Sidcup, Kent, DA15 8QP            Classification: Cleaning Services - Domestic  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12SE (SW)	452	-	545681 174212
67	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: D T R Preservations            Location: 73, Queenswood Road, Sidcup, Kent, DA15 8QP            Classification: Damp &amp; Dry Rot Control  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12SE (SW)	463	-	545669 174209
68	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Allgas &amp; Plumbing Services            Location: 26, Orchard Rise East, Sidcup, Kent, DA15 8RT            Classification: Boilers - Servicing, Replacements &amp; Repairs  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12NE (NW)	454	-	545630 174696
69	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Berlin Motor Works            Location: 88, BURNS AVENUE, SIDCUP, DA15 9HR            Classification: Garage Services  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A14SW (SE)	528	-	546560 174257
69	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Berlin Motor Works            Location: 88, BURNS AVENUE, SIDCUP, DA15 9HR            Classification: Garage Services  <b>Status: Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A14SW (SE)	528	-	546560 174257

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
70	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Kent Surfacing            Location: 43, Cowper Close, Welling, Kent, DA16 2JT            Classification: Asphalt &amp; Coated Macadam Laying Contractors            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A18SE (NE)	539	-	546386 174931
71	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Chips Away            Location: 362, Blackfen Road, Sidcup, DA15 9NY            Classification: Car Body Repairs            Status: <b>Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A14SW (E)	551	-	546628 174401
72	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Cooker Cure            Location: 35, Fen Grove, Sidcup, Kent, DA15 8QG            Classification: Domestic Appliances - Servicing, Repairs &amp; Parts            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A7NE (SW)	563	-	545684 174043
73	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Dane-Lites Ltd            Location: 56, Portland Avenue, Sidcup, Kent, DA15 9HA            Classification: Candle Manufacturers &amp; Suppliers            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A9NW (SE)	570	-	546498 174093
74	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: The Oval Digital Photo Centre            Location: Marlborough Park Post Office, 41, The Oval, Sidcup, Kent, DA15 9ER            Classification: Photographic Processors            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A8NE (S)	581	-	546229 173916
75	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: 1st Hire 2000 Ltd            Location: 78, Blackfen Road, Sidcup, Kent, DA15 8SW            Classification: Gas Suppliers            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12NE (W)	600	-	545443 174582
76	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Oval Pet Centre Ltd            Location: 19, The Oval, Sidcup, Kent, DA15 9ER            Classification: Veterinary Equipment Manufacturers            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A8NE (S)	623	-	546188 173862
77	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Trez Motors Ltd            Location: 15, Ramillies Road, Sidcup, Kent, DA15 9JA            Classification: Commercial Vehicle Servicing, Repairs, Parts &amp; Accessories            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A14SW (E)	626	-	546691 174336
78	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Bob Barker Auto Repairs            Location: 22, Wellan Close, Sidcup, DA15 9PN            Classification: Garage Services            Status: <b>Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A14NW (E)	652	-	546726 174599
78	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Bob Barker Auto Repairs            Location: 22, Wellan Close, Sidcup, Kent, DA15 9PN            Classification: Car Engine Tuning &amp; Diagnostic Services            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A14NW (E)	652	-	546726 174599
79	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Bexley Carpet Cleaners            Location: 70, Ramillies Road, Sidcup, Kent, DA15 9HZ            Classification: Cleaning Services - Domestic            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A14SW (SE)	653	-	546671 174200
79	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Bexley Carpet Cleaners            Location: 70, Ramillies Road, Sidcup, DA15 9HZ            Classification: Carpet, Curtain &amp; Upholstery Cleaners            Status: <b>Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A14SW (SE)	653	-	546671 174200

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
80	<b>Contemporary Trade Directory Entries</b> Name: E & M Waste Clearance Location: 153, Yorkland Avenue, Welling, DA16 2LQ Classification: Waste Disposal Services Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A18SW (N)	654	-	545950 175144
81	<b>Contemporary Trade Directory Entries</b> Name: Motors Express Location: 9, Gloucester Avenue, Welling, DA16 2LL Classification: Garage Services Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A18SW (N)	662	-	545841 175128
81	<b>Contemporary Trade Directory Entries</b> Name: Aztec Autos Location: 34, Gloucester Avenue, Welling, Kent, DA16 2LJ Classification: Garage Services Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A18SW (NW)	674	-	545792 175125
82	<b>Contemporary Trade Directory Entries</b> Name: Andrews Timber Location: 387, Blackfen Road, Sidcup, Kent, DA15 9NJ Classification: Sawmills & Wood Shavings Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A14SE (E)	664	-	546746 174426
83	<b>Contemporary Trade Directory Entries</b> Name: Olins Pharmacy Location: 3, The Oval, Sidcup, Kent, DA15 9ER Classification: Pharmaceutical Manufacturers & Distributors Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A8NE (S)	668	-	546173 173813
83	<b>Contemporary Trade Directory Entries</b> Name: Oval Dry Cleaners Location: 1, The Oval, Sidcup, Kent, DA15 9ER Classification: Dry Cleaners Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A8NE (S)	671	-	546167 173808
83	<b>Contemporary Trade Directory Entries</b> Name: Floyds Of Sidcup Location: 1b, The Oval, Sidcup, DA15 9ER Classification: Builders' Merchants Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A8SE (S)	674	-	546162 173804
83	<b>Contemporary Trade Directory Entries</b> Name: Scotts Of Sidcup Location: 1b, The Oval, Sidcup, Kent, DA15 9ER Classification: Paint Spraying Equipment & Accessories Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A8SE (S)	674	-	546162 173804
83	<b>Contemporary Trade Directory Entries</b> Name: Floyds Of Sidcup Location: 1b, The Oval, Sidcup, Kent, DA15 9ER Classification: Builders' Merchants Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A8SE (S)	674	-	546162 173804
84	<b>Contemporary Trade Directory Entries</b> Name: Brad'S Rubbish Clearance Location: 35, HADDON GROVE, SIDCUP, DA15 8NA Classification: Waste Disposal Services Status: <b>Active</b> Positional Accuracy: Automatically positioned to the address	A8SW (S)	670	-	546030 173800
85	<b>Contemporary Trade Directory Entries</b> Name: Abtek Servicing Location: 34, Sherwood Park Avenue, Sidcup, Kent, DA15 9HW Classification: Boilers - Servicing, Replacements & Repairs Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A9NW (SE)	679	-	546542 173985
85	<b>Contemporary Trade Directory Entries</b> Name: Abtek Servicing Location: 34, Sherwood Park Avenue, Sidcup, DA15 9HW Classification: Boilers - Servicing, Replacements & Repairs Status: <b>Inactive</b> Positional Accuracy: Automatically positioned to the address	A9NW (SE)	679	-	546542 173985

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
86	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Sunstop Blinds            Location: A, 2, Burns Avenue, Sidcup, Kent, DA15 9HP            Classification: Blinds, Awnings &amp; Canopies            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A9NW (SE)	679	-	546599 174043
87	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: P A Cleaning Contractors            Location: 141, Merlin Road, Welling, Kent, DA16 2JS            Classification: Cleaning Services - Commercial            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A19SW (NE)	702	-	546527 175029
88	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Cool Dynamics Ltd            Location: 46, Ridgeway West, Sidcup, Kent, DA15 8SD            Classification: Air Conditioning &amp; Refrigeration Contractors            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A17SE (NW)	740	-	545395 174862
89	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Denlin Hygiene Services Ltd            Location: 117, Marlborough Park Avenue, Sidcup, Kent, DA15 9DY            Classification: Chemicals &amp; Allied Products            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A8SE (S)	742	-	546187 173740
90	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Southside Cleaning Ltd            Location: 34, Gordon Road, Sidcup, Kent, DA15 8SX            Classification: Cleaning Services - Commercial            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12NW (W)	761	-	545305 174704
90	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Southside Cleaning Ltd            Location: 34, Gordon Road, Sidcup, Kent, DA15 8SX            Classification: Commercial Cleaning Services            Status: <b>Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A12NW (W)	761	-	545305 174704
91	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Surecure            Location: 11a, Oaklands Avenue, Sidcup, DA15 8NF            Classification: Damp &amp; Dry Rot Control            Status: <b>Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A8SW (S)	778	-	545798 173734
92	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Earl Power Engineering Ltd            Location: 7, Oaklands Avenue, Sidcup, Kent, DA15 8NF            Classification: Electrical Engineers            Status: <b>Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A8SW (S)	785	-	545864 173708
93	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Bishop Graphics            Location: 45, Blackfen Road, Sidcup, Kent, DA15 8QB            Classification: Printers            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12NW (W)	789	-	545252 174571
94	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: S M Artwork            Location: 197, Burnt Oak Lane, Sidcup, Kent, DA15 9DQ            Classification: Copying &amp; Duplicating Services            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A9NW (SE)	808	-	546606 173870
95	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Premier Print            Location: 189, Norfolk Crescent, Sidcup, Kent, DA15 8HX            Classification: Printers            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A7NE (SW)	811	-	545428 173952
96	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: A2 Fast Lift Recovery            Location: 879, East Rochester Way, Sidcup, Kent, DA15 8TF            Classification: Car Breakdown &amp; Recovery Services            Status: <b>Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A17SW (NW)	818	-	545358 174952

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
96	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Vehicle Recovery South East London            Location: 879, East Rochester Way, SIDCUP, Kent, DA15 8TF            Classification: Car Breakdown &amp; Recovery Services  <b>Status: Active</b>            Positional Accuracy: Automatically positioned to the address</p>	A17SW (NW)	818	-	545358 174952
96	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Vehicle Recovery South East London            Location: 879, East Rochester Way, Sidcup, DA15 8TF            Classification: Car Breakdown &amp; Recovery Services  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A17SW (NW)	818	-	545358 174952
97	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: The Parade            Location: 17, Falconwood Parade, Welling, Kent, DA16 2PL            Classification: Dry Cleaners  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A17NE (NW)	824	-	545597 175194
98	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: A Star Recovery            Location: 45, Orchard Rise West, Sidcup, Kent, DA15 8TA            Classification: Breakdown and Recovery  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12NW (W)	853	-	545228 174764
99	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Arnasons Ltd            Location: 104, Berwick Crescent, Sidcup, Kent, DA15 8HR            Classification: Air Conditioning Equipment &amp; Systems  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A7NW (SW)	856	-	545320 174024
100	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Rileys Carpet Cleaners            Location: 2, Warne Place, Westerham Drive, Sidcup, Kent, DA15 9PA            Classification: Carpet, Curtain &amp; Upholstery Cleaners  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A14SE (E)	860	-	546939 174400
101	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: K Germin            Location: 169, Norfolk Crescent, Sidcup, Kent, DA15 8HX            Classification: Painting &amp; Decorating Supplies  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A7NW (SW)	861	-	545373 173939
102	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: A J Services            Location: 19, Blackfen Road, Sidcup, Kent, DA15 8QD            Classification: Boilers - Servicing, Replacements &amp; Repairs  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A12NW (W)	879	-	545159 174510
103	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: P W Refrigeration Services            Location: 141, Hook Lane, Welling, Kent, DA16 2DU            Classification: Refrigerators &amp; Freezers - Servicing &amp; Repairs  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A18NW (N)	914	-	546037 175410
104	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: A1 Recovery            Location: East Rochester Way, Sidcup, Kent, DA15 8TF            Classification: Car Breakdown &amp; Recovery Services  <b>Status: Inactive</b>            Positional Accuracy: Manually positioned within the geographical locality</p>	A17SW (NW)	930	-	545249 174990
104	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: South East Recovery Services            Location: East Rochester Way, Sidcup, Kent, DA15 8TF            Classification: Breakdown and Recovery  <b>Status: Inactive</b>            Positional Accuracy: Manually positioned within the geographical locality</p>	A17SW (NW)	930	-	545249 174990
105	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Sherwood Installations            Location: 153, Sherwood Park Avenue, Sidcup, Kent, DA15 9JG            Classification: Boilers - Servicing, Replacements &amp; Repairs  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A9NE (E)	935	-	546952 174138

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
106	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Ace Autos At Home            Location: 100, Orchard Rise West, Sidcup, Kent, DA15 8SZ            Classification: Garage Services  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A17SW (NW)	954	-	545164 174880
107	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: R P Motor Repairs            Location: 40, Rosebery Avenue, Sidcup, DA15 8HZ            Classification: Garage Services  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A7SW (SW)	990	-	545325 173797
108	<p><b>Contemporary Trade Directory Entries</b></p> <p>Name: Valentina Fine Foods            Location: 63, Yorkland Avenue, WELLING, Kent, DA16 2LE            Classification: Meat - Wholesale  <b>Status: Inactive</b>            Positional Accuracy: Automatically positioned to the address</p>	A17NE (N)	995	-	545707 175435
109	<p><b>Fuel Station Entries</b></p> <p>Name: Shell Woodman            Location: Westwood Lane Lyndon Ave, , Sidcup, Outer London, DA15 9PT            Brand: Shell            Premises Type: Not Applicable  <b>Status: Obsolete</b>            Positional Accuracy: Approximate location provided by supplier</p>	A13NW (NW)	137	-	545941 174593
110	<p><b>Underground Electrical Cables</b></p> <p>Unique Feature Identifier: 0            Cable Status: Planned            Cable Type: Alternating Current            Record Last Updated: 2nd June 2020</p>	A13NE (N)	229	7	546138 174710



Agency & Hydrological	Version	Update Cycle
<b>Contaminated Land Register Entries and Notices</b> Environment Agency - Head Office London Borough of Barking And Dagenham - Health and Consumer Services London Borough of Greenwich - Environmental Health Department London Borough of Newham - Environmental Health Department Dartford Borough Council - Environmental Health Department London Borough of Bexley - Environmental Health Department London Borough of Bromley - Environmental Health Department London Borough of Lewisham - Environmental Health Department	June 2020 October 2017 October 2017 October 2017 September 2017 September 2017 September 2017 September 2017	Annually Annual Rolling Update Annual Rolling Update Annual Rolling Update Annual Rolling Update Annual Rolling Update Annual Rolling Update
<b>Discharge Consents</b> Environment Agency - Southern Region Environment Agency - Thames Region	October 2022 October 2022	Quarterly Quarterly
<b>Enforcement and Prohibition Notices</b> Environment Agency - Southern Region Environment Agency - Thames Region	March 2013 March 2013	
<b>Integrated Pollution Controls</b> Environment Agency - Southern Region Environment Agency - Thames Region	January 2009 January 2009	
<b>Integrated Pollution Prevention And Control</b> Environment Agency - South East Region - Kent & South London Area Environment Agency - South East Region - North East Thames Area Environment Agency - Southern Region Environment Agency - Thames Region	October 2022 October 2022 October 2022 October 2022	Quarterly Quarterly Quarterly Quarterly
<b>Local Authority Integrated Pollution Prevention And Control</b> London Borough of Bromley - Environmental Health Department London Borough of Greenwich - Environmental Health Department London Borough of Bexley - Environmental Health Department London Borough of Newham - Environmental Health Department London Borough of Barking And Dagenham - Environmental Health Department London Port Health Authority - Environmental Services Dartford Borough Council - Environmental Health Department London Borough of Lewisham - Environmental Health Department	July 2015 June 2014 March 2015 March 2015 May 2016 October 2014 September 2014 September 2014	Variable Variable Variable Variable Variable Variable Variable Variable
<b>Local Authority Pollution Prevention and Controls</b> London Borough of Bromley - Environmental Health Department London Borough of Greenwich - Environmental Health Department London Borough of Bexley - Environmental Health Department London Borough of Newham - Environmental Health Department London Borough of Barking And Dagenham - Environmental Health Department London Port Health Authority - Environmental Services Dartford Borough Council - Environmental Health Department London Borough of Lewisham - Environmental Health Department	July 2015 June 2014 March 2015 March 2015 May 2016 October 2014 September 2014 September 2014	Annual Rolling Update Annual Rolling Update Annual Rolling Update Annual Rolling Update Annual Rolling Update Annual Rolling Update Annual Rolling Update Annual Rolling Update
<b>Local Authority Pollution Prevention and Control Enforcements</b> London Borough of Bromley - Environmental Health Department London Borough of Greenwich - Environmental Health Department London Borough of Bexley - Environmental Health Department London Borough of Newham - Environmental Health Department London Borough of Barking And Dagenham - Environmental Health Department London Port Health Authority - Environmental Services Dartford Borough Council - Environmental Health Department London Borough of Lewisham - Environmental Health Department	July 2015 June 2014 March 2015 March 2015 May 2016 October 2014 September 2014 September 2014	Variable Variable Variable Variable Variable Variable Variable Variable
<b>Nearest Surface Water Feature</b> Ordnance Survey	October 2022	
<b>Pollution Incidents to Controlled Waters</b> Environment Agency - Southern Region Environment Agency - Thames Region	December 1999 September 1999	

Agency & Hydrological	Version	Update Cycle
<b>Prosecutions Relating to Authorised Processes</b> Environment Agency - Southern Region Environment Agency - Thames Region	July 2015 July 2015	
<b>Prosecutions Relating to Controlled Waters</b> Environment Agency - Southern Region Environment Agency - Thames Region	March 2013 March 2013	
<b>Registered Radioactive Substances</b> Environment Agency - Southern Region Environment Agency - Thames Region	June 2016 June 2016	As notified As notified
<b>River Quality</b> Environment Agency - Head Office	November 2001	Not Applicable
<b>River Quality Biology Sampling Points</b> Environment Agency - Head Office	April 2012	
<b>River Quality Chemistry Sampling Points</b> Environment Agency - Head Office	April 2012	
<b>Substantiated Pollution Incident Register</b> Environment Agency - South East Region - Kent & South London Area Environment Agency - South East Region - North East Thames Area Environment Agency - Southern Region - Kent Area Environment Agency - Southern Region - Kent and East Sussex Environment Agency - Thames Region - North East Area Environment Agency - Thames Region - South East Area	October 2022 October 2022 October 2022 October 2022 October 2022 October 2022	Quarterly Quarterly Quarterly Quarterly Quarterly Quarterly
<b>Water Abstractions</b> Environment Agency - Southern Region Environment Agency - Thames Region	October 2022 October 2022	Quarterly Quarterly
<b>Water Industry Act Referrals</b> Environment Agency - Southern Region Environment Agency - Thames Region	October 2017 October 2017	
<b>Groundwater Vulnerability Map</b> Environment Agency - Head Office	June 2018	As notified
<b>Groundwater Vulnerability - Soluble Rock Risk</b> Environment Agency - Head Office	June 2018	As notified
<b>Bedrock Aquifer Designations</b> Environment Agency - Head Office	January 2018	Annually
<b>Superficial Aquifer Designations</b> Environment Agency - Head Office	January 2018	Annually
<b>Source Protection Zones</b> Environment Agency - Head Office	September 2022	Bi-Annually
<b>Extreme Flooding from Rivers or Sea without Defences</b> Environment Agency - Head Office	August 2022	Quarterly
<b>Flooding from Rivers or Sea without Defences</b> Environment Agency - Head Office	August 2022	Quarterly
<b>Areas Benefiting from Flood Defences</b> Environment Agency - Head Office	August 2022	Quarterly
<b>Flood Water Storage Areas</b> Environment Agency - Head Office	August 2022	Quarterly
<b>Flood Defences</b> Environment Agency - Head Office	August 2022	Quarterly
<b>OS Water Network Lines</b> Ordnance Survey	October 2022	Quarterly
<b>BGS Groundwater Flooding Susceptibility</b> British Geological Survey - National Geoscience Information Service	May 2013	As notified











Waste	Version	Update Cycle
<b>BGS Recorded Landfill Sites</b> British Geological Survey - National Geoscience Information Service	November 2002	As notified
<b>Historical Landfill Sites</b> Environment Agency - Head Office	November 2022	Quarterly
<b>Integrated Pollution Control Registered Waste Sites</b> Environment Agency - Southern Region Environment Agency - Thames Region	January 2009 January 2009	Not Applicable Not Applicable
<b>Licensed Waste Management Facilities (Landfill Boundaries)</b> Environment Agency - South East Region - Kent & South London Area Environment Agency - South East Region - North East Thames Area Environment Agency - Southern Region - Kent Area Environment Agency - Southern Region - Kent and East Sussex Environment Agency - Thames Region - North East Area Environment Agency - Thames Region - South East Area	October 2022 October 2022 October 2022 October 2022 October 2022 October 2022	Quarterly Quarterly Quarterly Quarterly Quarterly Quarterly
<b>Licensed Waste Management Facilities (Locations)</b> Environment Agency - South East Region - Kent & South London Area Environment Agency - South East Region - North East Thames Area Environment Agency - Southern Region - Kent Area Environment Agency - Southern Region - Kent and East Sussex Environment Agency - Thames Region - North East Area Environment Agency - Thames Region - South East Area	July 2022 July 2022 July 2022 July 2022 July 2022 July 2022	Quarterly Quarterly Quarterly Quarterly Quarterly Quarterly
<b>Local Authority Landfill Coverage</b> Dartford Borough Council - Environmental Health Department Kent County Council - Waste Management Group London Borough of Barking And Dagenham - Environmental Health Department London Borough of Bexley - Environmental Health Department London Borough of Bromley - Environmental Health Department London Borough of Greenwich - Environmental Health Department London Borough of Lewisham - Environmental Health Department London Borough of Newham	February 2003 February 2003 February 2003 February 2003 February 2003 February 2003 February 2003 February 2003	Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable
<b>Local Authority Recorded Landfill Sites</b> Dartford Borough Council - Environmental Health Department Kent County Council - Waste Management Group London Borough of Barking And Dagenham - Environmental Health Department London Borough of Bexley - Environmental Health Department London Borough of Bromley - Environmental Health Department London Borough of Greenwich - Environmental Health Department London Borough of Lewisham - Environmental Health Department London Borough of Newham	October 2018 October 2018 October 2018 October 2018 October 2018 October 2018 October 2018 October 2018	
<b>Registered Landfill Sites</b> Environment Agency - Southern Region - Kent Area Environment Agency - Southern Region - Kent and East Sussex Environment Agency - Thames Region - North East Area Environment Agency - Thames Region - South East Area	March 2006 March 2006 March 2006 March 2006	Not Applicable Not Applicable Not Applicable Not Applicable
<b>Registered Waste Transfer Sites</b> Environment Agency - Southern Region - Kent Area Environment Agency - Southern Region - Kent and East Sussex Environment Agency - Thames Region - North East Area Environment Agency - Thames Region - South East Area	April 2018 April 2018 April 2018 April 2018	
<b>Registered Waste Treatment or Disposal Sites</b> Environment Agency - Southern Region - Kent Area Environment Agency - Southern Region - Kent and East Sussex Environment Agency - Thames Region - North East Area Environment Agency - Thames Region - South East Area	June 2015 June 2015 June 2015 June 2015	

Hazardous Substances	Version	Update Cycle
<b>Control of Major Accident Hazards Sites (COMAH)</b> Health and Safety Executive	January 2022	Bi-Annually
<b>Explosive Sites</b> Health and Safety Executive	March 2017	Annually
<b>Notification of Installations Handling Hazardous Substances (NIHHS)</b> Health and Safety Executive	August 2001	
<b>Planning Hazardous Substance Enforcements</b> London Borough of Lewisham - Planning Services London Borough of Barking And Dagenham London Borough of Bromley London Borough of Greenwich - Planning Department London Borough of Newham London Port Health Authority - Environmental Services Dartford Borough Council Kent County Council London Borough of Bexley - Development Control	April 2015 February 2016 February 2016 February 2016 February 2016 January 2008 January 2016 January 2016 January 2016	Variable Variable Variable Variable Variable Annual Rolling Update Variable Variable Variable
<b>Planning Hazardous Substance Consents</b> London Borough of Lewisham - Planning Services London Borough of Barking And Dagenham London Borough of Bromley London Borough of Greenwich - Planning Department London Borough of Newham London Port Health Authority - Environmental Services Dartford Borough Council Kent County Council London Borough of Bexley - Development Control	April 2015 February 2016 February 2016 February 2016 February 2016 January 2008 January 2016 January 2016 January 2016	Variable Variable Variable Variable Variable Annual Rolling Update Variable Variable Variable

Geological	Version	Update Cycle
<b>BGS 1:625,000 Solid Geology</b> British Geological Survey - National Geoscience Information Service	January 2009	As notified
<b>BGS Recorded Mineral Sites</b> British Geological Survey - National Geoscience Information Service	November 2022	Bi-Annually
<b>CBSCB Compensation District</b> Cheshire Brine Subsidence Compensation Board (CBSCB) Cheshire Brine Subsidence Compensation Board (CBSCB)	August 2011 November 2020	As notified
<b>Coal Mining Affected Areas</b> The Coal Authority - Property Searches	March 2014	Annual Rolling Update
<b>Mining Instability</b> Ove Arup & Partners	June 1998	Not Applicable
<b>Non Coal Mining Areas of Great Britain</b> British Geological Survey - National Geoscience Information Service	May 2015	Not Applicable
<b>Potential for Collapsible Ground Stability Hazards</b> British Geological Survey - National Geoscience Information Service	April 2020	As notified
<b>Potential for Compressible Ground Stability Hazards</b> British Geological Survey - National Geoscience Information Service	January 2019	As notified
<b>Potential for Ground Dissolution Stability Hazards</b> British Geological Survey - National Geoscience Information Service	January 2019	As notified
<b>Potential for Landslide Ground Stability Hazards</b> British Geological Survey - National Geoscience Information Service	January 2019	As notified
<b>Potential for Running Sand Ground Stability Hazards</b> British Geological Survey - National Geoscience Information Service	January 2019	As notified
<b>Potential for Shrinking or Swelling Clay Ground Stability Hazards</b> British Geological Survey - National Geoscience Information Service	January 2019	As notified
<b>Radon Potential - Radon Affected Areas</b> British Geological Survey - National Geoscience Information Service	September 2022	Annually
<b>Radon Potential - Radon Protection Measures</b> British Geological Survey - National Geoscience Information Service	September 2022	Annually
Industrial Land Use	Version	Update Cycle
<b>Contemporary Trade Directory Entries</b> Thomson Directories	October 2022	Quarterly
<b>Fuel Station Entries</b> Catalist Ltd - Experian	January 2023	Quarterly
<b>Gas Pipelines</b> National Grid	October 2021	Bi-Annually
<b>Underground Electrical Cables</b> National Grid	May 2021	Bi-Annually

Sensitive Land Use	Version	Update Cycle
<b>Ancient Woodland</b> Natural England	February 2021	Bi-Annually
<b>Areas of Adopted Green Belt</b> Dartford Borough Council London Borough of Barking And Dagenham London Borough of Bexley - Development Control London Borough of Bromley London Borough of Greenwich London Borough of Lewisham London Borough of Newham	July 2022 July 2022 July 2022 July 2022 July 2022 July 2022 July 2022	Quarterly Quarterly Quarterly Quarterly Quarterly Quarterly Quarterly
<b>Areas of Unadopted Green Belt</b> Dartford Borough Council London Borough of Barking And Dagenham London Borough of Bexley - Development Control London Borough of Bromley London Borough of Greenwich London Borough of Lewisham London Borough of Newham	July 2022 July 2022 July 2022 July 2022 July 2022 July 2022 July 2022	Quarterly Quarterly Quarterly Quarterly Quarterly Quarterly Quarterly
<b>Areas of Outstanding Natural Beauty</b> Natural England	August 2022	Bi-Annually
<b>Environmentally Sensitive Areas</b> Natural England	January 2017	
<b>Forest Parks</b> Forestry Commission	April 1997	Not Applicable
<b>Local Nature Reserves</b> Natural England	February 2021	Bi-Annually
<b>Marine Nature Reserves</b> Natural England	July 2019	Bi-Annually
<b>National Nature Reserves</b> Natural England	January 2021	Bi-Annually
<b>National Parks</b> Natural England	February 2018	Bi-Annually
<b>Nitrate Sensitive Areas</b> Natural England	April 2016	Not Applicable
<b>Nitrate Vulnerable Zones</b> Department for Environment, Food and Rural Affairs (DEFRA - formerly FRCA) Environment Agency - Head Office	April 2016 June 2017	Bi-Annually
<b>Ramsar Sites</b> Natural England	August 2020	Bi-Annually
<b>Sites of Special Scientific Interest</b> Natural England	February 2021	Bi-Annually
<b>Special Areas of Conservation</b> Natural England	July 2020	Bi-Annually
<b>Special Protection Areas</b> Natural England	February 2021	Bi-Annually

A selection of organisations who provide data within this report

Data Supplier	Data Supplier Logo
Ordnance Survey	
Environment Agency	
Scottish Environment Protection Agency	
The Coal Authority	
British Geological Survey	 <b>British Geological Survey</b> <small>NATURAL ENVIRONMENT RESEARCH COUNCIL</small>
Centre for Ecology and Hydrology	 <b>Centre for Ecology &amp; Hydrology</b> <small>NATURAL ENVIRONMENT RESEARCH COUNCIL</small>
Natural Resources Wales	
Scottish Natural Heritage	
Natural England	
Public Health England	
Ove Arup	
Stantec UK Ltd	

Contact	Name and Address	Contact Details
1	<b>British Geological Survey - Enquiry Service</b> British Geological Survey, Environmental Science Centre, Keyworth, Nottingham, Nottinghamshire, NG12 5GG	Telephone: 0115 936 3143 Fax: 0115 936 3276 Email: enquiries@bgs.ac.uk Website: www.bgs.ac.uk
2	<b>London Borough of Bexley - Environmental Health Department</b> 2a Hadlow Road, Sidcup, Kent, DA14 4AF	Telephone: 020 8303 7777 Fax: 020 8308 4897 Website: www.bexley.gov.uk
3	<b>Environment Agency - National Customer Contact Centre (NCCC)</b> PO Box 544, Templeborough, Rotherham, S60 1BY	Telephone: 03708 506 506 Email: enquiries@environment-agency.gov.uk
4	<b>Environment Agency - Head Office</b> Rio House, Waterside Drive, Aztec West, Almondsbury, Bristol, Avon, BS32 4UD	Telephone: 01454 624400 Fax: 01454 624409
5	<b>Ordnance Survey</b> Adanac Drive, Southampton, Hampshire, SO16 0AS	Telephone: 03456 05 05 05 Email: customerservices@ordnancesurvey.co.uk Website: www.ordnancesurvey.gov.uk
6	<b>London Borough of Greenwich - Environmental Health Department</b> 12th Floor, Riverside House, Woolwich, London, SE18 6DN	Telephone: 020 8854 8888 Fax: 020 8921 8322 Website: www.greenwich.gov.uk
7	<b>Landmark Information Group Limited</b> Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0844 844 9966 Fax: 0844 844 9951 Email: helpdesk@landmark.co.uk Website: www.landmark.co.uk
8	<b>Natural England</b> County Hall, Spetchley Road, Worcester, WR5 2NP	Telephone: 0300 060 3900 Email: enquiries@naturalengland.org.uk Website: www.naturalengland.org.uk
-	<b>Public Health England - Radon Survey, Centre for Radiation, Chemical and Environmental Hazards</b> Chilton, Didcot, Oxfordshire, OX11 0RQ	Telephone: 01235 822622 Fax: 01235 833891 Email: radon@phe.gov.uk Website: www.ukradon.org
-	<b>Landmark Information Group Limited</b> Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0844 844 9952 Fax: 0844 844 9951 Email: customerservices@landmarkinfo.co.uk Website: www.landmarkinfo.co.uk

Please note that the Environment Agency / Natural Resources Wales / SEPA have a charging policy in place for enquiries.



**APPENDIX B  
PHOTOGRAPHS**



The Site 14<sup>th</sup> January 2023 viewed east top and south east bottom





The Site 14<sup>th</sup> January 2023 viewed west top and south east bottom





The Site 14<sup>th</sup> January 2023 viewed south west top and west bottom

