

NEW TIMBER FRAMED WINDOW UNITS TO MATCH PREVIOUSLY RESTORED, SECURED AND SAVED FROM DETERIORATION FOLLOWING STORM DAMAGE

SURROUNDING STONEWORK REPAIRED TO MATCH EXG INC. FINISH + JOINTING.

