

## Homecheck Environmental



### Contamination Risk **PASSED**

#### Professional Opinion

Argyll Environmental Consultants have passed this report in accordance with the definition of contaminated land within Part 2A of the Environmental Protection Act 1990. Please refer to the Professional Opinion page and Section 1 for further information.



### Flood Risk: None Identified

Refer to Section 2 for further information

#### Conveyancer Guidance

While this report may have identified areas at risk of flooding within 250m of the search centre, we consider there to be no significant risk of flooding to the property. Please refer to Section 2 for further information.



### Radon: IDENTIFIED

Refer to Section 3 for further information



### Ground Stability: IDENTIFIED

Refer to Section 4 for further information



### Other Influential Factors:

Refer to Section 5 for further information

**Environmental Constraints: None Identified**

**See Section 5a**

Report issued for the property at  
**Messrs Wm Woods Exors Ltd, Wm  
Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND  
HX4 8AA**

Report Reference  
**331313424\_1\_1**

National Grid Reference  
**409720 421170**

Customer Reference  
**1510\_HCP**

Report Date  
**15 January 2024**

#### Contact Details

If you require assistance please contact your Search Provider or phone Customer Services on 0844 844 9966 or email [helpdesk@homecheck.co.uk](mailto:helpdesk@homecheck.co.uk)

#### Landmark Contribution

By purchasing this report, the recipient may be eligible for Remediation Contribution of up to £100,000 if served with a Remediation Notice by the Local Authority. Such a notice may require the homeowner to pay for all, or contribute to, the remediation of the property. For more information see Landmark's Terms and Conditions.



## Professional Opinion

Contamination Risk

# PASSED

In the professional opinion of Argyll Environmental Consultants, following a review of additional information, the level of contamination risk in respect of the Homecheck Professional report dated 15th January 2024 and reference 331313424\_1\_1, 1510\_HCP for

**Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited**  
**Lambert Street**  
**West Vale**  
**ELLAND**  
**HX4 8AA**

1) is unlikely that the property would be designated "contaminated land" within the meaning of Part 2A of the Environmental Protection Act 1990.

2) is unlikely to have an adverse effect on the security of the property for normal lending purposes.

The professional opinion refers to Section 1 of this report and should always be read in conjunction with the full text of that report. No physical site inspection or survey has been carried out or is proposed.

Approved by

**Argyll Environmental Ltd**



## Contents and Summary of Findings



### Site Location



### Section 1: Contamination Risk Findings

Contamination Risk	0-25m	25-250m	250-500m	See Section
<b>Designated Contaminated Land</b>	No	No	No	1a
<b>Landfill and Waste</b>	No	No	<b>Yes</b>	1b
<b>Potentially Contaminative Activities</b>	No	<b>Yes</b>	<b>Yes</b>	1c
<b>Known Pollution Incidents</b>	No	No	No	1d
<b>Other Potential Contaminative Land Uses</b>	<b>Yes</b>	<b>Yes</b>	n/a	1e



### Section 2: Flood Findings

Flood	0-25m	25-250m	See Section
<b>River Flooding</b>	No	<b>Yes</b>	2a
<b>Coastal Flooding</b>	No	No	2b
<b>Surface Water Flooding</b>	No	<b>Yes</b>	2c



### Section 3: Radon Findings

Radon	Result	See Section
<b>Radon Affected Property</b>	<b>Yes</b>	3



### Section 4: Ground Stability Findings

Ground Stability	Result	See Section
<b>Man-Made Factors</b>	<b>Yes</b>	4a
<b>Natural Factors</b>	No	4b



### Section 5: Other Influential Factors

Other Influential Factors	Result	See Section
<b>Environmental Constraints</b>	No	5a



## Site Location



## Aerial Photograph

The photograph below shows the location of the site to which this report relates.



### Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND, HX4 8AA


### Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
All rights reserved  
Date 15 January 2024  
Page 2 of 29



# Location Map

The map below shows the location of the site to which this report relates.



## Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND, HX4 8AA

## Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
All rights reserved  
Date 15 January 2024  
Page 3 of 29




## Section 1: Contamination Risk Findings

The whole of section 1 deals with potential sources of contamination and provides the information by which this report has either been passed or referred for assessment.



### Section 1a and 1b: Information Map

The map detailed below shows the location of the Designated Contaminated Land and Landfill and Waste features highlighted within sections 1a and 1b of this report.



Contains Ordnance Survey data © Crown copyright and database right 2024

#### Section 1a

- Contaminated Land Registry Entries and Notices

#### Section 1b

- Registered Landfill Sites
- Registered Landfills (Potential Buffer)
- BGS Recorded Landfill Sites
- Local Authority Recorded Landfill Sites
- Historical Landfill Sites

- Permitted Waste Sites - Authorised Landfill Site Boundaries
- Environmental Permitting Regulations - Waste
- Integrated Pollution Control Registered Waste Sites
- Registered Waste Treatment or Disposal Sites
- Registered Waste Transfer Sites

#### Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND, HX4 8AA

#### Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
All rights reserved  
Date 15 January 2024  
Page 4 of 29

## Section 1a: Designated Contaminated Land

The data within this section tells you whether your property or surrounding area has been identified by the Local Authority as "Contaminated Land" under the Environmental Protection Act 1990. Should there be an indication of contamination, it is not necessarily a cause for concern. Your report will be assessed by our professional environmental consultants who will advise you what, if any, considerations need to be made should you proceed with the property purchase.

Enquiry	Result
Has any contaminated land been identified within 500m of the property?	No

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

### Contaminated Land Register Entries and Notices

No factors identified for this property

## Section 1b: Landfill and Waste

The information in this section is telling you about active and historic landfill and waste sites within 500 metres of the property. Having a landfill or waste site near your property does not necessarily mean that you or the property will be affected. However, it is something you need to be aware of, because landfill and waste can have a detrimental effect on the surrounding environment, house value and health. A closed landfill/waste site should be given equal consideration to an active site, because of landfill by-products. For instance, landfill with lots of organic material can continue to produce odours and gas for many years.

Enquiry	Result
Have any landfill and waste sites been identified within 500m of the property?	Yes

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

### Registered Landfill Sites

1	<b>Name:</b> Longland Plant <b>Reference:</b> 459	Onecliffe Mill Greetland Halifax West Yorkshire	<b>Licence Status:</b> Licence lapsed/cancelled/ defunct/not applicable/surrenderedCancelled <b>Record Date:</b> 1st December 1984 <b>Site Category:</b> Landfill <b>Boundary Quality:</b> Not Applicable <b>Positional Accuracy:</b> Manually positioned to the road within the address or location	451m	1
2	<b>Name:</b> J Speak & Co Ltd <b>Reference:</b> 630	Ingwood Mills Greetland Halifax West Yorkshire	<b>Licence Status:</b> Licence lapsed/cancelled/ defunct/not applicable/surrenderedCancelled <b>Record Date:</b> 1st August 1987 <b>Site Category:</b> Landfill <b>Boundary Quality:</b> Not Applicable <b>Positional Accuracy:</b> Manually positioned to the address or location	483m	1

### BGS Recorded Landfill Sites

No factors identified for this property

### Local Authority Recorded Landfill Sites

No factors identified for this property

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

## Local Authority Recorded Landfill Coverage

The following list details the Local Authorities that cover the search area who have made landfill data available:

**Calderdale Metropolitan Borough Council** - Has supplied landfill data 2

For further information regarding the availability of Local Authority Recorded Landfill data you may wish to forward enquiries to one or more of the contacts indicated above.

## Historical Landfill Sites

3	<b>Name:</b> Woodside Lock <b>Reference:</b> EAHLD05854	West Vale, Halifax, West Yorkshire	<b>Specified Waste Type:</b> Not Supplied <b>Date of Issue:</b> 6th June 1991 <b>First Input Date:</b> Not Supplied <b>Last Input Date:</b> Not Supplied <b>Boundary Quality:</b> As Supplied <b>Positional Accuracy:</b> Positioned by the supplier	287m	1
4	<b>Name:</b> Onecliffe Mills <b>Reference:</b> EAHLD04093	Stainland Road, Bacup	<b>Specified Waste Type:</b> Deposited Waste included Inert, Industrial, Commercial and Household Waste <b>Date of Issue:</b> 11th December 1984 <b>First Input Date:</b> 31st July 1984 <b>Last Input Date:</b> 24th April 1991 <b>Boundary Quality:</b> As Supplied <b>Positional Accuracy:</b> Positioned by the supplier	332m	1
5	<b>Name:</b> Holly Mount <b>Reference:</b> EAHLD34969	Adjacent Bank Field Grange, Saddleworth Road, Greetland	<b>Specified Waste Type:</b> Not Supplied <b>Date of Issue:</b> Not Supplied <b>First Input Date:</b> Not Supplied <b>Last Input Date:</b> Not Supplied <b>Boundary Quality:</b> As Supplied <b>Positional Accuracy:</b> Positioned by the supplier	347m	1
6	<b>Name:</b> Ingwood Mills <b>Reference:</b> EAHLD04092	Stainland Road, West Vale, Greetland	<b>Specified Waste Type:</b> Deposited Waste included Inert and Commercial Waste <b>Date of Issue:</b> 21st January 1985 <b>First Input Date:</b> 31st January 1985 <b>Last Input Date:</b> 28th July 1987 <b>Boundary Quality:</b> As Supplied <b>Positional Accuracy:</b> Positioned by the supplier	475m	1
7	<b>Name:</b> Ingwood Mills <b>Reference:</b> EAHLD04091	Stainland Road, Greetland	<b>Specified Waste Type:</b> Deposited Waste included Inert and Commercial Waste <b>Date of Issue:</b> 14th August 1987 <b>First Input Date:</b> 31st August 1987 <b>Last Input Date:</b> 18th June 1990 <b>Boundary Quality:</b> As Supplied <b>Positional Accuracy:</b> Positioned by the supplier	475m	1

## Permitted Waste Sites - Authorised Landfill Site Boundaries

No factors identified for this property

## Environmental Permitting Regulations - Waste

8	<b>Reference:</b> 60761	Land/ Premises At Calder Street West Vale Halifax West Yorkshire HX4 8AQ	<b>Licensed Waste Type:</b> Household, Commercial and Industrial transfer stations <b>Operator Name:</b> C Heath & Son <b>Status:</b> Issued <b>Date of issue:</b> 6th June 1991 <b>Positional Accuracy:</b> Located by supplier to within 10m	287m	1
---	-------------------------	--	--	------	---

## Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND, HX4 8AA

## Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
All rights reserved  
Date 15 January 2024  
Page 6 of 29



Map ID	Reference	Location	Details	Distance	Contact
9	<b>Reference:</b> 60775	Brook Mills Saddleworth Road Greenland Halifax West Yorkshire HX4 8LZ	<b>Licensed Waste Type:</b> Metal recycling sites (vehicle dismantlers) <b>Operator Name:</b> Hulme James Rodney <b>Status:</b> Expired <b>Date of issue:</b> 10th June 1993 <b>Positional Accuracy:</b> Located by supplier to within 10m	467m	1

### Integrated Pollution Control Registered Waste Sites

No factors identified for this property

### Registered Waste Treatment or Disposal Sites

10	<b>Name:</b> J R Hulme <b>Reference:</b> 1325	Brook Mills Saddleworth Road Greetland Halifax West Yorkshire	<b>Site Category:</b> Scrapyard <b>Licence Status:</b> Operational as far as is knownOperational <b>Record Date:</b> 1st June 1993 <b>Max Input Rate:</b> Very Small (Less than 10,000 tonnes per year) <b>Boundary Quality:</b> Not Supplied <b>Positional Accuracy:</b> Manually positioned to the address or location	466m	1
----	--	---	---	------	---

### Registered Waste Transfer Sites


11	<b>Name:</b> C Heath & Son <b>Reference:</b> 939	Solar Works Calder Street West Vale Halifax West Yorkshire Hx4 8ha	<b>Site Category:</b> Transfer <b>Licence Status:</b> Operational as far as is knownOperational <b>Record Date:</b> 1st June 1991 <b>Boundary Quality:</b> Not Supplied <b>Positional Accuracy:</b> Manually positioned to the address or location	266m	1
12	<b>Name:</b> Joseph Redford Ltd <b>Reference:</b> 351	Hollyns Warehouse Greetland Halifax West Yorkshire	<b>Site Category:</b> Transfer <b>Licence Status:</b> Licence lapsed/cancelled/defunct/not applicable/surrenderedCancelled <b>Record Date:</b> 17th January 1983 <b>Boundary Quality:</b> Not Supplied <b>Positional Accuracy:</b> Approximate location provided by supplier	313m	1

### Next Steps

If you would like any further information in respect of the above findings we recommend that you get in touch with those listed in the 'Useful Contacts' section. Each contact reference shown in the above table relates to detailed contact information contained near the back of this report. Further information is also available in the 'Useful Information' section.

# Section 1c and 1d: Information Map

The map detailed below shows the location of the Potentially Contaminative Activities and Known Pollution Incidents features highlighted within sections 1c and 1d of this report.



Contains Ordnance Survey data © Crown copyright and database right 2024

### Section 1c

- ▲ Local Authority Pollution Prevention and Controls
- ▼ Local Authority Integrated Pollution Prevention and Control
- ▲ Integrated Pollution Controls
- ▶ Environmental Permitting Regulations - Industry
- ◆ Consent to Discharge to Controlled Waters
- ✕ Radioactive Substances Register
- ✕ Planning Hazardous Substance Consents
- ✕ Control of Major Accident Hazards Sites (COMAH)
- ✕ Notification of Installations Handling Hazardous Substances (NIHHS)
- ★ Explosive Sites

### Section 1d

- + Local Authority Pollution Prevention and Control Enforcements
- + Enforcement and Prohibition Notices
- + Planning Hazardous Substance Enforcements
- Prosecutions Relating to Authorised Processes
- Environmental Pollution Incidents
- Prosecutions Relating to Controlled Waters

## Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
 Lambert Street  
 West Vale  
 ELLAND, HX4 8AA

## Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
 All rights reserved  
 Date 15 January 2024  
 Page 8 of 29

## Section 1c: Potentially Contaminative Activities

This section describes current and historic licensed activities within 500 metres of the property, which have the potential to cause contamination or have an impact on the environment. The licensed activities could range from pollution to air, land or water; storage or disposal of radioactive substances; or storage of hazardous or explosive materials. Licences may no longer be active, but the nature of the past activity means it could still have an impact.

Enquiry	Result
Have any potentially contaminative activities been identified within 500m of the property?	Yes

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

### Local Authority Pollution Prevention and Controls

13	<b>Name:</b> Hebble Concrete Co <b>Reference:</b> Not Given	Bandwalk Industrial Walk Saddleworth Road Greetland HALIFAX West Yorkshire HX	<b>Description:</b> PG3/1Blending, packing, loading and use of bulk cement  <b>Status:</b> Authorisation revoked  <b>Date of Issue:</b> Not Supplied  <b>Positional Accuracy:</b> Manually positioned to the road within the address or location	181m	2
14	<b>Name:</b> D Bottomley Ltd <b>Reference:</b> 16	Saddleworth Road Greetland Halifax HX4 8LZ	<b>Description:</b> PG1/1Waste oil burners, less than 0.4MW net rated thermal input  <b>Status:</b> Permitted  <b>Date of Issue:</b> 1st February 2004  <b>Positional Accuracy:</b> Manually positioned to the address or location	435m	2

### Local Authority Integrated Pollution Prevention And Control

No factors identified for this property

### Integrated Pollution Controls

No factors identified for this property

### Environmental Permitting Regulations - Industry

No factors identified for this property

### Consent to Discharge to Controlled Waters

15	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Wra9266	Brow Bridge Cso Brow Bridge Off Stainland Rd Greetland Halifax West Yorkshire Hx4 8al	<b>Type:</b> Sewage Discharge  <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company  <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY)  <b>Discharge Environment Type:</b> Freshwater Stream/River  <b>Receiving Water:</b> Black Brook  <b>Status:</b> Varied under EPR 2010  <b>Date of Issue:</b> 26th February 2018  <b>Positional Accuracy:</b> Located by supplier to within 10m	129m	1
----	--	--	---	------	---

Map ID	Reference	Location	Details	Distance	Contact
16	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Wra9266	Brow Bridge Cso Brow Bridge Off Stainland Rd Greetland Halifax West Yorkshire Hx4 8al	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> New Consent (Water Resources Act 1991, Section 88 & Schedule 10 as amended by Environment Act 1995) <b>Date of Issue:</b> 4th September 2007 <b>Positional Accuracy:</b> Located by supplier to within 10m	131m	1
17	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Eprup3320ge	Hoyles Memorial Gardens Cso Rochdale Road West Vale Halifax West Yorkshire Hx4 8al	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> New issued under EPR 2010 <b>Date of Issue:</b> 22nd March 2016 <b>Positional Accuracy:</b> Located by supplier to within 10m	136m	1
18	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Eprup3320ge	Hoyles Memorial Gardens Cso Rochdale Road West Vale Halifax West Yorkshire Hx4 8al	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> Varied under EPR 2010 <b>Date of Issue:</b> 26th October 2017 <b>Positional Accuracy:</b> Located by supplier to within 10m	136m	1
19	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Wra8442	Rochdale Road Cso Rochdale Road Opp Foxbridge Hse Greetland Halifax West Yorkshire Hx4 8ef	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> Varied under EPR 2010 <b>Date of Issue:</b> 26th March 2018 <b>Positional Accuracy:</b> Located by supplier to within 10m	153m	1



Map ID	Reference	Location	Details	Distance	Contact
20	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Wra8440	Hoults Lane Cso Road End Junction Hoults Lane Rear Of 2 Hoults Lane Greetland Halifax West Yorkshire Hx4 8hn	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> Varied under EPR 2010 <b>Date of Issue:</b> 19th March 2018 <b>Positional Accuracy:</b> Located by supplier to within 10m	153m	1
21	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Wra8440	Hoults Lane Cso Road End Junction Hoults Lane Rear Of 2 Hoults Lane Greetland Halifax West Yorkshire Hx4 8hn	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> New Consent (Water Resources Act 1991, Section 88 & Schedule 10 as amended by Environment Act 1995) <b>Date of Issue:</b> 16th March 2005 <b>Positional Accuracy:</b> Located by supplier to within 10m	153m	1
22	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Wra8442	Rochdale Road Cso Rochdale Road Opp Foxbridge Hse Greetland Halifax West Yorkshire Hx4 8ef	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> New Consent (Water Resources Act 1991, Section 88 & Schedule 10 as amended by Environment Act 1995) <b>Date of Issue:</b> 16th March 2005 <b>Positional Accuracy:</b> Located by supplier to within 10m	154m	1
23	<b>Name:</b> North Dean Automotive Ltd <b>Reference:</b> 2003	North Dean Garage Stainland Road Greetland Halifax West Yorkshire Hx4 8ls	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Final/Treated Effluent - Not Water Company <b>Property Type:</b> Undefined Or Other <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> Transferred from Rivers (Prevention of Pollution) Act 1951-1961 <b>Date of Issue:</b> 12th November 1965 <b>Positional Accuracy:</b> Located by supplier to within 100m	188m	1

Map ID	Reference	Location	Details	Distance	Contact
24	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> Eprsb3590wc	West Vale Cso Saddleworth Greetland Halifax West Yorkshire Hx4 8ba	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Black Brook <b>Status:</b> Varied under EPR 2010 <b>Date of Issue:</b> 23rd September 2020 <b>Positional Accuracy:</b> Located by supplier to within 10m	296m	1
25	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> 3112	West Vale Stainland Elland West Yorkshire	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> River Calder <b>Status:</b> Transferred from Rivers (Prevention of Pollution) Act 1951-1961 <b>Date of Issue:</b> 30th September 1975 <b>Positional Accuracy:</b> Located by supplier to within 10m	296m	1
26	<b>Name:</b> Yorkshire Water Services Limited <b>Reference:</b> 2515	Yws Unknown Sites Default	<b>Type:</b> Sewage Discharge <b>Discharge Type:</b> Sewage Discharges - Stw Storm Overflow/Storm Tank - Water Company <b>Property Type:</b> STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) <b>Discharge Environment Type:</b> Freshwater Stream/River <b>Receiving Water:</b> Calder And Tribs <b>Status:</b> Transferred from Rivers (Prevention of Pollution) Act 1951-1961 <b>Date of Issue:</b> 13th June 1969 <b>Positional Accuracy:</b> Located by supplier to within 10m	301m	1

### Radioactive Substances Register

No factors identified for this property

### Planning Hazardous Substance Consents

No factors identified for this property

### Control of Major Accident Hazards Sites (COMAH)

No factors identified for this property

### Notification of Installations Handling Hazardous Substances (NIHHS)

No factors identified for this property

### Explosive Sites

No factors identified for this property

### Next Steps

If you would like any further information in respect of the above findings we recommend that you contact the relevant Local Authority or the Environment Agency/Natural Resources Wales, their contact details can be found in the 'Useful Contacts' section of this report. Further Information is also available in the 'Useful Information' section.

### Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND, HX4 8AA

### Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
All rights reserved  
Date 15 January 2024  
Page 12 of 29

## Section 1d: Known Pollution Incidents

The data within this section describes unpermitted activity in your area (e.g. polluting incidents, or exceedance of permitted allowance) where the activity led to a prosecution or enforcement of regulations. Whilst all of these records are historic, the nature of the incident may have long term effects.

Enquiry	Result
Have any known pollution incidents been identified within 500m of the property?	No

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

### Local Authority Pollution Prevention and Control Enforcements

No factors identified for this property

### Enforcement and Prohibition Notices

No factors identified for this property

### Planning Hazardous Substance Enforcements

No factors identified for this property

### Prosecutions Relating to Authorised Processes

No factors identified for this property

### Environmental Pollution Incidents

No factors identified for this property


### Prosecutions Relating to Controlled Waters

No factors identified for this property



## Section 1e: Information Map

The map detailed below shows the location of the Other Potential Contaminative Land Uses features highlighted within section 1e of this report.



Contains Ordnance Survey data © Crown copyright and database right 2024

- |  |   |
|--|---|
| ✕ Fuel Station Entries                   | 🟩▲ Potentially Infilled Land (Non-Water)                    |
| ★ Contemporary Trade Directories         | 🟦▲ Potentially Infilled Land (Water)                        |
| ⊕ Former Marshes                         | 🟪 Potentially Contaminative Industrial Uses (Past Land Use) |
| ▼ Historical Tanks and Energy Facilities |   |



## Section 1e: Other Potential Contaminative Land Uses

This section describes either current or historic activity, which could be considered to be contaminative. This section makes no statement about whether the activity requires a licence; however our environmental experts deem that the activities described in this section could lead to potential contamination. The information is taken from a variety of sources including trade directories, Landmark's extensive historical map collection and analysis of historic activity. Records are highlighted due to the potential for contamination to exist.

Enquiry	Result
Have any other potential sources of contamination been identified within 250m of the property?	Yes

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

### Fuel Station Entries

No factors identified for this property

### Contemporary Trade Directory Entries

27	<b>Name:</b> The Engineerium Ltd	Lambert Street Greetland Halifax West Yorkshire HX4 8AA	<b>Classification:</b> Engineers - General <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	12m	-
28	<b>Name:</b> Lambert Street Garage	Lambert Street Greetland Halifax HX4 8AA	<b>Classification:</b> Garage Services <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	19m	-
29	<b>Name:</b> Marron Design	7-9 Maude Street Greetland Halifax West Yorkshire HX4 8AJ	<b>Classification:</b> Clothing & Fabrics - Manufacturers <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	21m	-
30	<b>Name:</b> Hebble Concrete Co	Saddleworth Road Greetland Halifax West Yorkshire HX4 8AG	<b>Classification:</b> Concrete Products <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	46m	-
31	<b>Name:</b> Car Scraping Scrap Yards In Halifax	West Vale Civic Hall Rochdale Road Greetland Halifax HX4 8AH	<b>Classification:</b> Car Breakers & Dismantlers <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	70m	-
32	<b>Name:</b> Clean World	72-74 Saddleworth Road Greetland Halifax West Yorkshire HX4 8AG	<b>Classification:</b> Dry Cleaners <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	81m	-
33	<b>Name:</b> Smith Construction Services	25 Saddleworth Road Greetland Halifax West Yorkshire HX4 8AG	<b>Classification:</b> Joinery Manufacturers <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	84m	-
34	<b>Name:</b> Andy Thornton Ltd	Victoria Mills Stainland Road Greetland Halifax West Yorkshire HX4 8AD	<b>Classification:</b> Reclamation Centres <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	109m	-

Map ID	Reference	Location	Details	Distance	Contact
35	<b>Name:</b> Barry Smithies	Rochdale Rd Greetland Halifax West Yorkshire HX4 8LJ	<b>Classification:</b> Car Dealers - Used <b>Status:</b> Inactive <b>Positional Accuracy:</b> Manually positioned to the road within the address or location	110m	-
36	<b>Name:</b> Express Office Solutions	9 North Street Greetland Halifax HX4 8DQ	<b>Classification:</b> Office Furniture & Equipment <b>Status:</b> Active <b>Positional Accuracy:</b> Automatically positioned to the address	129m	-
36	<b>Name:</b> Carroll Cleaning Company Ltd	Spring Hey Mill,1 North Street Greetland Halifax West Yorkshire HX4 8DQ	<b>Classification:</b> Commercial Cleaning Services <b>Status:</b> Active <b>Positional Accuracy:</b> Manually positioned to the address or location	129m	-
37	<b>Name:</b> G B R S Ltd Within St Johns Church	Calder Street Greetland Halifax West Yorkshire HX4 8AQ	<b>Classification:</b> Clocks & Watches - Manufacturers & Wholesalers <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	132m	-
37	<b>Name:</b> Watches R Us	St. Johns Calder Street Greetland Halifax West Yorkshire HX4 8AQ	<b>Classification:</b> Clocks & Watches - Manufacturers & Wholesalers <b>Status:</b> Inactive <b>Positional Accuracy:</b> Manually positioned to the address or location	132m	-
37	<b>Name:</b> Tik Tik	St. Johns Calder Street Greetland Halifax West Yorkshire HX4 8AQ	<b>Classification:</b> Clocks & Watches - Manufacturers & Wholesalers <b>Status:</b> Inactive <b>Positional Accuracy:</b> Manually positioned to the address or location	132m	-
38	<b>Name:</b> Whitaker Electrical Ltd	6 Garwick Terrace Greetland Halifax HX4 8DA	<b>Classification:</b> Electrical Engineers <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	138m	-
39	<b>Name:</b> Carpets & Rugs @ 47	47 Stainland Road Greetland Halifax West Yorkshire HX4 8BD	<b>Classification:</b> Carpets & Rugs - Manufacturers <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	152m	-
40	<b>Name:</b> Brow Bridge Garage	16 Rochdale Road Greetland Halifax HX4 8AL	<b>Classification:</b> Garage Services <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	158m	-
40	<b>Name:</b> Brow Bridge Garage	16 Rochdale Road Greetland Halifax West Yorkshire HX4 8AL	<b>Classification:</b> Garage Services <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	158m	-
40	<b>Name:</b> North Dean Automotive Ltd	Stainland Road Greetland Halifax West Yorkshire HX4 8LS	<b>Classification:</b> Car Body Repairs <b>Status:</b> Active <b>Positional Accuracy:</b> Automatically positioned to the address	158m	-
41	<b>Name:</b> Sheard Security Ltd	Calder Street Greetland Halifax West Yorkshire HX4 8AQ	<b>Classification:</b> Boxes & Cartons <b>Status:</b> Active <b>Positional Accuracy:</b> Manually positioned to the address or location	167m	-

Map ID	Reference	Location	Details	Distance	Contact
42	<b>Name:</b> West Vale Laundry Services	55 Stainland Road Greetland Halifax West Yorkshire HX4 8BD	<b>Classification:</b> Laundries & Launderettes <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	167m	-
41	<b>Name:</b> Bag It Up Ltd	3a Calder Street Greetland Halifax West Yorkshire HX4 8AQ	<b>Classification:</b> Recycling Centres <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	168m	-
43	<b>Name:</b> Habitat Unique Ltd	The Long Mill Rochdale Road Greetland Halifax HX4 8AL	<b>Classification:</b> Lighting Manufacturers <b>Status:</b> Active <b>Positional Accuracy:</b> Automatically positioned to the address	179m	-
44	<b>Name:</b> Marshall Gas Services Ltd	61a Stainland Road Greetland Halifax West Yorkshire HX4 8BD	<b>Classification:</b> Boilers - Servicing, Replacements & Repairs <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	180m	-
45	<b>Name:</b> D Pitchforth Ltd	Park Garage Rochdale Road Greetland Halifax West Yorkshire HX4 8AL	<b>Classification:</b> Garage Services <b>Status:</b> Active <b>Positional Accuracy:</b> Automatically positioned to the address	181m	-
45	<b>Name:</b> Park Garage	Park Garage Rochdale Road Greetland Halifax HX4 8AL	<b>Classification:</b> Garage Services <b>Status:</b> Active <b>Positional Accuracy:</b> Automatically positioned to the address	182m	-
45	<b>Name:</b> Park Garage	Park Garage Rochdale Road Greetland Halifax HX4 8AL	<b>Classification:</b> Garage Services <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	182m	-
44	<b>Name:</b> Marshall Gas Services Ltd	West Vale Chambers 61 Stainland Road Greetland Halifax West Yorkshire HX4 8BD	<b>Classification:</b> Boilers - Servicing, Replacements & Repairs <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	182m	-
46	<b>Name:</b> Prospect Furniture Ltd	Prospect Mills Alfred Street Greetland Halifax West Yorkshire HX4 8LT	<b>Classification:</b> Office Furniture & Equipment <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	189m	-
47	<b>Name:</b> E Binns & Sons Ltd	63-69 Stainland Road Greetland Halifax West Yorkshire HX4 8BD	<b>Classification:</b> Engineers - General <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	193m	-
48	<b>Name:</b> Greetlands & District Trading Society Ltd	Victoria Street Greetland Halifax West Yorkshire HX4 8DF	<b>Classification:</b> Pet Foods & Animal Feeds <b>Status:</b> Inactive <b>Positional Accuracy:</b> Automatically positioned to the address	229m	-

## Former Marshes

No factors identified for this property

## Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND, HX4 8AA

## Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
All rights reserved  
Date 15 January 2024  
Page 17 of 29

Map ID	Reference	Location	Details	Distance	Contact
<b>Potentially Infilled Land (Non-Water)</b>					
49	Not Supplied	Not Supplied	Unknown Filled Ground (Pit, quarry etc) <b>Map Published Date:</b> 1983	148m	-
<b>Potentially Infilled Land (Water)</b>					
50	Not Supplied	Not Supplied	Unknown Filled Ground (Pond, marsh, river, stream, dock etc) <b>Map Published Date:</b> 1956	216m	-
<b>Potentially Contaminative Industrial Uses (Past Land Use)</b>					
51	Not Supplied	Not Supplied	<b>Class:</b> Factory or works - use not specified <b>Map Published Date:</b> 1895 - 1983	86m	-
52	Not Supplied	Not Supplied	<b>Class:</b> Factory or works - use not specified <b>Map Published Date:</b> 1895	94m	-
53	Not Supplied	Not Supplied	<b>Class:</b> General quarrying <b>Map Published Date:</b> 1895	148m	-
54	Not Supplied	Not Supplied	<b>Class:</b> Factory or works - use not specified <b>Map Published Date:</b> 1895 - 1908	148m	-
55	Not Supplied	Not Supplied	<b>Class:</b> Factory or works - use not specified <b>Map Published Date:</b> 1983	178m	-
56	Not Supplied	Not Supplied	<b>Class:</b> Factory or works - use not specified <b>Map Published Date:</b> 1895 - 1983	187m	-
57	Not Supplied	Not Supplied	<b>Class:</b> Sewage <b>Map Published Date:</b> 1908 - 1983	191m	-
58	Not Supplied	Not Supplied	<b>Class:</b> Machinery: engines, building and general industrial [manufacture] <b>Map Published Date:</b> 1938 - 1956	213m	-
<b>Historical Tanks And Energy Facilities</b>					
59	Not Supplied	Not Supplied	<b>Type:</b> Potential Tanks <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1989	19m	-
60	Not Supplied	Not Supplied	<b>Type:</b> Electrical Sub Station Facilities <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1989	129m	-
61	Not Supplied	Not Supplied	<b>Type:</b> Tanks <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1989	140m	-
62	Not Supplied	Not Supplied	<b>Type:</b> Potential Tanks <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1989	169m	-
63	Not Supplied	Not Supplied	<b>Type:</b> Potential Tanks <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1960	181m	-



Map ID	Reference	Location	Details	Distance	Contact
63	Not Supplied	Not Supplied	<b>Type:</b> Potential Tanks <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1989	181m	-
63	Not Supplied	Not Supplied	<b>Type:</b> Potential Tanks <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1961	182m	-
64	Not Supplied	Not Supplied	<b>Type:</b> Potential Tanks <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1989	202m	-
65	Not Supplied	Not Supplied	<b>Type:</b> Electrical Sub Station Facilities <b>Positional Accuracy:</b> Positioned to location of cartographic text <b>Date of Mapping:</b> 1989	241m	-

### Next Steps

If you would like any further information in respect of the above findings we recommend that you contact our Customer Services Team, whose details can be found in the 'Useful Contacts' section of this report. Further Information is also available in the 'Useful Information' section.




## Section 2: Flood Findings

The whole of this section deals with potential sources of flooding that may impact the property.




### Section 2a and 2b: River and Coastal Flood Map


The map detailed below shows the location of potential river and coastal flood risk. The potential risk has been modelled on the basis of an event occurring on average every 75, 200 or 1000 years.



#### River Flooding




#### Coastal Flooding






## Section 2c: Surface Water Flood Map

The map detailed below shows the location of potential surface water flood risk. The potential risk has been modelled on the basis of an event occurring on average every 75, 200 or 1000 years.



Contains Ordnance Survey data © Crown copyright and database right 2024

### Surface Water Flooding



#### Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND, HX4 8AA

#### Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
All rights reserved  
Date 15 January 2024  
Page 21 of 29

## Section 2a: River Flooding

River flooding mainly happens when the river catchment (that is the area of land that feeds water into the river and the streams that flow into the main river) receives greater than usual amounts of water (for example through rainfall or melting of snow). The amount of runoff depends on the soil type, catchment steepness, drainage characteristics, agriculture and urbanisation as well as the saturation of the catchment. The extra water causes the level of the water in the river to rise above its banks or retaining structures.

Enquiry	Result	Contact
Is there a potential risk of river flooding within 250m of the property?	Yes	-

## Section 2b: Coastal Flooding

Coastal flooding is the inundation of land areas along the coast caused by sea water rising above normal tidal conditions. Coastal flooding can arise from a combination of high tides, wind induced tidal surge, storm surge created by low pressure and wave action.

Enquiry	Result	Contact
Is there a potential risk of coastal flooding within 250m of the property?	No	-

## Section 2c: Surface Water Flooding

Surface water flooding results from rainfall running over ground before entering a watercourse or sewer. It is usually associated with high intensity rainfall events (typically greater than 30mm per hour) but can also occur with lower intensity rainfall or melting snow where the ground is already saturated, frozen, developed (for example in an urban setting) or otherwise has low permeability.

Enquiry	Result	Contact
Is there a potential risk of surface water flooding within 250m of the property?	Yes	-

### Next Steps

In order to gain more detailed information on the type and likelihood of your property being impacted by a flood event, and the potential impact on insurance, we recommend that you purchase our Landmark Flood Report.

If you would like more information please contact your Search Provider or our Customer Services Team on **0844 844 9966** or email [helpdesk@homecheck.co.uk](mailto:helpdesk@homecheck.co.uk).

Flood data provided by JBA Risk Management Limited. © Copyright JBA Risk Management Limited 2008-2024



## Section 3: Radon Findings

The information within this section tells you whether the property is located in a radon affected area. Radon is a radioactive gas which occurs naturally in rocks and soils. You cannot see, hear, feel or taste it. Exposure to particularly high levels of radon may increase the risk of developing lung cancer, and is therefore something you need to be aware of or should consider.

Enquiry	Result	Contact
<b>Is the property in a radon affected area?</b>	<b>The property is in a radon affected area, as between 3 and 5% of homes are above the action level</b>	3
<b>What level of radon protection measures for new dwellings or extensions to existing ones is required for the property?</b>	<b>Basic radon protective measures are necessary in the construction of new dwellings or extensions</b>	3

### Next Steps

The level of radon concentration can only be established by having the building tested. Action should be taken if the indoor radon level is measured and found to be above 200 becquerel's per cubic meter. If you would like any further information we recommend you contact Public Health England whose details can be found in the 'Useful Contacts' section of this report.

### Further Action

Airtech Environmental Systems can advise on radon testing kits, which cost £39.36 including VAT and can run from 7 days to 3 months. They also have a team of surveyors on hand to provide recommendations and advice for any properties above the target level of 100 becquerel's per cubic meter or action level of 200 becquerel's per cubic meter. Airtech Environmental Systems can provide a report, recommendations and a quotation for any recommended works. For more detailed information please call their free-phone number 0800 378017.



## Section 4: Ground Stability Findings

This section provides summary information on factors that could affect the ground stability of the property. It considers both man-made factors (e.g. mining activity) and natural hazards (e.g. geological stability).

### Section 4a: Man-Made Factors

Enquiry	Result	Contact
Is the property within 25m of a Coal Mining Affected Area?	Yes	4
<b>Comment:</b> The property is in an area which may be affected by coal mining activity. It is recommended that a Landmark Coal report is obtained.		

#### Next Steps

This section has highlighted that the property is in a coal mining affected area. We recommend that you purchase a Landmark Coal report. Please contact your Search Provider or our Customer Services Team on **0844 844 9966** or email **helpdesk@homecheck.co.uk**.

### Section 4b: Natural Factors

Enquiry	Result	Contact
What is the potential for natural ground instability in the area within 50m of the property?	Low	-
<b>Comment:</b> The British Geological Survey has assessed the area of search as having low potential for natural ground instability. This does not necessarily mean there is cause for concern in terms of the property's stability. Active subsidence will be dependent on local conditions, such as the proximity of trees or areas where trees have been removed, which require an inspection of the site to identify the nature of the ground on which the property is built. A house buyers survey is advised to look for signs of property damage that may indicate poor natural ground conditions.		





## Section 5: Other Influential Factors

The following section provides information on a variety of factors which may have an influence on the property or surrounding area.



## Section 5a: Environmental Constraints

Enquiry	Result
Is the property within 250m of an area likely to be impacted by Environmental Constraints?	No

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

### Areas of Outstanding Natural Beauty

No factors identified for this property

### Local Nature Reserves

No factors identified for this property

### National Nature Reserves

No factors identified for this property

### National Parks

No factors identified for this property

### Ramsar Sites

No factors identified for this property

### Sites of Special Scientific Interest

No factors identified for this property

### Special Areas of Conservation

No factors identified for this property

### Special Protection Areas

No factors identified for this property

## Useful Contacts

### Contact 1 - Environment Agency - National Customer Contact Centre (NCCC)

---

PO Box 544	Tel: 03708 506 506	enquiries@environment-agency.gov.uk
Templeborough		
Rotherham		
S60 1BY		

### Contact 2 - Calderdale Metropolitan Borough Council - Environmental Health

---

Northgate House	Tel: 01422 357257	www.calderdale.gov.uk
Northgate	Fax: 01422 392238	
Halifax		
West Yorkshire		
HX1 1UN		

### Contact 3 - Public Health England - Radon Survey, Centre for Radiation, Chemical and Environmental Hazards

---

Chilton	Tel: 01235 822622	radon@phe.gov.uk
Didcot	Fax: 01235 833891	www.ukradon.org
Oxfordshire		
OX11 0RQ		

### Contact 4 - The Coal Authority - Property Searches

---

200 Lichfield Lane	Tel: 0345 762 6848	groundstability@coal.gov.uk
Mansfield	Fax: 01623 637 338	www2.groundstability.com
Nottinghamshire		
NG18 4RG		

### Landmark Information Group Limited

---

Legal and Financial	Tel: 0844 844 9966	helpdesk@homecheck.co.uk
Imperium	Fax: 0844 844 9980	www.landmarkinfo.co.uk
Reading		
Berkshire		
RG2 0TD		

The Landmark website contains links to many of our data suppliers which may prove useful.

Please note that the Environment Agency/Natural Resources Wales/SEPA have a charging policy in place for enquiries.

Landmark works in association with:



Report Version: HCP v1.0.4.5

---

#### Homecheck® Report

Messrs Wm Woods Exors Ltd, Wm Woods Exors Limited  
Lambert Street  
West Vale  
ELLAND, HX4 8AA

#### Report Reference 331313424\_1\_1

©Copyright 2024, Landmark Information Group Ltd  
All rights reserved  
Date 15 January 2024  
Page 26 of 29

## Useful Information

The following explanatory notes may be of assistance to users of the Homecheck Professional report. Practitioners are reminded that full guidance notes are contained in the Practitioners Guide.

### Professional Opinion

A Professional Opinion in relation to Part 2A of the Environmental Protection Act 1990 is provided by Argyll Environmental Consultants. In many cases the report will be PASSED without referral. However, in some cases, entries that may be of concern are revealed by the search, in which case the report is REFERRED free of charge for more detailed consideration, although this will not include a physical site inspection. After such referral the report may be PASSED or suggestions made of some FURTHER ACTION that could be taken, in the form of questions to ask of the appropriate authorities. When responses to these questions are received it is the responsibility of the client and their professional advisors to decide if they are happy to proceed.

### Flood Risk

A limited flood risk screening exercise is included in this report designed to satisfy basic flood risk screening due diligence including consideration of river, coastal and surface water flooding. Where a potential flood risk is "Identified" you may wish to consider commissioning a more detailed flood risk screening report. When there is "None Identified" this does not indicate that there is not risk of flooding at the property, but that the risk of flooding from the sources screened (river, coastal and surface water) within the vicinity of the property is such that the risk may not be considered significant.

### Location Map

The Ordnance Survey location map may show features which are not necessarily otherwise included in this report. You are advised to supplement the information contained in the report with the descriptive text shown on the map.

### Positional Accuracy

We locate data in a variety of ways according to information provided to us and subsequent in-house research. If data is provided as a point on the ground, we provide a "positional accuracy" which tells you how confident we are of the actual location.

### Section 1b: Landfill and Waste

At present no complete national data set exists for landfill site boundaries, therefore, a point grid reference, provided by the data supplier, is used for some landfill sites. In certain cases the point grid references supplied provide only an approximate position, and can vary from the site entrance to the centre of the site. Where the exact position of the site is unclear for Registered Landfill data, Landmark construct either a 100 metre or 250 metre "buffer" around the point to warn of the possible presence of landfill. The size of this "buffer" relates to the positional accuracy that can be attributed to the site. The "buffer" is shown on the map as a red hatched area. For further information regarding landfill sites identified in the report, please contact the relevant environment agency or authority referenced in the Useful Contacts section.

The BGS holds records of over 3,000 landfill sites that accepted waste prior to the Control of Pollution Act (COPA) 1974. These were not subject to any strict regulation or monitoring.

Permitted Waste Sites and Environmental Permitting Regulations - Waste cover current or recently current consents issued for landfill sites, waste transfer, treatment or disposal sites by the Environment Agency/Natural Resources Wales, under Section 64 of the Environmental Protection Act 1990 (Part 2) and prescribed by regulation 10 of SI No. 1056 of the Waste Management Licensing Regulations 1994.

### Section 1c: Potentially Contaminative Activities

Identified discharge consents could be for storm water discharges, soakaways or septic tanks.

If a radioactive substance licence has been identified the consent band will be given under enquiries and replies. Consents fall into one of four bands: Band 1 and 2 Nuclear licensed sites authorised by the Nuclear Installations Inspectorate e.g. nuclear power stations Band 3 Site registered/authorised to accumulate and dispose of radioactive materials, only non-nuclear operations are carried out on site e.g. hospitals Band 4 Sites registered to keep and use radioactive material e.g. laboratories, universities, commercial premises using appliances such as monitoring equipment, alarm systems, tritium lighting etc.

Data supplied for Explosive Sites, Control of Major Accident Hazards Sites (COMAH) and Notification of Installations Handling Hazardous Substances (NIHHS) contains public sector information published by the Health and Safety Executive and licensed under the Open Government Licence.

### Section 1e: Other Potential Contaminative Land Uses

This section relates to categories of potentially contaminative land uses that have been identified by the analysis of selected Ordnance Survey historical mapping. The published date (range of dates) of the map (s) and the distance from the centre of search to the nearest point of the feature is given. Further details of the extent of the site or its activities are not available. Should you wish to examine the Ordnance Survey maps these are normally available for public inspection at the local archive or local major library. Alternatively, extracts of editions of Ordnance Survey maps are available on [www.old-maps.co.uk](http://www.old-maps.co.uk)

Potentially infilled land has been identified when a 'cavity' (a hole made by an extractive industry or natural occurrence e.g. pond) was indicated on a historic map but there was no evidence of its existence in the last available map for the area. No details of what may have been used to fill the cavity or exactly when or if it was filled are available from the mapping.

The point locations of historical tanks and energy facilities are identified from the text on Ordnance Survey 1:1250 and 1:2500 scale mapping published between 1943 and 1996, based upon a predetermined list of abbreviations, e.g. El Sub (Electricity Sub-station) and F Stn (Filling Station). The position of the point has been located at the centre of the identified text so that it would be within approximately 30 meters of the feature it was describing. The features themselves are related to energy and petroleum storage and cover the following: tanks, petrol storage, potential tanks (at depots etc.), electricity sub stations and related features, gas and gas monitoring related features, oil related features and miscellaneous power features. NB: It should be noted that the Ordnance Survey abbreviation for tank (tk) is the same as that for tracks. Therefore some of the captured text may relate to tracks and not tanks when the exact nature of the feature is not clear from the mapping.

## Section 2: Flood Findings

Sections 2a, b and c of the report provide data on modelled extents of river, coastal and surface water flooding generated by JBA Risk Management, a market leader in flood risk assessment commonly engaged by insurers to assess flood risk. The data has been modelled for several perils or return periods: 1 in 75, 1 in 200 or 1 in 1000 which relate to areas with a 1.3%, 0.5% and 0.1% annual probability of flooding in any one year respectively. Properties at risk of flooding during a 1 in 75 year event are typically considered to be at a high risk of flooding. The data has been generated to provide a UK wide screening tool and as a result may have inherent limitations. In addition, there may be areas of the country which are modelled to varying degrees of accuracy based on currently available topographical information.

## Section 3: Radon Findings

Due to the nature of way the information is gathered, your property/site may have more than one probability of radon attributed to it. We report the worst case scenario on the property/site you have provided. This information is an estimate of the probability that a property /site in Great Britain is at or above the "Action Level" for radon (the level at which Public Health England recommends that radon levels should be reduced, those with an average of 200 Bq m<sup>-3</sup> or more). This information satisfies CON29 Standard Enquiry of Local Authority; 3.13 Radon Gas: Location of the Property in a Radon Affected Area. Where the property/site is a new build, this information provides information on the level of protection required for new buildings under BR211 (Scivyer, 2007) Radon: Guidance on protective measures for new buildings.

Disclaimer: "Some of the responses contained in this section are based on data and information provided by the Natural Environment Research Council (NERC) or its component bodies the British Geological Survey (BGS). Your use of any information contained in this report which is derived from or based upon such data and information is at your own risk. Neither NERC, BGS nor Public Health England where applicable, gives any warranty, condition or representation as to the quality, accuracy or completeness of such information and all liability (including liability for negligence) arising from its use is excluded to the fullest extent permitted by law."

## Section 5a: Environmental Constraints

The Local Nature Reserves national dataset is "indicative" not "definitive". Definitive information can only be provided by individual local authorities and you should refer directly to their information for all purposes that require the most up to date and complete dataset.

## General

If after reading the details in this report regarding the sites identified, you still require further information, please contact the relevant environment agency or authority indicated in the Useful Contacts section quoting the corresponding reference given in the text of the report.

The contacts in the Useful Contacts section may be able to provide further information relating to items identified in the report, however they are not in a position to advise how these might affect the value of a property. The findings of the report should be discussed with your professional advisor.

## The Purpose and Scope of the Report

The report is designed to satisfy the concerns raised by the Law Society warning card and has been prepared to assist conveyancing professionals who may be advising clients when they sell or buy a property, obtain a mortgage, seek further mortgage advice, or commence any building works. It is designed to bring information to their attention and help them decide whether they need to seek any further specialist advice. As the report is so detailed, this information can cause concern, but professional advisors will see that further action is suggested on all issues that have been identified.

## Limitations

This report has been published by Landmark Information Group Limited ("Landmark") and is supplied subject to our Terms and Conditions of Business, which can be found at <http://www.landmarkinfo.co.uk/Terms/Show/534>. It has been prepared on the understanding that it is to be used for an individual residential property transaction and should not be used or relied upon in a commercial property transaction. This report is neither a guarantee of the physical condition of the subject property nor a substitute for any physical investigation or inspection. The information in Homecheck Professional is derived from a number of statutory and non-statutory sources (see The Practitioner Guide for details). Whilst every effort is made to ensure the details in the report are correct, Landmark cannot guarantee the accuracy or completeness of such information or data, nor identify all the factors that may be relevant. If you are a private individual using this report Landmark recommends that you discuss its contents in full with your professional advisor. The methodology for risk assessment and the conclusions drawn therefrom are the responsibility of Argyll Environmental Consultants.

## Insurance

Houses registered between 1st April 1999 and 31st December 2002 and covered by the NHBC Buildmark scheme probably have insurance against certain costs if contamination occurs within ten years of their construction. From 1st January 2003, NHBC will only provide this cover if building control has been carried out by NHBC Building Control Services Limited.

## Landmark Standard Terms and Conditions

Full Terms and Conditions can be found on the following link: <http://www.landmarkinfo.co.uk/Terms/Show/534>

If you experience difficulties accessing our Terms and Conditions, please copy and paste the link directly into your browser, you will then be able to access our Terms and Conditions from there. Should you still experience difficulties, please telephone our Customer Service Team on 0844 844 9966.

## Copyright Statement

The data supplied for this Homecheck Professional report falls under the following copyrights: © Landmark Information Group and/or its Data Suppliers 2024; © Environment Agency and database right 2024; © Environment Agency & United Kingdom Research and Innovation 2024; ©Experian Ltd 2024; Produced in whole or in part under licence from, and based in whole or in part from copyright material of © Thomson Directories Limited; © The Coal Authority owns the copyright to this data and the coal mining information used to produce it; © Peter Brett Associates LLP 2024; © Ofcom copyright 2024; © Natural England copyright. Contains Ordnance Survey data © Crown copyright and database right 2024; Ordnance Survey © Crown copyright and/or Database Right. All rights reserved. Licence 100022432; © HS2 Ltd and licensed under the Open Government Licence; © Natural Resources Wales & United Kingdom Research and Innovation 2024; Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right.

## Important Consumer Protection Information

This search has been produced by Landmark Information Group Ltd, Imperium, Imperial Way, Reading, Berkshire, RG2 0TD

Tel: 0844 844 9966

Fax: 0844 844 9980

Email: [helpdesk@landmark.co.uk](mailto:helpdesk@landmark.co.uk)

Landmark adheres to the Conveyancing Information Executive (CIE) standards.

## The Standards:

- Conveyancing Information Executive Members shall act in a professional and honest manner at all times in line with the Conveyancing Information Executive Standards and carry out the delivery of the Search with integrity and due care and skill.
- Compliance with the Conveyancing Information Executive Standards will be a condition within the Conveyancing Information Executive Member's Terms and Conditions.
- Conveyancing Information Executive Members will promote the benefits of and deliver the Search to the agreed standards and in the best interests of the customer and associated parties.
- The standards can be seen here: <http://www.conveyinfoexec.com>

## Complaints

If you have a query or complaint about your search, you should raise it directly with the search firm, and if appropriate ask for any complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response, after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Standards.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPO.

## TPOs Contact Details:

The Property Ombudsman scheme  
Milford House  
43-55 Milford Street  
Salisbury  
Wiltshire SP1 2BP

Tel: 01722 333306

Fax: 01722 332296

Website: [www.tpos.co.uk](http://www.tpos.co.uk)

Email: [admin@tpos.co.uk](mailto:admin@tpos.co.uk)



## Landmark Complaints Procedure

If you want to make a complaint to Landmark, we will:

- Acknowledge it within 5 working days of receipt
- Normally deal with it fully and provide a final response, in writing, within 20 working days of receipt
- Keep you informed by letter, telephone or e-mail, as you prefer, if we need more time
- Provide a final response, in writing, at the latest within 40 working days of receipt
- Liaise, at your request, with anyone acting formally on your behalf

Complaints should be sent to:

Customer Relationships Manager  
Landmark Information  
Imperium  
Imperial Way  
Reading  
RG2 0TD

Tel: 0844 844 9966

Email: [helpdesk@landmark.co.uk](mailto:helpdesk@landmark.co.uk)

Fax: 0844 844 9980

If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman scheme (TPOs):

Tel: 01722 333306

Email: [admin@tpos.co.uk](mailto:admin@tpos.co.uk)

We will co-operate fully with the Ombudsman during an investigation and comply with his final decision.